

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20004208/R1DA3Q2

**Date:** 16/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993916

**Claimant**  
**Vehicle No :** SBJ1918U **Insured Vehicle No :** SMR7645U

Date of Loss: 17/03/2020 Nature of Claim: TP Claim No: 3328720268SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBJ1918U</b>	Engine No:	CJS284273
Make & Model:	VOLKSWAGEN PASSAT B8, 1.8 TFSI (A)	Chassis No:	WVWZZZ3CZJE211971
Reg. Date:	25/07/2018 (Man. Year: 2018)	Odometer:	25927 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,130.82	4,006.61	1,124.21	21.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	3,760.00	3,560.00	48.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>12,450.82</b>	<b>7,766.61</b>	<b>4,684.21</b>	<b>37.62</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	871.56	543.66	327.90	37.62
<b>Nett Amount (\$\$)</b>	<b>13,322.38</b>	<b>8,310.27</b>	<b>5,012.11</b>	<b>37.62</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (\$\$)</b>		400.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>8,717.72</b>		

### INSPECTION

Date of Assignment: 19/03/2020

Date Inspected: 19/03/2020 Inspected At: Volkswagen Centre Singapore (HQ)  
247 Alexandra Road  
Singapore 159934

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Scratched	1,486.25 FS	*1,486.25 FS
2	1		*SPOILER SATIN BLACK	Serviceable	219.39 FS	*- FS
3	3		*HEXAGON SOCKET HEAD PANEL	Serviceable	1.32 FS	*- FS
4	1		*GUIDE PIECE LHF BUMPER BRACKET	Serviceable	39.51 FS	*- FS
5	1		*COOLING AIR GRILL SATIN B LH VENT GRILLE	Serviceable	98.43 FS	*- FS
6	1		*COVER STRIP SATIN BLACK LH VENT GRILL COVER	Serviceable	68.97 FS	*- FS
7	1		*DECORATIVE MOULDING BRIGH LH VENT GRILLE CHROME	Scratched	88.13 FS	*88.13 FS
8	1		*FENDER	Repair	642.60 FS	*- FS
9	1		*BRACKET LH FENDER	Serviceable	53.99 FS	*- FS
10	1		*LED HEADLIGHT	Scratched	2,254.30 FS	*2,254.30 FS
11	1		*SET SENSOR BRACKETS	Necessary	42.59 FS	*42.59 FS
12	1		*2K-PLASTIC ADHESIVE	Necessary	75.94 FS	*75.94 FS
13	1		*BONDING AGENT FOR PLASTIC	Necessary	59.40 FS	*59.40 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **5,130.82** **4,006.61**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
3	LABOUR	New	3,360.00	1,680.00
4	SPRAY PAINTING	New	3,200.00	1,600.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,320.00</b>	<b>3,760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >