



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 7637T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT NUMBER PLATE BASE GARNISH (WCP)	SERVICEABLE	55.00	-
1	FRONT BUMPER - TOP (WCP)	CRACKED	330.00	330.00
2	FRONT BUMPER SIDE RETAINER (LH/RH) @\$50.00 (WCP)	N/S CRACKED	100.00	50.00
1	FRONT BUMPER - BOTTOM (WCP)	DISTORTED	180.00	180.00
1	N/S FRONT BUMPER PARKING SENSOR (WCP)	SERVICEABLE	155.00	-
1	N/S FRONT BUMPER FOGLAMP (WCP)	MTG CRACKED	125.00	125.00
1	N/S FRONT BUMPER FOGLAMP BRACKET (WCP)	CRACKED	60.00	60.00
1	N/S FRONT BUMPER FOGLAMP COVER (WCP)	SERVICEABLE	35.00	-
15	FRONT BUMPER CLIPS @\$1.50 (WCP)	NECESSARY	22.50	22.50
1	N/S FRONT FENDER (WCP)	BENT	360.00	360.00
1	N/S FRONT FENDER INNER BRACKET (WCP)	DISTORTED	70.00	70.00
1	N/S FRONT FENDER INNER SHIELD (WCP)	TORN	200.00	200.00
4	FRONT FENDER INNER SHIELD RETAINER @\$10.00 (WCP)	NECESSARY	40.00	40.00
4	FRONT FENDER INNER SHIELD RETAINER PIN @\$5.00 (WCP)	NECESSARY	20.00	20.00
10	N/S FRONT FENDER INNER SHIELD CLIPS @\$1.50 (WCP)	NECESSARY	15.00	15.00
1	FRONT SUPPORT PANEL (WCP)	TO REPAIR SEE LABOUR	520.00	-
1	N/S HEADLAMP (WCP)	CRACKED	1,450.00	1,450.00
1	N/S HEADLAMP LOWER BRACKET (WCP)	CRACKED	55.00	55.00
1	N/S HEADLAMP HID BULB (WCP)	SERVICEABLE	200.00	-
1	N/S HEADLAMP HID BALLAST (WCP)	SERVICEABLE	270.00	-
1	N/S HEADLAMP NOZZLE PUMP (WCP)	SERVICEABLE	250.00	-
1	FRONT BUMPER LOWER CENTRE GRILLE (WCP)	SERVICEABLE	110.00	-
	COST PLUS 10%		462.25	297.75
			5,084.75	3,275.25
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	40.00	-
			40.00	-

Report Ref No. CS/UOI20004210/Kyd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		650.00	500.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		1,000.00	600.00
	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.		50.00	20.00
	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	NOT NECESSARY	100.00	-
			1,800.00	1,120.00
	<b>GRAND TOTAL</b>		<b>6,924.75</b>	<b>4,395.25</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>4,395.25</b>
	<b>LESS EXCESS</b>			<b>-3,000.00</b>
	<b>NETT LIABILITY</b>			<b>1,395.25</b>

Report Ref No. CS/UOI20004210/Kyd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.