

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20004217/GSD3E2

Date: 26/11/2020

REFERENCE

Insured/Claimant: DOWNTOWN TRAVEL SERVICES PTE LTD Policy No: 0999993918
Date of Loss: 04/03/2020 Nature of Claim: OD Claim No: 0427459837SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE9843G**
Make & Model: SUBARU LEGACY, 2.5 I-S (A) Engine No: FB25Y250796
Reg. Date: 10/08/2016 (Man. Year: 2016) Chassis No: JF1BN9KC2GG011167
Colour: Grey Odometer: 61900 km
Engine Capacity: 2498 cc
Market Value/New Car Price: S\$64,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50Z R18 Rear Tyre Size: 225/50Z R18
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,364.81	7,062.20	4,302.61	37.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,699.00	2,878.00	821.00	22.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,063.81	9,940.20	5,123.61	34.01
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	14,063.81	8,940.20	5,123.61	36.43
+ GST 7.00/7.00% (S\$)	984.47	625.81	358.66	36.43
Nett Amount (S\$)	15,048.28	9,566.01	5,482.27	36.43

INSPECTION

Date of Assignment: 19/03/2020
Date Inspected: 19/03/2020 Inspected At: Motor Image Enterprises Pte Ltd (Toa Payoh)
19 Lorong 8 Toa Payoh
Singapore 319255

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
2	1		*BUMPER FACE-FRONT	Cracked	594.00 FL	*594.00 FL
3	1		*BACK BEAM COMPLETE-FRONT	Not Necessary	342.40 FL	*- FL
4	1		*ENERGY ABSORBER-FRONT BUMPER	Cracked	57.60 FL	*57.60 FL
5	1		*ENERGY ABSORBER-FRONT BUMPER	Not Necessary	35.10 FL	*- FL
6	1		*BRACKET-BUMPER, FRONT LOWER	Missing	57.60 FL	*57.60 FL
7	1		*SEAL-FRONT BUMPER	Not Necessary	27.00 FL	*- FL
8	1		*ENERGY ABSORBER-UPPER	Not Necessary	18.00 FL	*- FL
9	1		*BRACKET-FRONT BUMPER CORNER, RIGHT	Not Necessary	32.40 FL	*- FL
10	1		*BRACKET-FRONT BUMPER CORNER, LEFT	Deformed	32.40 FL	*32.40 FL
11	1		*BRACKET-FRONT BUMPER SIDE, RIGHT	Not Necessary	18.00 FL	*- FL
12	1		*BRACKET-FRONT BUMPER SIDE, LEFT	Not Necessary	18.00 FL	*- FL
13	1		*COVER-FOG LIGHT, RIGHT	Missing	50.40 FL	*50.40 FL
14	1		*COVER-FOG LIGHT, LEFT	Missing	50.40 FL	*50.40 FL
15	1		*COVER-INTAKE, FRONT	Missing	50.40 FL	*50.40 FL
16	1		*FRONT GRILLE ASSEMBLY	Not Necessary	576.00 FL	*- FL
17	1		*BRACKET-GRILL	Not Necessary	42.20 FL	*- FL
18	1		*ORNAMENT	Scratched	72.00 FL	*72.00 FL
19	1		*COVER ASSEMBLY-LAMP WASHER NOZZLE, LEFT	Missing	54.00 FL	*54.00 FL
20	1		*NOZZLE-LAMP WASHER, LEFT	Missing	90.00 FL	*90.00 FL
21	1		*EXHAUST PIPE ASSEMBLY-REAR	Repair	756.00 FL	*- FL
22	1		*MUFFLER ASSEMBLY-LEFT	Dented	540.00 FL	*540.00 FL
23	1		*GASKET A	Necessary	7.20 FL	*7.20 FL
24	1		*TAIL PIPE CUTTER	Not Necessary	86.40 FL	*- FL
25	1		*CONVERTER COMPLETE-FRONT	Not Necessary	2,520.00 FL	*- FL
26	1		*CONVERTER COMPLETE-FRONT	Not Necessary	1,105.20 FL	*- FL
27	1		*UNDER COVER-FRONT	Missing	162.00 FL	*162.00 FL
28	1		*FOG LIGHT ASSEMBLY-FRONT	N/S Broken / O/S Not Necessary	544.00 FL	*272.00 FL
29	1		*FRAME COMPLETE-RADIATOR PANEL, LOWER	Repair	64.80 FL	*- FL
30	1		*FRAME COMPLETE-RADIATOR, LOWER	Repair	64.80 FL	*- FL
31	1		*NUMBER PLATE	Scratched	45.00 FS	*45.00 FS
32	1		*UNIT ASSY ACTIVE GRILLE	Broken	475.20 FL	*475.20 FL
33	1		*RADIATOR COMPLETE	Bent	810.00 FL	*810.00 FL
34	1		*HOSE RADIATOR INLET	Twisted	36.00 FL	*36.00 FL
35	1		*HOSE RADIATOR OUTLET	Twisted	36.00 FL	*36.00 FL
36	1		*CONDENSER ASSEMBLY	Bent	756.00 FL	*756.00 FL
37	1		*FRAME COMPLETE - CRADLE	Bent	1,080.00 FL	*1,080.00 FL
38	1		*LAMP ASSEMBLY HEAD RIGHT	Broken	1,870.00 FL	*1,870.00 FL
39	1		*LAMP ASSEMBLY HEAD LEFT	Broken	1,870.00 FL	*1,870.00 FL
40	1		*COVER ASSEMBLY HEAD LAMP	Repeated	54.00 FL	*- FL
41	1		*HOSE ASSEMBLY HEAD LAMP	Broken	108.00 FL	*108.00 FL
42	1		*MUD GUARD FRONT RIGHT	Torn	108.00 FL	*108.00 FL
43	1		*MUD GUARD FRONT LEFT	Torn	108.00 FL	*108.00 FL
44	2		*RADIATOR PARKING	Deformed	47.60 FL	*47.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
45	1		*RAD PNL COMPLETE RPR	Buckled	601.20 FL	*601.20 FL	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$)	16,173.30	10,061.00
					- List Item Discount on L Items 30.00/30.00% (\$)	4,808.49	2,998.80
					Total Parts (\$)	11,364.81	7,062.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR / REPLACE FRONT BUMPER & FRONT PANEL	New	1,000.00	750.00
2	RESPRAY FRONT BUMPER & FRONT PANEL	New	800.00	400.00
3	DISMENTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIRS	New	684.00	684.00
4	REMOVE & REFIX EXHAUST	New	114.00	114.00
5	REMOVE & REFIX AIR CON CONDENSER & RADIATOR TO FACILITATE REPAIR	New	171.00	171.00
6	MECHANICAL REPAIRS - ALTERNATOR, COMPRESSOR, STEERING PUMP	New	171.00	0.00
7	FAULT DIAGNOSTIC	New	235.00	235.00
8	REMOVE / REFIX FRT HEADLAMP WASHER & PIPING	New	125.00	125.00
9	CONDUCT 4 WHEEL ALIGNMENT	New	171.00	171.00
10	REMOVE & REFIX WIRE HARNESS	New	228.00	228.00
Gross Labour Cost (\$)			3,699.00	2,878.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >