


16. The 3 tyres of the Motor Car were also found to be in serviceable condition. I did not find any tear, cut or burst mark(s) on the outer and the inner sidewalls as well as across the tread of the 4 tyres. The front right tyre was deflated because of the cut to the tyre as a result of the accident. However the other 3 tyres were observed to be sufficiently inflated for vehicular operation. All 4 tyres were observed with remaining tread depth of approximately 4.1mm to 6mm.



Sherwin Beh
Technical Investigator



Ang Bryan Tani
AMSOE, AMRTE, AFF SAE, M.MATAI, AFF.Inst.AEA
Senior Technical Investigator
Technical Investigation & Reconstructionist (SAE-A)

DISCLAIMER OF LIABILITY TO THIRD PARTIES: - This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part does so at his or her own risk.