

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19014965/FES3Q2

Date: 11/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : GBF6239J	Insured Vehicle No :	SHC8201Z
Date of Loss: 05/06/2019	Nature of Claim: TP	Claim No: MCT19060105

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF6239J		
Make & Model:	MITSUBISHI CANTER, 2.5 D FB510B (M)	Engine No:	4P10C25399
Reg. Date:	09/01/2017 (Man. Year: 2016)	Chassis No:	FEA01BA20279
Colour:	White	Odometer:	102912 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13 (D)
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 6/6 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	900.00	800.00	47.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,700.00	900.00	800.00	47.06
+ GST 7.00/7.00% (S\$)	119.00	63.00	56.00	47.06
Nett Amount (S\$)	1,819.00	963.00	856.00	47.06
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
		(S\$)		
		1,463.00		
Liabe Amount (50.00%) (S\$)		731.50		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		738.99		
Global Sum Settlement (S\$)		800.00		

INSPECTION

Date of Assignment: 23/08/2019

Date Inspected: 10/01/2020 Inspected At:

Efficient Motor & Engineering Works
Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang
Enterprise Building
Singapore 508775

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 23 Apr 2020)

Parts: N/A MITSUBISHI CANTER 2.5 D FB510B (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF6239J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING AFFECTED AREA: REAR MUD FLAP L/H, REAR OUTER RIM L/H, REAR DOOR CATCH L/H AND REAR CORNER SAFETY BAR L/H	New	800.00	400.00
2	SPRAY PAINTING	New	800.00	450.00
3	RE ALIGN TAILLAMP BRACKET L/H	New	100.00	50.00
Gross Labour Cost (\$\$)			1,700.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >