

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20004234/EPA3Q2

Date: 31/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SFG9086K	Insured Vehicle No :	SHD7124P
Date of Loss: 18/03/2020	Nature of Claim:	TP Claim No: MCT20030306

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFG9086K		
Make & Model:	MINI COOPER, 1.5 (A)	Engine No:	F984H749B38A15A
Reg. Date:	02/07/2018 (Man. Year: 2018)	Chassis No:	WMWXU52080TH94273
Colour:	Red	Odometer:	21179 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,176.90	1,146.90	30.00	2.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,030.00	4,890.00	1,140.00	18.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,206.90	6,036.90	1,170.00	16.23
+ GST 7.00/7.00% (S\$)	504.48	422.58	81.90	16.23
Nett Amount (S\$)	7,711.38	6,459.48	1,251.90	16.23
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
		Nett Liability (S\$)	6,759.48	

INSPECTION

Date of Assignment:	19/03/2020	
Date Inspected:	19/03/2020	Inspected At:
		Eurokars Habitat Pte Ltd (HQ) 27A Tanjong Penjuru Level 5 Singapore 609042
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2020)
Parts: 144	MINI COOPER 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFG9086K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RIM LH	Cut	825.17 F	*825.17 F
2	1		*REAR RIM CAP LH	Cut	34.38 F	*34.38 F
3	1		*REAR DOOR ARCH LH	Cut	106.99 F	*106.99 F
4	1		*REAR FENDER ARCH LH	Cut	142.68 F	*142.68 F
5	8		*ARCH CLIP	Necessary	17.68 F	*17.68 F
6	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **1,176.90** **1,146.90**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR BUMPER,REAR DOOR LH & FRONT DOOR LH AND ALL AREAS AFFECTED BY THE ACCIDENT	New	1,900.00	1,260.00
2	TO RESPRAY REAR BUMPER,REAR DOOR LH AND FRONT DOOR LH	New	2,600.00	2,400.00
3	TO CARRY -OUT BODY CAVITY PRESERVATION	New	250.00	150.00
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	120.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	560.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	250.00
			Gross Labour Cost (\$\$)	4,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >