

dr.mn

COMPANY: HOL Ann REF: CS31 II 20021987/44-3 Special Instruction: 19/3/2020

From (Person): Gabriel W of II Date/Time: 5.2.2020 11:29.47

Estimated Cost: SGV 2511E Bill to: SHB 66444

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS Insured: 96333593

To Inspect Vehicle No: MCSRS Derrick motor Tel: 96333593

at Workshop n/s: Blk 902 Tampines st 93 #01-72

Policy No: MCOM0015 Claim No: MCT20010641

Sum Insured: Brooks

Make of Veh: D.O.A 25.1.2020

Client's Record: CA / REV / REP. / REV 24 HRS

Date/Time: 5/2/20 11.34.47 Person Contacted: Jeromy H.O.D Endorsement: Vehicle IN/OUT

Date/Time	Action/Instruction (X) (Strike)
	SGV 2511E - (C3) [A15 14/04/20 11/01/2021] - 1 P.O.A - 26/04/2018
	SHB 66444 - (C3) [A15 14/04/20 11/01/2021] - 1 P.O.A - 26/04/2018

Demantle part: 07/02/2020 12:06PM

Submit \$2300, 4 days
(cred 700: 25%)

Photo in system View
x
members

2013 File pass to typist


20/3/2020

RECEIVED 20 MAR 2020

250 + 11 = 261
261 - 131 = 130

REC BY: H. ANN

REF: III

ASSIGNMENT

From

Date

5/21/2020

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

SGV 2511E

a Workshop m/s

Messrs Derrick Motor

at Blk 902 Tampines st 93 #01-72

Insured

Policy No

Claims No

Sum Insured


Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value

IDAC Accident Rpt

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs

3

days

Res.: Yes or No

Turn Sum

%

3 Val.

Yes or No

CA / REV / REP. / 24 HRS

my

Vehicle: IN / OUT

Date

Person Contacted

Veh No

SGV 2511E

Regn

09/106/2020

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN ARTIS

CC 1478

Colour

Black / Gold

A/C

Insured / Std / NI / NA

Sp Reading

22522 km

T/Radio

Insured / Std / NI / NA

Eng/No

C/No:

JN1BAC1120005051

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi Nil / S/Rim / STD A/Rim or

Tyre Size

F:

195/60/R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

5 mm

R/Bal

4 mm

L/Bal

5 mm

L/Bal

4 mm

D.O.A

25/1/20

D.O.I

5/2/20

0316PM

Survey held at

Messrs Derrick Motor

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range → 1.5-2.2 km

Apr Days → 3

* SGV 2511E

PRC work

RECEIVED 11 FEB 2020

UV - 14000

PV - 11740

NV - 2200

Finag → 96333573

Draw Time, File Pass out



: Preli. Report



: Final Report

11/2 Typist

Date/Time, File Return in?

3

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Next day (\$

Survey Fee:

Transportation

5 + RS 50

Photos

11

131

Rep. Form

PRS

Long Form / 11/2

Celine Fong (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Thursday, 19 March 2020 10:56 AM
To: 'Derrick Tan'; assignments
Cc: 'Dhanya B.Purushothaman'; SUR
Subject: RE: PAPER SURVEY SGV2511E III REF: MCT20010641

Dear Derrick,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Derrick Tan <DerrickTan@iii.com.sg>
Sent: Thursday, 19 March 2020 10:53 AM
To: 'sur@lkkauto.com' <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Dhanya B.Purushothaman <Dhanya@iii.com.sg>
Subject: PAPER SURVEY SGV2511E III REF: MCT20010641

Dear Sir/Mdm,

Please conduct paper survey for the below TP vehicle and let us have your report URGENTLY. LOD uploaded and rights granted to you in Merimen.

TP Veh No. : SGV2511E.

Thank you.

Best Regards,

Derrick Tan
Motor & Work Injury Claims Department
India International Insurance Pte Ltd
64 Cecil Street, #04/#05 IOB Building, Singapore 049711
Tel: 6347 6100, Ext – 264

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance

Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



This email has been checked for viruses by AVG antivirus software.
www.avg.com

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 02-20004/DY / 2020
Date of Report : 20 Feb 2020

Goh Kim Leng
c/o Blk 9002 Tampines Street 93
#01-72 Tampines Ind Park A
Singapore 528836

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 25 Jan 2020

As per your instruction dated 5 Feb 2020 with regard to the above matter. We have carried out a physical inspection on the said vehicle **SGV 2511 E**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SGV 2511 E
Model : Nissan Latio
Year / Capacity : 2007/1498
Chassis No : JN1BAAC11Z0005051
Engine No : HR15155342A
Mileage : 225282
Colour : Silver

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 195/60 R15	Bridgestone	3.00	mm	Sport
REAR	O/S	: 195/60 R15	Bridgestone	3.00	mm	Sport
FRONT	N/S	: 195/60 R15	Bridgestone	3.00	mm	Sport
REAR	N/S	: 195/60 R15	Bridgestone	3.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Derrick Motor Works
Blk 9002 Tampines Street 93
#01-72 Tampines Ind Park A
Singapore 528836

5. Estimated normal period of repair : 5 working days to complete.

6. Enclosed number of photograph : 82 copies.

7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SGV 2511 E**
 Report No: **TP/ 02-20004/DY / 2020**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Boot lid	Repair	\$ 764.60	\$
1	Rear taillamp panel	Repair	\$ 236.80	\$
1	Rear end panel	Damage	\$ 442.70	\$ 442.70
1	Rear bumper	Damage	\$ 551.00	\$ 551.00
2	Rear bumper brackets	Repair	\$ 183.40	\$
			<u>\$ 2178.50</u>	<u>\$ 993.70</u>
	Discount	30.0%	\$ 653.55	\$ 298.11
			<u>\$ 1524.95</u>	<u>\$ 695.59</u>
<u>Nett Items</u>				
1	Boot lid lock	Damage	\$ 99.80	\$ 99.80
1	Boot lid rubber	Damage	\$ 85.60	\$ 85.60
1	Boot lid 'LATIO' emblem	Necessary	\$ 62.40	\$ 62.40
1	Boot lid 'NISSAN' emblem	Necessary	\$ 52.70	\$ 52.70
2	Rear taillamps	Damage	\$ 439.80	\$ 439.80
1	Rear end panel inner garnish	Damage	\$ 158.60	\$ 158.60
1	Rear bumper inner sponge	Damage	\$ 56.20	\$ 56.20
2	Rear bumper side retainers	Damage	\$ 126.00	\$ 126.00
1	Rear bumper splash shield	Intact	\$ 58.50	\$
			<u>\$ 1139.60</u>	<u>\$ 1081.10</u>
	Discount	10.0%	\$ 113.96	\$ 108.11
			<u>\$ 1025.64</u>	<u>\$ 972.99</u>
<u>Special Nett Items</u>				
2	Rear taillamp side clips (2 set)	Damage	\$ 42.00	\$ 42.00
1	Rear bumper clip (1 set)	Damage	\$ 35.00	\$ 35.00
1	Rear bumper lower spoiler	Damage	\$ 588.50	\$ 588.50
			<u>\$ 665.50</u>	<u>\$ 665.50</u>

Spare Parts Total \$ 3216.09 \$ 2334.08

Vehicle No: **SGV 2511 E**
Report No: **TP/ 02-20004/DY / 2020**


LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 3216.09	\$ 2334.08
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 60.00	\$ 40.00
2	To remove and refit rear bumper sensor.	\$ 100.00	\$ 80.00
3	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 650.00	\$ 550.00
4	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1200.00	\$ 880.00
5	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 50.00	\$ 30.00
Total		\$ 5276.09	\$ 3914.08

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 3100.00

SDLS: THREE THOUSAND ONE HUNDRED ONLY


Qualified Appraiser

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 02-20004/DY / 2020
Date of Report : 20 Feb 2020

Goh Kim Leng
c/o Blk 9002 Tampines Street 93
#01-72 Tampines Ind Park A
Singapore 528836

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 25 Jan 2020

As per your instruction dated 5 Feb 2020 with regard to the above matter. We have carried out a physical inspection on the said vehicle **SGV 2511 E**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SGV 2511 E
Model : Nissan Latio
Year / Capacity : 2007/1498
Chassis No : JN1BAAC11Z0005051
Engine No : HR15155342A
Mileage : 225282
Colour : Silver

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 195/60 R15	Bridgestone	3.00	mm	Sport
REAR	O/S	: 195/60 R15	Bridgestone	3.00	mm	Sport
FRONT	N/S	: 195/60 R15	Bridgestone	3.00	mm	Sport
REAR	N/S	: 195/60 R15	Bridgestone	3.00	mm	Sport

Vehicle No: **SGV 2511 E**
 Report No: **TP/ 02-20004/DY / 2020**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Boot lid X (R)	Repair	\$ 764.60	\$
1	Rear taillamp panel X (R)	Repair	\$ 236.80	\$
1	Rear end panel ✓ B+	Damage	\$ 442.70	\$ 442.70 ✓
1	Rear bumper ✓ CRA	Damage	\$ 551.00	\$ 551.00 ✓
2	Rear bumper brackets X (R)	Repair	\$ 183.40	\$
			<u>\$ 2178.50</u>	<u>\$ 993.70</u>
	Discount	30.0%	\$ 653.55	\$ 298.11
			<u>\$ 1524.95</u>	<u>\$ 695.59</u>
<u>Nett Items</u>				
1	Boot lid lock ✓ Jm	Damage	\$ 99.80	\$ 99.80 ✓
1	Boot lid rubber X (SVC)	Damage	\$ 85.60	\$ 85.60 ✓
1	Boot lid 'LATIO' emblem ✓ m	Necessary	\$ 62.40	\$ 62.40 ✓
1	Boot lid 'NISSAN' emblem ✓ m	Necessary	\$ 52.70	\$ 52.70 ✓
1	2 Rear taillamps R/H only ✓ CRA	Damage	\$ 439.80	\$ 439.80 219 ✓
1	Rear end panel inner garnish ✓ CRA	Damage	\$ 158.60	\$ 158.60 ✓
1	Rear bumper inner sponge ✓ CRA	Damage	\$ 56.20	\$ 56.20 ✓
2	Rear bumper side retainers ✓ m	Damage	\$ 126.00	\$ 126.00 ✓
1	Rear bumper splash shield X (SVC)	Intact	\$ 58.50	\$
			<u>\$ 1139.60</u>	<u>\$ 1081.10</u>
	Discount	10.0%	\$ 113.96	\$ 108.11
			<u>\$ 1025.64</u>	<u>\$ 972.99</u>
<u>Special Nett Items</u>				
2	Rear taillamp side clips (2 set) ✓ m	Damage	\$ 42.00	\$ 42.00 10 ✓
1	Rear bumper clip (1 set) ✓ m	Damage	\$ 35.00	\$ 35.00 20 ✓
1	Rear bumper lower spoiler → 100% repair \$150 ✓	Damage	\$ 588.50	\$ 588.50
			<u>\$ 665.50</u>	<u>\$ 665.50</u>

Spare Parts Total \$ 3216.09 \$ 2334.08

Vehicle No: **SGV 2511 E**
 Report No: **TP/ 02-20004/DY / 2020**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 3216.09	\$ 2334.08
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 60.00	\$ 40.00 30 ✓
2	To remove and refit rear bumper sensor.	\$ 100.00	\$ 80.00 20 ✓
3	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 650.00	\$ 550.00 ✓
4	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1200.00	\$ 880.00 650 ✓
5	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 50.00	\$ 30.00 ✓
Total		\$ 5276.09	\$ 3914.08

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 3100.00

SDLS: THREE THOUSAND ONE HUNDRED ONLY

Handwritten notes:
 2/5 report without proper running after part 4 day 1 survey morning 20/3/20 9.00 AM H.AN (11/11)

Qualified Appraiser

Handwritten calculations:
 parts 993.70
 parts less 30%
 695.59 ✓
 nett item 774.70
 nett item less 10%
 697.23 ✓
 180 ✓
 1280 ✓
 2852.82
 25%
 2282.25
 total 4/5 part → \$2300 A

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Invoice No 02-20004/DY

Billing Name & Address

Goh Kim Leng
c/o Blk 9002 Tampines Street 93
#01-72 Tampines Ind Park A
Singapore 528836

Date 20 Feb 2020

Vehicle No : SGV 2511 E

Model : Nissan Latio

Item	Descriptions	Amount S\$
1	Date of inspection : <u>5 Feb 2020</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>82</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 602.00</u>
	SDLS : SIX HUNDRED AND TWO ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp


E & O. E

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CS3/III20001987/Htf3e2-1	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 23-03-2020	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6644Y	Veh. Inspected	SGV 2511E	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT20010641	Excess (\$)	0.00	
Assign From	DERRICK TAN	Assign Date	19/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN LATIO	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JN1BAAC11Z0005051	Colour	GOLD	
Odometer	225282	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195/60 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195/60 R15	BRIDGESTONE	4 mm	
L/H Rear Tyre	195/60 R15	BRIDGESTONE	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.5				
5. General Information				
Accident Date	25/01/2020	Inspection Date	05/02/2020	
Survey held at	MESSRS DERRICK - BLK 9002 TAMPINES ST 93 #01-72			
Repairer	-			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 2511E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	TO REPAIR SEE LABOUR	764.60	-
1	REAR TAILLAMP PANEL	TO REPAIR SEE LABOUR	236.80	-
1	REAR END PANEL	BENT	442.70	442.70
1	REAR BUMPER	CRACKED	551.00	551.00
2	REAR BUMPER BRACKETS	TO REPAIR SEE LABOUR	183.40	-
	LESS 30% DISCOUNT		-653.55	-298.11
			1,524.95	695.59
<u>NETT ITEMS</u>				
1	BOOT LID LOCK (N)	JAMMED	99.80	99.80
1	BOOT LID RUBBER (N)	SERVICEABLE	85.60	-
1	BOOT LID 'LATIO' EMBLEM (N)	NECESSARY	62.40	62.40
1	BOOT LID 'NISSAN' EMBLEM (N)	NECESSARY	52.70	52.70
2	REAR TAILLAMPS (N)	O/S CRACKED	439.80	219.00
1	REAR END PANEL INNER GARNISH (N)	CRACKED	158.60	158.60
1	REAR BUMPER INNER SPONGE (N)	CRUMPLED	56.20	56.20
2	REAR BUMPER SIDE RETAINERS (N)	NECESSARY	126.00	126.00
1	REAR BUMPER SPLASH SHIELD (N)	SERVICEABLE	58.50	-
	LESS 10% DISCOUNT		-113.96	-77.47
			1,025.64	697.23
<u>SPECIAL NETT ITEMS</u>				
2	SET REAR TAILLAMP SIDE CLIPS (SN)	NECESSARY	42.00	10.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	35.00	20.00
1	REAR BUMPER LOWER SPOILER (SN) (LOCAL REPAIR)	DAMAGED	588.50	150.00
			665.50	180.00
<u>LABOUR</u>				
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		60.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		100.00	20.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF BOOT LID, REAR TAILLAMP PANEL AND REAR BUMPER BRACKETS.		650.00	550.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,200.00	650.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		50.00	30.00
			2,060.00	1,280.00
GRAND TOTAL			5,276.09	2,852.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS3/III20001987/Htf3e2-1

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.