

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20004242/UGA3Q2

Date: 30/06/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00008272
Claimant
Vehicle No : SMG8662X **Insured Vehicle No :** SGL3966Y
Date of Loss: 15/03/2020 **Nature of Claim:** TP **Claim No:** 1202000013258

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG8662X
Make & Model: HONDA FIT, 1.5 HYBRID (A) **Engine No:** LEB1441052
Reg. Date: 02/01/2019 (Man. Year: 2018) **Chassis No:** GP51334227
Colour: Blue **Odometer:** 79882 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 **Rear Tyre Size:** 195/55 R15
Front Left Side: Michelin 6 mm **Rear Left Side:** Michelin 6 mm
Front Right Side: Michelin 6 mm **Rear Right Side:** Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	56,369.00	4,113.84	52,255.16	92.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,380.00	2,190.00	8,190.00	78.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	66,749.00	6,303.84	60,445.16	90.56
Approved Total (Overridden) (\$)		5,000.00		
(S\$)	66,749.00	5,000.00	61,749.00	92.51
+ GST 7.00/7.00% (S\$)	4,672.43	350.00	4,322.43	92.51
Nett Amount (S\$)	71,421.43	5,350.00	66,071.43	92.51
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,057.45		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment: 19/03/2020
Date Inspected: 19/03/2020 **Inspected At:** RICO 60 AUTO SERVICES PTE LTD (HQ)
 8, KAKI BUKIT AVENUE 4, #02-24,
 PREMIER @ KAKI BUKIT
 Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jun 2020)
Parts:	144	HONDA FIT 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG8662X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	391.00 F	*68.50 FL
2	1		*REAR TAILGATE	Badly Dented	1,264.00 F	*880.40 FL
3	1		*REAR TAILGATE WIPER ARM	Not Necessary	266.00 F	*- FL
4	1		*REAR TAILGATE WIPER MOTOR	Not Necessary	396.00 F	*- FL
5	1		*REAR TAILGATE WIPER MOTOR COVER	Not Necessary	213.00 F	*- FL
6	1		*REAR TAILGATE CHROME HANDLE	Not Necessary	451.00 F	*- FL
7	1		*REAR TAILGATE CHROME HANDLE LOGO	Not Necessary	103.00 F	*- FL
8	2		*REAR TAILGATE CHROME HANDLE LICENSE PLATE LAMP L+R	Not Necessary	228.00 F	*- FL
9	1		*REAR TAILGATE OPENER	Not Necessary	361.00 F	*- FL
10	1		*REAR TAILGATE LOCK	Twisted	652.00 F	*109.40 FL
11	1		*REAR TAILGATE INNER TRIM TOP	Not Necessary	312.00 F	*- FL
12	1		*REAR TAILGATE INNER TRIM BTM	Deformed	576.00 F	*341.80 FL
13	1		*REAR TAILGATE WEATHERSTRIP	Twisted	324.00 F	*148.20 FL
14	2		*REAR TAILGATE LAMP L+R	Not Necessary	966.00 F	*- FL
15	2		*REAR TAILLAMP	Cracked	1,854.00 F	*610.00 FL
16	1		*REAR TAILLAMP PANEL	Repair	984.00 F	*- FL
17	1		*REAR BUMPER	Dented	1,061.00 F	*548.10 FL
18	2		*REAR BUMPER RETAINER L+R	Bent	268.00 F	*70.00 FL
19	2		*REAR BUMPER SIDE SPONGE	Cracked	382.00 F	*382.00 FL
20	2		*REAR BUMPER BRACKET L+R	Not Necessary	242.00 F	*- FL
21	1		*REAR BUMPER REINFORCEMENT BAR	No such part	513.00 F	*- FL
22	1		*REAR BUMPER SPONGE	No such part	302.00 F	*- FL
23	2		*REAR FENDER L+R	Not Necessary	3,638.00 F	*- FL
24	2		*REAR FENDER COWLING L+R	Not Necessary	484.00 F	*- FL
25	2		*REAR FENDER INNER TRIM BTM L+R	Deformed / Torn	2,118.00 F	*770.00 FL
26	2		*REAR FENDER INNER TRIM TOP L+R	Not Necessary	1,682.00 F	*- FL
27	1		*REAR END PANEL	Badly Dented	1,229.00 F	*306.20 FL
28	1		*REAR END PANEL TOP GARNISH	Twisted	481.00 F	*166.50 FL
29	1		*REAR FLOOR PANEL	Repair	1,951.00 F	*- FL
30	1		*REAR FLOOR PANEL TOP BOARD	Warped	781.00 F	*366.20 FL
31	1		*REAR BATTERY	Not Necessary	26,421.00 F	*- FL
32	1		*REAR BATTERY COVER	Not Necessary	357.00 F	*- FL
33	1		*REAR BATTERY CASING	Not Necessary	468.00 F	*- FL
34	1		*REAR BATTERY MOUNTING	Not Necessary	310.00 F	*- FL
35	1		*REAR EXHAUST PIPE	Not Necessary	1,193.00 F	*- FL
36	1		*REAR EXHAUST MOUNTING	Not Necessary	104.00 F	*- FL
37	1		*REAR EXHAUST GASKET	Not Necessary	261.00 F	*- FL
38	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	322.00 F	*- FL
39	1		*REAR NUMBER PLATE	Not Necessary	120.00 FS	*- FS
40	2		*REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
41	1		*REVERSE CAM	Not Necessary	1,200.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*50.00 FS
43	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	120.00 FS	*- FS
44	10		*REAR BUMPER CLIPS	Necessary	120.00 FS	*50.00 FS
45	10		*REAR FENDER COWLING CLIPS	Not Necessary	120.00 FS	*- FS
46	10		*REAR FENDER INNER TRIM CLIPS	Not Necessary	120.00 FS	*- FS
47	10		*BOOTLID INNER TRIM CLIPS	Not Necessary	120.00 FS	*- FS
48	10		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 56,369.00 5,067.30
- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 953.46

Total Parts (\$\$) 56,369.00 4,113.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RNR ACCIDENT DAMAGE PARTS ,CUT /WELD ,KNOCK & REALIGN	New	2,500.00	600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	2,500.00	900.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	60.00
4	TO RNR REAR WINDSCREEN	New	400.00	120.00
5	TO RNR REAR BOOT MECHANISM	New	120.00	60.00
6	TO RNR REAR LUGGAGE COMPARTMENT	New	400.00	80.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	300.00	50.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
9	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	New	250.00	20.00
10	TO DO DIAGNOSIS AND RESET ,REPROGRAM OR CODING FAULT CODE	New	800.00	0.00
11	TO DO WATER LEAK TEST	New	120.00	0.00
12	TO RNR FUEL TANK TO ASSIST WORK LOAD	New	120.00	0.00
13	TO RNR HYBRID BATTERY AND PERFORM SAFETY TEST	New	2,500.00	300.00
Gross Labour Cost (\$\$)			10,380.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >