

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC3/AIG20004248/KRA3Q2  
**Date:** 20/12/2021

**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	190006668
<b>Claimant Vehicle No :</b>	SHD9788K	<b>Insured Vehicle No :</b>	SMH2205S
Date of Loss:	17/03/2020	Nature of Claim:	TP
		Claim No:	9110726850SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHD9788K</b>		
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Engine No:	2ZR2H29551
Reg. Date:	30/11/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU003093003
Colour:	Metallic White/Red	Odometer:	774928 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	25,095.67	3,378.02	21,717.65	86.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,850.00	1,660.00	16,190.00	90.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>42,945.67</b>	<b>5,038.02</b>	<b>37,907.65</b>	<b>88.27</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,050.00</b>		

(S\$)	42,945.67	4,050.00	38,895.67	90.57
<b>+ GST 7.00/7.00% (S\$)</b>	3,006.20	283.50	2,722.70	90.57
<b>Nett Amount (S\$)</b>	<b>45,951.87</b>	<b>4,333.50</b>	<b>41,618.37</b>	<b>90.57</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Car Rental (4.0 x S\$95.04/day) (S\$)</b>		380.16		
<b>(S\$)</b>		4,913.66		
<b>Liabe Amount (90.00%) (S\$)</b>		<b>4,422.29</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>+ Other Costs (S\$)</b>		428.00		
<b>Nett Liability (S\$)</b>		<b>4,857.74</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,900.00</b>		

INSPECTION

Date of Assignment: 18/03/2020

Date Inspected: 18/03/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Trans-Cab Auto Services Pte Ltd - Amk (HQ)  
 No 2 Ang Mo Kio St 63  
 Singapore 569111

**Adjuster:** KENNETH KONG**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL FRT LH	Bent	2,844.66 FL	*2,844.66 FL
2	1		*DOOR HINGE UPPER LH	Repair	274.50 FL	*- FL
3	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
4	1		*DOOR CHECK FRT LH	Serviceable	90.90 FL	*- FL
5	1		*DOOR REGULATOR FRT LH	Serviceable	758.10 FL	*- FL
6	1		*DOOR REGULATOR MOTOR FRT LH	Serviceable	501.40 FL	*- FL
7	1		*DOOR REGULATOR GUIDE FRT LH	Serviceable	69.00 FL	*- FL
8	1		*DOOR WEATHERSTRIP FRT LH	Serviceable	316.00 FL	*- FL
9	1		*DOOR SEAL FRONT LH	Serviceable	69.60 FL	*- FL
10	1		*DOOR SEAL FRONT LH	Serviceable	63.10 FL	*- FL
11	1		*DOOR SEAL LOWER FRT LH	Serviceable	93.90 FL	*- FL
12	1		*DOOR MOULDING FRT LH	Serviceable	100.50 FL	*- FL
13	1		*DOOR FINISHER FRT LH	Serviceable	258.90 FL	*- FL
14	1		*DOOR FINISHER CLIP KIT FRT LH	Not Necessary	94.00 FL	*- FL
15	1		*DOOR GLASS RUNNER SEAL FRONT LH	Serviceable	332.00 FL	*- FL
16	1		*DOOR HANDLE OUTER FRONT LH	Serviceable	169.50 FL	*- FL
17	1		*DOOR HANDLE CAP FRONT LH	Serviceable	17.30 FL	*- FL
18	1		*DOOR HANDLE MODULE FRT LH L70Y	Serviceable	133.40 FL	*- FL
19	1		*DOOR LOCK FRT LH	Repair	453.80 FL	*- FL
20	1		*DOOR MIRROR ASSY LH	Serviceable	727.90 FL	*- FL
21	1		*DOOR HARNESS WIRE LH	Serviceable	2,670.00 FL	*- FL
22	1		*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
23	1		*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
24	1		*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	*- FL
25	1		*FENDER PANEL FRT LH	Repair	414.40 FL	*- FL
26	1		*WHEELARCH FRT LH	Serviceable	112.30 FL	*- FL
27	1		*FENDER BRACKET LOWER LH	Serviceable	11.80 FL	*- FL
28	1		*FENDER INSULATOR LH	Serviceable	65.50 FL	*- FL
29	1		*FENDER BRACKET FRT LH	Repair	38.90 FL	*- FL
30	1		*BUMPER COVER FRT	Serviceable	747.20 FL	*- FL
31	1		*BUMPER RETAINER FRT LH	Serviceable	101.40 FL	*- FL
32	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
33	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
34	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
35	1		*DOOR PANEL REAR LH	Bent	758.70 FL	*758.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*DOOR GUIDE REAR LH	Serviceable	136.40 FL	*- FL
37	1		*DOOR HINGE UPPER REAR LH L70Y	Repair	180.70 FL	*- FL
38	1		*DOOR HINGE LOWER REAR LH L70Y	Repair	169.90 FL	*- FL
39	1		*DOOR CHECK REAR LH	Serviceable	114.90 FL	*- FL
40	1		*DOOR REGULATOR REAR LH L70Y	Repair	657.10 FL	*- FL
41	1		*DOOR REGULATOR MOTOR REAR LH L70Y	Serviceable	450.60 FL	*- FL
42	1		*DOOR HANDLE OUTER REAR LH L70Y	Serviceable	42.10 FL	*- FL
43	1		*DOOR HANDLE CAP REAR LH L70Y	Serviceable	57.90 FL	*- FL
44	1		*DOOR HANDLE MODULE REAR LH L70Y	Serviceable	133.40 FL	*- FL
45	1		*DOOR SEAL REAR LH	Serviceable	119.40 FL	*- FL
46	1		*DOOR WEATHERSTRIP REAR LH	Serviceable	240.50 FL	*- FL
47	1		*DOOR GLASS RUBBER SEAL REAR LH	Serviceable	116.10 FL	*- FL
48	1		*DOOR FINISHER REAR LH	Serviceable	230.30 FL	*- FL
49	1		*DOOR WAIST SEAL OUTER REAR LH	Serviceable	169.60 FL	*- FL
50	1		*DOOR MOULDING BLACK REAR LH	Serviceable	100.50 FL	*- FL
51	1		*DOOR LOCK REAR LH L70Y	Repair	468.20 FL	*- FL
52	1		*FENDER PANEL REAR LH	Repair	1,933.20 FL	*- FL
53	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
54	1		*WHEELARCH REAR LH	Serviceable	181.60 FL	*- FL
55	1		*AIR VENT	Serviceable	59.40 FL	*- FL
56	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
57	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
58	1		*BUMPER COVER REAR	Repair	561.70 FL	*- FL
59	1		*BUMPER LOWER REAR	Serviceable	411.90 FL	*- FL
60	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
61	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
62	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
63	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL
64	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
65	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
66	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
67	1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	*60.00 FS
68	1		*LH SIDE RENAULT TYRE 215/60/16	Serviceable	330.00 FS	*- FS
69	1		*LH SIDE RENAULT TYRE RIM	Serviceable	380.00 FS	*- FS
70	1		*WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
71	1		*REAR WINDSCREEN MOULDING	Not Necessary	160.00 FS	*- FS
72	2		*WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
73	1		*REAR WINDSCREEN INNER SPONGE SEAL	Serviceable	100.00 FS	*- FS
74	1		*DOOR CHECK BOLT	Serviceable	10.20 FS	*- FS
75	1		*DOOR CHECK NUT	Serviceable	10.20 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*DOOR GUIDE SCREW	Serviceable	10.85 FS	*- FS
77	1		*DOOR HINGE BOLT	Serviceable	12.60 FS	*- FS
78	1		*DOOR HINGE NUT LH	Serviceable	7.20 FS	*- FS
79	1		*DOOR SEAL CLIP LH	Not Necessary	4.90 FS	*- FS
80	1		*DOOR MOULDING CLIP	Not Necessary	5.90 FS	*- FS
81	1		*BUMPER CLIP FRT	Not Necessary	66.00 FS	*- FS
82	1		*SET BUMPER RETAINER FRONT LH	Not Necessary	35.00 FS	*- FS
83	1		*TAILLAMP CLIL LH	Not Necessary	5.00 FS	*- FS
84	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
85	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
86	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
87	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
88	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
89	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
90	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
91	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
92	1		*REAR BUMPER PROTECTOR	Serviceable	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>27,595.71</b>	<b>3,738.36</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	2,500.04	360.34
<b>Total Parts (\$)</b>	<b>25,095.67</b>	<b>3,378.02</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	7,500.00	500.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	880.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	80.00
9	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
10	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
11	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
12	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
13	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
15	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
16	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>17,850.00</b>	<b>1,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >