

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20004251/GPS3Q2
Date: 30/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1900102739	
Claimant Vehicle No : SFW9109U	Insured Vehicle No : SML6839R	
Date of Loss: 14/03/2020	Nature of Claim: TP	Claim No: 4075969968SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFW9109U		
Make & Model: TOYOTA ESTIMA, 2.4 (A)	Engine No: 2AZF181435	
Reg. Date: 25/09/2008 (Man. Year: 2008)	Chassis No: ACR507067359	
Colour: Silver	Odometer: 182877 km	
Engine Capacity: 2362 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R18	Rear Tyre Size: 225/50R18	
Front Left Side: Bridgestone 6 mm	Rear Left Side: Bridgestone 6 mm	
Front Right Side: Bridgestone 6 mm	Rear Right Side: Bridgestone 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	400.00	600.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,000.00	400.00	600.00	60.00
+ GST 7.00/7.00% (\$\$)	70.00	28.00	42.00	60.00
Nett Amount (\$\$)	1,070.00	428.00	642.00	60.00
+ Loss of Use (2.0 x S\$90.00/day) (\$\$)		180.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		610.00		
Global Sum Settlement (\$\$)		610.00		

INSPECTION

Date of Assignment: 18/03/2020		
Date Inspected: 18/03/2020	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair: 2.0 days		

3/30/2021

Adjuster Report

Adjuster: XING GUO QIANG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTEN THE O/S REAR PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	350.00	200.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	650.00	200.00
Gross Labour Cost (\$\$)			1,000.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >