

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20004254/QEA3Q2

Date: 29/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100427382
Claimant		
Vehicle No : SHB144M	Insured Vehicle No :	SKV959M
Date of Loss: 14/03/2020	Nature of Claim: TP	Claim No: 7990396566SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB144M	Engine No:	2ZRS105065
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU403574436
Reg. Date:	28/11/2017 (Man. Year: 2017)	Odometer:	249903 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,987.44	39.68	6,947.76	99.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,312.00	600.00	1,712.00	74.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	9,299.44	639.68	8,659.76	93.12
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	17/03/2020	
Date Inspected:	17/03/2020 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: OI SUN PIN

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
2	1		*COVER ,FR BUMPER	Repair	495.50 F	*- F
3	1		*FENDER SUB-ASSY ,FR ,LH	Repair	933.10 F	*- F
4	1		*CLIPS PIECE ,FRT & RR BUMPER	Serviceable	1.50 F	*- F
5	1		*SUPPORT ,FR BUMPER LH	Serviceable	82.30 F	*- F
6	1		*SUPPORT ,FR BUMPER RH	Serviceable	76.90 F	*- F
7	1		*LAMP ASSY ,FOG ,LH	Serviceable	910.20 F	*- F
8	1		*UNIT HEADLAMP ,LH	Serviceable	2,558.90 F	*- F
9	1		*LINER ,FR FENDER ,LH	Serviceable	194.30 F	*- F
10	1		*TYRE	Serviceable	126.74 F	*- F
11	1		*WHEEL ,DISC	Serviceable	1,555.10 F	*- F
					Total Parts (S\$)	6,987.44 39.68

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	936.00	400.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
6	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
7	TO REMOVE AND REFIT WIRE HARDESS	New	120.00	0.00
8	TO REPLACE SUNDRY PARTS	New	100.00	0.00
9	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			2,312.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >