Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20004259/AGS3Q2

Date: 14/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993863

Claimant Vehicle No: Insured Vehicle No: SMF4881L

Date of Loss: 17/03/2020 Nature of Claim: TP Claim No: 9319335520SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM69S

Make & Model: AUDI S4, 3.0 TFSI QU S-TRONIC (A) Engine No: CWG003119

Reg. Date: 09/03/2017 (Man. Year: 2016) Chassis No: WAUZZZF47HA095266

Colour: Black Odometer: 60947 km

Engine Capacity: 2995 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm
Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		26,768.00	12,299.28	14,468.72	54.05
Miscellaneous Items		0.00	0.00	0.00	
Labour		24,162.00	9,662.00	14,500.00	60.01
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	50,930.00	21,961.28	28,968.72	56.88
	+ GST 7.00/7.00% (S\$)	3,565.10	1,537.29	2,027.81	56.88
	Nett Amount (S\$)	54,495.10	23,498.57	30,996.53	56.88
	+ Loss of Use (14.0 x S	\$100.00/day) (S\$)	1,400.00		
	+ Doo	/Search Fee (S\$)	7.45		
	1	Nett Liability (S\$)	24,906.02		

INSPECTION

Date of Assignment: 24/03/2020

Date Inspected: 24/03/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING Manager: Chong Pui Lin

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

2 1 *REAR BUMPER FIXING PARTS Not Necessary 69.00 FS *-FS 3 1 *REAR BUMPER SECURING STRIP Not Necessary 210.00 FS *-FS 4 1 *REAR BUMPER TRIM Cut 275.00 FS *219.60 FS 5 2 *REAR BUMPER TRIM LH/RH Not Necessary 76.00 FS *-FS 6 2 *REAR LIGHT REFLECTOR -LH/RH Cut 78.00 FS *-FS 7 2 *REAR PARKING AID SENSOR -INNER /OUTER (NPA) Not Necessary 0.00 FS *-FS 8 1 *REAR BUMPER CARRIER Bent 955.00 FS *675.60 FS 9 2 *REAR BUMPER CARRIER Bent 955.00 FS *20.80 FS 10 1 *REAR BUMPER GUIDE SECTION -LH Not Necessary 41.00 FS *-FS 11 1 *REAR BUMPER GUIDE SECTION -LH Not Necessary 41.00 FS *-FS 12 2 *REAR BUMPER GUIDE SECTION -LH/RH Damaged 42.00 FS *33.12 FS 13 1 *TAILGATE OPENING SENSOR LINE Not Necessary 396.00 FS *-FS 14 1 *BOOT LID CONTROL UNIT Not Necessary 396.00 FS *-FS 15 1 *REAR LID Dented 2,496.00 FS *1,996.80 FS 16 2 *REAR LID HINGE -LH/RH Not Necessary 432.00 FS *-FS 17 1 *REAR LID DOK NOT NECESSARY 31.00 FS *-FS 18 1 *REAR LID HINGE -LH/RH Not Necessary 31.00 FS *-FS 19 1 *REAR LID LOCK STRIKER NOT Necessary 31.00 FS *-FS 19 1 *REAR LID LOCK STRIKER NOT Necessary 18.00 FS *-FS 20 1 *PACKING ADHESIVE Necessary 117.00 FS *-FS 21 1 *AUDI EMBLEM Necessary 117.00 FS *-93.20 FS 22 1 *S4 INSCRIPTION Necessary 117.00 FS *93.20 FS 23 1 *REAR LID SPOILER (NPA) NOT Necessary 117.00 FS *-FS	No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
TREAR BUMPER SECURING STRIP	1	1	*REAR BUMPER	Deformed	2,687.00 FS	*2,149.60 FS
1	2	1	*REAR BUMPER FIXING PARTS	Not Necessary	69.00 FS	*-FS
5 2 "REAR BUMPER TRIM -LH/RH Not Necessary 76.00 FS "-FS 6 2 "REAR LIGHT REFLECTOR -LH/RH Cut 78.00 FS "61.28 FS 7 2 "REAR PARKING AID SENSOR -INNER /OUTER (NPA) Not Necessary 26.00 FS "-FS 8 1 "REAR BUMPER CARRIER Bent 955.00 FS "57.60 FS 9 2 "REAR BUMPER CARRIER Bent 955.00 FS "20.80 FS 10 1 "REAR BUMPER GUIDE SECTION -LH Not Necessary 41.00 FS "-FS 11 1 "REAR BUMPER GUIDE SECTION -LH/RH Not Necessary 43.00 FS "-FS 13 1 "TAILGATE OPENING SENSOR LINE Not Necessary 194.00 FS "-FS 14 1 "BOOT LID CONTROL UNIT Not Necessary 194.00 FS "-FS 15 1 "REAR LID Dented 2.496.00 FS "-1996.80 FS 16 2 "REAR LID HINGE -LH/RH Not Necessary 130.00 FS "-FS 16 1 "REAR LID LOCK	3	1	*REAR BUMPER SECURING STRIP	Not Necessary	210.00 FS	*-FS
6 2 *REAR LIGHT REFLECTOR -LH/RH Cut 78.00 FS *61.28 FS 8 1 *REAR PARKING AID SENSOR -INNER /OUTER (IPA) Not Necessary 0.00 FS *675.60 FS 8 1 *REAR BUMPER CARRIER Bent 955.00 FS *675.60 FS 9 2 *REAR BUMPER GUIDE SECTION -LH Not Necessary 26.00 FS *20.80 FS 111 1 *REAR BUMPER GUIDE SECTION -H Not Necessary 41.00 FS *-FS 112 2 *REAR BUMPER GUIDE SECTION -LH/RH Damaged 42.00 FS *33.12 FS 112 2 *REAR BUMPER GUIDE SECTION -LH/RH Damaged 42.00 FS *-FS 114 1 *BOOT LID CONTROL UNIT Not Necessary 396.00 FS *-FS 115 1 *REAR LID **-FS *-FS 116 2 *REAR LID LOCK Not Necessary 217.00 FS *-FS 117 1 *REAR LID LOCK Not Necessary 31.00 FS *-FS 117 1 *REAR LID LOCK Not Necessary	4	1	*REAR BUMPER TRIM	Cut	275.00 FS	*219.60 FS
REAR PARKING AID SENSOR -INNER /OUTER (NPA) Not Necessary	5	2	*REAR BUMPER TRIM -LH/RH	Not Necessary	76.00 FS	*-FS
REAR BUMPER CARRIER	6	2	*REAR LIGHT REFLECTOR -LH/RH	Cut	78.00 FS	*61.28 FS
Pack	7	2	*REAR PARKING AID SENSOR -INNER /OUTER (NPA)	Not Necessary	0.00 FS	*-FS
10	8	1	*REAR BUMPER CARRIER	Bent	955.00 FS	*675.60 FS
11	9	2	*REAR BUMPER CARRIER SEAL	Necessary	26.00 FS	*20.80 FS
12 2 *REAR BUMPER GUIDE SECTION -LH/RH	10	1	*REAR BUMPER GUIDE SECTION -LH	Not Necessary	41.00 FS	*-FS
**TAILGATE OPENING SENSOR LINE Not Necessary 194.00 FS *-FS 196.00	11	1	*REAR BUMPER GUIDE SECTION -RH	Not Necessary	43.00 FS	*-FS
1	12	2	*REAR BUMPER GUIDE SECTION -LH/RH	Damaged	42.00 FS	*33.12 FS
**REAR LID	13	1	*TAILGATE OPENING SENSOR LINE	Not Necessary	194.00 FS	*- FS
16 2 *REAR LID HINGE -LH/RH Not Necessary 432.00 FS *-FS 17 1 *REAR LID LOCK Not Necessary 217.00 FS *-FS 18 1 *REAR LID LOCK STRIKER Not Necessary 31.00 FS *-FS 19 1 *REAR LID FLAP GASKET Not Necessary 119.00 FS *-FS 20 1 *PACKING ADHESIVE Necessary 117.00 FS **93.20 FS 21 1 *AUDI EMBLEM Necessary 117.00 FS *93.20 FS 21 1 **4 INSCRIPTION Not Necessary 117.00 FS *93.20 FS 22 1 **54 INSCRIPTION Not Necessary 117.00 FS *93.20 FS 23 1 **REAR LID SPOILER (NPA) Not Necessary 10.00 FS *-FS 24 2 **LED TAIL LIGHT T.H/RH OUTER Cut 1,918.00 FS *1,534.40 FS 25 2 **TAIL LIGHT TRIM -LH/RH INNER Cut 56.00 FS *44.32 FS 26 2 **LED TAIL LIGHT TRIM -LH/RH INNER	14	1	*BOOT LID CONTROL UNIT	Not Necessary	396.00 FS	*- FS
**REAR LID LOCK Not Necessary 217.00 FS *-FS 18 1 **REAR LID LOCK STRIKER Not Necessary 31.00 FS *-FS 19 1 **REAR LID FLAP GASKET Not Necessary 193.00 FS *-FS 20 1 **PACKING ADHESIVE Necessary 18.00 FS *-14.24 FS 14.24 FS Necessary 117.00 FS *93.20 FS *-15.24 1 **AUDI EMBLEM Necessary 117.00 FS *93.20 FS *-52.24 1 **SA INSCRIPTION Necessary 117.00 FS *93.20 FS *-52.24 2 **LED TAIL LIGHT -LH/RH OUTER Cut 1,918.00 FS *1,534.40 FS *-52.25 2 **TAIL LIGHT TEIM -LH /RH OUTER Cut 1,918.00 FS *1,534.40 FS *-52.25 2 **TAIL LIGHT TEIM -LH /RH OUTER Cut 1,918.00 FS *1,534.40 FS *-52.25 2 **TAIL LIGHT TEIM -LH /RH INNER Cut 1,918.00 FS *1,534.40 FS *-52.25 2 **TAIL LIGHT TEIM -LH /RH INNER Cut 56.00 FS *44.32 FS *-52.25 2 **TAIL LIGHT TEIM -LH /RH INNER Cut 56.00 FS *44.32 FS *-52.25 2 **TAIL LIGHT TEIM -LH /RH INNER Cut 56.00 FS *44.32 FS *-52.25 1 **REAR CROSS PANEL Dented 245.00 FS *195.60 FS *-153.35 1 **REAR CROSS PANEL REINFORCEMENT Dented 245.00 FS *-36.00 FS *-53.35 1 **REAR CROSS PANEL TRIM Not Necessary 156.00 FS *-58.35 1 **REAR SIDE PANEL REINFORCEMENT -RH Buckled 194.00 FS *-58.35 1 **REAR SIDE PANEL REINFORCEMENT -RH Buckled 194.00 FS *-58.35 1 **REAR WINDSCREEN Not Necessary 37.00 FS *-58.35 1 **REAR WINDSCREEN Not Necessary 37.00 FS *-58.35 1 **REAR SIDE PANEL REINFORCEMENT -RH Not Necessary 37.00 FS *-58.35 1 **REAR SIDE PANEL REINFORCEMENT -RH Not Necessary 37.00 FS *-58.35 1 **REAR SIDE PANEL REINFORCEMENT -RH Not Necessary 37.00 FS *-58.35 1 **REAR WINDSCREEN Not Necessary 37.00 FS *-58.35 1 **REAR SIDE PANEL REINFORCEMENT -RH Not Necessary 37.00 FS *-58.35 1 **REAR SIDE PANEL REINFORCEMENT -RH Not Necessary 37.00 FS *-58.35 1 **REAR SIDE PANEL REINFORCEMENT -RH Not Necessary 37.00 FS *-58.35 1 **	15	1	*REAR LID	Dented	2,496.00 FS	*1,996.80 FS
**REAR LID LOCK	16	2	*REAR LID HINGE -LH/RH	Not Necessary		
18 1 *REAR LID LOCK STRIKER Not Necessary 31.00 FS *-FS 19 1 *REAR LID FLAP GASKET Not Necessary 193.00 FS *-FS 20 1 *PACKING ADHESIVE Necessary 117.00 FS **14.24 FS 21 1 *AUDI EMBLEM Necessary 117.00 FS *93.20 FS 22 1 *S4 INSCRIPTION Necessary 117.00 FS *93.20 FS 23 1 *REAR LID SPOILER (NPA) Not Necessary 0.00 FS *-FS 24 2 *LED TAIL LIGHT *LH/RH OUTER Cut 1,918.00 FS *1,534.40 FS 25 2 *LED TAIL LIGHT *LH/RH INNER Cut 56.00 FS *1,534.40 FS 26 2 *LED TAIL LIGHT *LH/RH INNER Cut 1,918.00 FS *1,534.40 FS 27 2 *TAIL LIGHT *TRIM *LH/RH INNER Cut 1,918.00 FS *1,534.40 FS 28 1 *REAR CROSS PANEL Dented 245.00 FS *195.60 FS *195.60 FS *195.60 FS *195.60 FS *195	17	1	*REAR LID LOCK	Not Necessary	217.00 FS	*-FS
1	18	1	*REAR LID LOCK STRIKER	•		
Packing Adhesive Necessary 18.00 FS *14.24 FS	19	1	*REAR LID FLAP GASKET	•		*-FS
21	20	1	*PACKING ADHESIVE	•		*14.24 FS
1	21	1	*AUDI EMBLEM	•		
23 1 *REAR LID SPOILER (NPA) Not Necessary 0.00 FS *-FS 24 2 *LED TAIL LIGHT -LH/RH OUTER Cut 1,918.00 FS *1,534.40 FS 25 2 *TAIL LIGHT TRIM -LH /RH OUTER Cut 56.00 FS *44.32 FS 26 2 *LED TAIL LIGHT -LH/RH INNER Cut 1,918.00 FS *1,534.40 FS 27 2 *TAIL LIGHT TRIM -LH/RH INNER Cut 56.00 FS *44.32 FS 28 1 *REAR CROSS PANEL Dented 245.00 FS *195.60 FS 29 1 *CROSS PANEL DENTED 245.00 FS *195.60 FS 29 1 *CROSS PANEL REINFORCEMENT DENTED 475.00 FS *380.00 FS 30 1 *REAR CROSS PANEL TRIM NOT NECESSARY 156.00 FS *-FS 31 1 *SIDE PANEL -RH REPARED 50 FS *-FS 32 1 *WHEEL HOUAING LINER ATTACHMENT PARTS NOT NECESSARY 86.00 FS *-FS 33 1 *REAR SIDE PANEL REINFORCEMENT -RH NOT NECESSARY 92.00 FS *-FS 34 1 *SIDE PANEL SUPPORT -RH NOT NECESSARY 92.00 FS *-FS 35 1 *REAR WINDSCREEN NOT NECESSARY 92.00 FS *-FS 36 1 *SIDE WINDOW -RH NOT NECESSARY 37.00 FS *-FS 37 2 *PRIMER NOT NECESSARY 37.00 FS *-FS 38 1 *EXHAUST SILENCER BRACKET NOT NECESSARY 40.00 FS *-FS 39 1 *REAR BUMPER LOWER DIFFUSAL Cracked 2,180.00 FS *-FS 40 1 *CAVITY WAX NECESSARY 180.00 FS *-FS 41 1 *ACRYLIC SEALANT NOT NECESSARY 180.00 FS *-FS 41 1 *CAVITY WAX NECESSARY 180.00 FS *-FS 42 1 *CAVITY WAX NECESSARY 180.00 FS *-FS 44 1 *STONE CHIP NECESSARY 180.00 FS *-FS 45 1 *REAR WINDSCREEN NOT NECESSARY 180.00 FS *-FS 46 1 *TI/4 GLASS SEALANT NOT NECESSARY 280.00 FS *-FS 47 1 *REAR NO PLATE NOT NECESSARY 100.00 FS *-FS 47 1 *REAR NO PLATE NOT NECESSARY 180.00 FS *-FS 48 1 *-FS 49 1 *-FS 40 1 *-FS 40 1 *-FS 41 *-FS 41 *-FS 41 *-FS 41 *-FS 42 *-FS 43 *-FS 44 *-FS 44 *-FS 45 *-FS 46 *-FS 47 *-FS 47 *-FS 48 *-FS 49 *-	22	1	*S4 INSCRIPTION	•		
24 2 *LED TAIL LIGHT -LH/RH OUTER Cut 1,918.00 FS *1,534.40 FS 25 2 *TAIL LIGHT TRIM -LH /RH OUTER Cut 56.00 FS *44.32 FS 26 2 *LED TAIL LIGHT T-LH/RH INNER Cut 1,918.00 FS *1,534.40 FS 27 2 *TAIL LIGHT TRIM -LH/RH INNER Cut 56.00 FS *44.32 FS 28 1 *REAR CROSS PANEL Dented 245.00 FS *195.60 FS 29 1 *CROSS PANEL REINFORCEMENT Dented 475.00 FS *380.00 FS 30 1 *REAR CROSS PANEL TRIM Not Necessary 156.00 FS *-FS 31 1 *SIDE PANEL -RH Repair 2,518.00 FS *-FS 32 1 *WHEEL HOUAING LINER ATTACHMENT PARTS Not Necessary 86.00 FS *-FS 33 1 *REAR SIDE PANEL SUPPORT -RH Not Necessary 92.00 FS *-FS 34 1 *SIDE PANEL SUPPORT -RH Not Necessary 1,085.00 FS *-FS 35 1 *REAR WINDSCREEN Not Necessary 1,085.00 FS *-FS 36 1 *SIDE WINDOW -RH <td< th=""><th></th><th>1</th><th></th><th>•</th><th></th><th></th></td<>		1		•		
25 2 *TAIL LIGHT TRIM -LH /RH OUTER Cut 56.00 FS *44.32 FS 26 2 *LED TAIL LIGHT -LH/RH INNER Cut 1,918.00 FS *1,534.40 FS 27 2 *TAIL LIGHT TRIM -LH/RH INNER Cut 56.00 FS *44.32 FS 28 1 *REAR CROSS PANEL Dented 245.00 FS *195.60 FS 29 1 *CROSS PANEL REINFORCEMENT Dented 475.00 FS *380.00 FS 30 1 *REAR CROSS PANEL TRIM Not Necessary 156.00 FS *-FS 31 1 *SIDE PANEL -RH Repair 2,518.00 FS *-FS 32 1 *WHEEL HOUAING LINER ATTACHMENT PARTS Not Necessary 86.00 FS *-FS 33 1 *REAR SIDE PANEL REINFORCEMENT -RH Buckled 194.00 FS *154.80 FS 34 1 *SIDE PANEL SUPPORT -RH Not Necessary 1,085.00 FS *-FS 35 1 *REAR WINDSCREEN Not Necessary 17.00 FS *-FS 36 1 *SIDE WIND	24	-	· · · · · · · · · · · · · · · · · · ·	•		
26 2 *LED TAIL LIGHT -LH/RH INNER Cut 1,918.00 FS *1,534.40 FS 27 2 *TAIL LIGHT TRIM -LH/RH INNER Cut 56.00 FS *44.32 FS 28 1 *REAR CROSS PANEL Dented 245.00 FS *195.60 FS 29 1 *CROSS PANEL REINFORCEMENT Dented 475.00 FS *380.00 FS 30 1 *REAR CROSS PANEL TRIM Not Necessary 156.00 FS *-FS 31 1 *SIDE PANEL -RH Repair 2,518.00 FS *-FS 32 1 *WHEEL HOUAING LINER ATTACHMENT PARTS Not Necessary 86.00 FS *-FS 33 1 *REAR SIDE PANEL REINFORCEMENT -RH Buckled 194.00 FS *-154 34 1 *SIDE PANEL SUPPORT -RH Not Necessary 92.00 FS *-FS 35 1 *REAR WINDSCREEN Not Necessary 1,085.00 FS *-FS 36 1 *SIDE WINDOW -RH Not Necessary 37.00 FS *-FS 37 2 *PRIMER Not Necessary <th></th> <th></th> <th></th> <th></th> <th></th> <th></th>						
27 2 *TAIL LIGHT TRIM -LH/RH INNER Cut 56.00 FS *44.32 FS 28 1 *REAR CROSS PANEL Dented 245.00 FS *195.60 FS 29 1 *CROSS PANEL REINFORCEMENT Dented 475.00 FS *380.00 FS 30 1 *REAR CROSS PANEL TRIM Not Necessary 156.00 FS *-FS 31 1 *SIDE PANEL REINFORCEMENT PARTS Not Necessary 86.00 FS *-FS 32 1 *WHEEL HOUAING LINER ATTACHMENT PARTS Not Necessary 86.00 FS *-FS 33 1 *REAR SIDE PANEL REINFORCEMENT -RH Buckled 194.00 FS *154.80 FS 34 1 *SIDE PANEL SUPPORT -RH Not Necessary 92.00 FS *-FS 35 1 *REAR WINDSCREEN Not Necessary 1,085.00 FS *-FS 36 1 *SIDE WINDOW -RH Not Necessary 579.00 FS *-FS 37 2 *PRIMER Not Necessary 40.00 FS *-FS 38 1 *EXHAUST SILENCER BR						
28 1 *REAR CROSS PANEL Dented 245.00 FS *195.60 FS 29 1 *CROSS PANEL REINFORCEMENT Dented 475.00 FS *380.00 FS 30 1 *REAR CROSS PANEL TRIM Not Necessary 156.00 FS *-FS 31 1 *SIDE PANEL -RH Repair 2,518.00 FS *-FS 32 1 *WHEEL HOUAING LINER ATTACHMENT PARTS Not Necessary 86.00 FS *-FS 33 1 *REAR SIDE PANEL REINFORCEMENT -RH Buckled 194.00 FS *154.80 FS 34 1 *SIDE PANEL SUPPORT -RH Not Necessary 92.00 FS *-FS 35 1 *REAR WINDSCREEN Not Necessary 1,085.00 FS *-FS 36 1 *SIDE WINDOW -RH Not Necessary 1,085.00 FS *-FS 37 2 *PRIMER Not Necessary 37.00 FS *-FS 38 1 *EXHAUST SILENCER BRACKET Not Necessary 40.00 FS *-FS 40 1 *EXHAUST TIP Not Nec			*TAIL LIGHT TRIM -LH/RH INNER			
29 1 *CROSS PANEL REINFORCEMENT Dented 475.00 FS *380.00 FS 30 1 *REAR CROSS PANEL TRIM Not Necessary 156.00 FS *-FS 31 1 *SIDE PANEL -RH Repair 2,518.00 FS *-FS 32 1 *WHEEL HOUAING LINER ATTACHMENT PARTS Not Necessary 86.00 FS *-FS 33 1 *REAR SIDE PANEL REINFORCEMENT -RH Buckled 194.00 FS *154.80 FS 34 1 *SIDE PANEL SUPPORT -RH Not Necessary 92.00 FS *-FS 35 1 *REAR WINDSCREEN Not Necessary 1,085.00 FS *-FS 36 1 *SIDE WINDOW -RH Not Necessary 579.00 FS *-FS 37 2 *PRIMER Not Necessary 37.00 FS *-FS 38 1 *EXHAUST SILENCER BRACKET Not Necessary 40.00 FS *-FS 40 1 *EXHAUST TIP Not Necessary 4680.00 FS *-FS 41 1 *ACRYLIC SEALANT Necessar		_				
30 1 *REAR CROSS PANEL TRIM Not Necessary 156.00 FS *-FS 31 1 *SIDE PANEL -RH Repair 2,518.00 FS *-FS 32 1 *WHEEL HOUAING LINER ATTACHMENT PARTS Not Necessary 86.00 FS *-FS 33 1 *REAR SIDE PANEL REINFORCEMENT -RH Buckled 194.00 FS *154.80 FS 34 1 *SIDE PANEL SUPPORT -RH Not Necessary 92.00 FS *-FS 35 1 *REAR WINDSCREEN Not Necessary 1,085.00 FS *-FS 36 1 *SIDE WINDOW -RH Not Necessary 579.00 FS *-FS 37 2 *PRIMER Not Necessary 37.00 FS *-FS 38 1 *EXHAUST SILENCER BRACKET Not Necessary 40.00 FS *-FS 39 1 *REAR BUMPER LOWER DIFFUSAL Cracked 2,180.00 FS *-FS 40 1 *EXHAUST TIP Not Necessary 4,680.00 FS *-FS 41 1 *ACRYLIC SEALANT Necessary						
31 1 *SIDE PANEL -RH Repair 2,518.00 FS *-FS 32 1 *WHEEL HOUAING LINER ATTACHMENT PARTS Not Necessary 86.00 FS *-FS 33 1 *REAR SIDE PANEL REINFORCEMENT -RH Buckled 194.00 FS *154.80 FS 34 1 *SIDE PANEL SUPPORT -RH Not Necessary 92.00 FS *-FS 35 1 *REAR WINDSCREEN Not Necessary 1,085.00 FS *-FS 36 1 *SIDE WINDOW -RH Not Necessary 579.00 FS *-FS 37 2 *PRIMER Not Necessary 37.00 FS *-FS 38 1 *EXHAUST SILENCER BRACKET Not Necessary 40.00 FS *-FS 39 1 *REAR BUMPER LOWER DIFFUSAL Cracked 2,180.00 FS *2,180.00 FS *-FS 40 1 *EXHAUST TIP Not Necessary 4,680.00 FS *-FS 41 1 *ACRYLIC SEALANT Necessary 180.00 FS *180.00 FS 43 1 *STONE CHIP		1				
32 1 *WHEEL HOUAING LINER ATTACHMENT PARTS Not Necessary 86.00 FS *-FS 33 1 *REAR SIDE PANEL REINFORCEMENT -RH Buckled 194.00 FS *154.80 FS 34 1 *SIDE PANEL SUPPORT -RH Not Necessary 92.00 FS *-FS 35 1 *REAR WINDSCREEN Not Necessary 1,085.00 FS *-FS 36 1 *SIDE WINDOW -RH Not Necessary 579.00 FS *-FS 37 2 *PRIMER Not Necessary 37.00 FS *-FS 38 1 *EXHAUST SILENCER BRACKET Not Necessary 40.00 FS *-FS 39 1 *REAR BUMPER LOWER DIFFUSAL Cracked 2,180.00 FS *2,180.00 FS 40 1 *EXHAUST TIP Not Necessary 4,680.00 FS *-FS 41 1 *ACRYLIC SEALANT Necessary 180.00 FS *180.00 FS 42 1 *CAVITY WAX Necessary 180.00 FS *180.00 FS 43 1 *STONE CHIP Necessa						
33 1 *REAR SIDE PANEL REINFORCEMENT -RH Buckled 194.00 FS *154.80 FS 34 1 *SIDE PANEL SUPPORT -RH Not Necessary 92.00 FS *-FS 35 1 *REAR WINDSCREEN Not Necessary 1,085.00 FS *-FS 36 1 *SIDE WINDOW -RH Not Necessary 579.00 FS *-FS 37 2 *PRIMER Not Necessary 37.00 FS *-FS 38 1 *EXHAUST SILENCER BRACKET Not Necessary 40.00 FS *-FS 39 1 *REAR BUMPER LOWER DIFFUSAL Cracked 2,180.00 FS *-FS 40 1 *EXHAUST TIP Not Necessary 4,680.00 FS *-FS 41 1 *ACRYLIC SEALANT Necessary 180.00 FS *180.00 FS 42 1 *CAVITY WAX Necessary 180.00 FS *180.00 FS 43 1 *STONE CHIP Necessary 280.00 FS *280.00 FS 44 1 *METAL FILLER POWDER Not Necessary <t< th=""><th></th><th>=</th><th></th><th>•</th><th></th><th></th></t<>		=		•		
34 1 *SIDE PANEL SUPPORT -RH Not Necessary 92.00 FS *-FS 35 1 *REAR WINDSCREEN Not Necessary 1,085.00 FS *-FS 36 1 *SIDE WINDOW -RH Not Necessary 579.00 FS *-FS 37 2 *PRIMER Not Necessary 37.00 FS *-FS 38 1 *EXHAUST SILENCER BRACKET Not Necessary 40.00 FS *-FS 39 1 *REAR BUMPER LOWER DIFFUSAL Cracked 2,180.00 FS *2,180.00 FS *-FS 40 1 *EXHAUST TIP Not Necessary 4,680.00 FS *-FS 41 1 *ACRYLIC SEALANT Necessary 180.00 FS *180.00 FS 42 1 *CAVITY WAX Necessary 180.00 FS *140.00 FS 43 1 *STONE CHIP Necessary 180.00 FS *280.00 FS 44 1 *METAL FILLER POWDER Necessary 280.00 FS *-FS 45 1 *REAR WINDSCREEN SEALANT Not Necessary		-		•		
35 1 *REAR WINDSCREEN Not Necessary 1,085.00 FS *-FS 36 1 *SIDE WINDOW -RH Not Necessary 579.00 FS *-FS 37 2 *PRIMER Not Necessary 37.00 FS *-FS 38 1 *EXHAUST SILENCER BRACKET Not Necessary 40.00 FS *-FS 39 1 *REAR BUMPER LOWER DIFFUSAL Cracked 2,180.00 FS *2,180.00 FS 40 1 *EXHAUST TIP Not Necessary 4,680.00 FS *-FS 41 1 *ACRYLIC SEALANT Necessary 180.00 FS *180.00 FS 42 1 *CAVITY WAX Necessary 140.00 FS *140.00 FS 43 1 *STONE CHIP Necessary 180.00 FS *180.00 FS 44 1 *METAL FILLER POWDER Necessary 280.00 FS *280.00 FS 45 1 *REAR WINDSCREEN SEALANT Not Necessary 200.00 FS *-FS 46 1 *1/4 GLASS SEALANT Not Necessary 60		-				
36 1 *SIDE WINDOW -RH Not Necessary 579.00 FS *-FS 37 2 *PRIMER Not Necessary 37.00 FS *-FS 38 1 *EXHAUST SILENCER BRACKET Not Necessary 40.00 FS *-FS 39 1 *REAR BUMPER LOWER DIFFUSAL Cracked 2,180.00 FS *2,180.00 FS 40 1 *EXHAUST TIP Not Necessary 4,680.00 FS *-FS 41 1 *ACRYLIC SEALANT Necessary 180.00 FS *180.00 FS 42 1 *CAVITY WAX Necessary 140.00 FS *140.00 FS 43 1 *STONE CHIP Necessary 180.00 FS *180.00 FS 44 1 *METAL FILLER POWDER Necessary 280.00 FS *280.00 FS 45 1 *REAR WINDSCREEN SEALANT Not Necessary 200.00 FS *-FS 46 1 *1/4 GLASS SEALANT Not Necessary 60.00 FS *-FS 47 1 *REAR NO PLATE Not Necessary 60.00 F		1				
37 2 *PRIMER Not Necessary 37.00 FS *-FS 38 1 *EXHAUST SILENCER BRACKET Not Necessary 40.00 FS *-FS 39 1 *REAR BUMPER LOWER DIFFUSAL Cracked 2,180.00 FS *2,180.00 FS 40 1 *EXHAUST TIP Not Necessary 4,680.00 FS *-FS 41 1 *ACRYLIC SEALANT Necessary 180.00 FS *180.00 FS 42 1 *CAVITY WAX Necessary 140.00 FS *140.00 FS 43 1 *STONE CHIP Necessary 180.00 FS *180.00 FS 44 1 *METAL FILLER POWDER Necessary 280.00 FS *280.00 FS 45 1 *REAR WINDSCREEN SEALANT Not Necessary 200.00 FS *-FS 46 1 *1/4 GLASS SEALANT Not Necessary 100.00 FS *-FS 47 1 *REAR NO PLATE Not Necessary 60.00 FS *-FS						
38 1 *EXHAUST SILENCER BRACKET Not Necessary 40.00 FS *-FS 39 1 *REAR BUMPER LOWER DIFFUSAL Cracked 2,180.00 FS *2,180.00 FS 40 1 *EXHAUST TIP Not Necessary 4,680.00 FS *-FS 41 1 *ACRYLIC SEALANT Necessary 180.00 FS *180.00 FS 42 1 *CAVITY WAX Necessary 140.00 FS *140.00 FS 43 1 *STONE CHIP Necessary 180.00 FS *180.00 FS 44 1 *METAL FILLER POWDER Necessary 280.00 FS *280.00 FS 45 1 *REAR WINDSCREEN SEALANT Not Necessary 200.00 FS *-FS 46 1 *1/4 GLASS SEALANT Not Necessary 100.00 FS *-FS 47 1 *REAR NO PLATE Not Necessary 60.00 FS *-FS						
39 1 *REAR BUMPER LOWER DIFFUSAL Cracked 2,180.00 FS *2,180.00 FS 40 1 *EXHAUST TIP Not Necessary 4,680.00 FS *-FS 41 1 *ACRYLIC SEALANT Necessary 180.00 FS *180.00 FS 42 1 *CAVITY WAX Necessary 140.00 FS *140.00 FS 43 1 *STONE CHIP Necessary 180.00 FS *180.00 FS 44 1 *METAL FILLER POWDER Necessary 280.00 FS *280.00 FS 45 1 *REAR WINDSCREEN SEALANT Not Necessary 200.00 FS *-FS 46 1 *1/4 GLASS SEALANT Not Necessary 100.00 FS *-FS 47 1 *REAR NO PLATE Not Necessary 60.00 FS *-FS				•		
40 1 *EXHAUST TIP Not Necessary 4,680.00 FS *-FS 41 1 *ACRYLIC SEALANT Necessary 180.00 FS *180.00 FS 42 1 *CAVITY WAX Necessary 140.00 FS *140.00 FS 43 1 *STONE CHIP Necessary 180.00 FS *180.00 FS 44 1 *METAL FILLER POWDER Necessary 280.00 FS *280.00 FS 45 1 *REAR WINDSCREEN SEALANT Not Necessary 200.00 FS *-FS 46 1 *1/4 GLASS SEALANT Not Necessary 100.00 FS *-FS 47 1 *REAR NO PLATE Not Necessary 60.00 FS *-FS						
41 1 *ACRYLIC SEALANT Necessary 180.00 FS *180.00 FS 42 1 *CAVITY WAX Necessary 140.00 FS *140.00 FS 43 1 *STONE CHIP Necessary 180.00 FS *180.00 FS 44 1 *METAL FILLER POWDER Necessary 280.00 FS *280.00 FS 45 1 *REAR WINDSCREEN SEALANT Not Necessary 200.00 FS *-FS 46 1 *1/4 GLASS SEALANT Not Necessary 100.00 FS *-FS 47 1 *REAR NO PLATE Not Necessary 60.00 FS *-FS					•	•
42 1 *CAVITY WAX Necessary 140.00 FS *140.00 FS 43 1 *STONE CHIP Necessary 180.00 FS *180.00 FS 44 1 *METAL FILLER POWDER Necessary 280.00 FS *280.00 FS 45 1 *REAR WINDSCREEN SEALANT Not Necessary 200.00 FS *-FS 46 1 *1/4 GLASS SEALANT Not Necessary 100.00 FS *-FS 47 1 *REAR NO PLATE Not Necessary 60.00 FS *-FS				-		
43 1 *STONE CHIP Necessary 180.00 FS *180.00 FS 44 1 *METAL FILLER POWDER Necessary 280.00 FS *280.00 FS 45 1 *REAR WINDSCREEN SEALANT Not Necessary 200.00 FS *-FS 46 1 *1/4 GLASS SEALANT Not Necessary 100.00 FS *-FS 47 1 *REAR NO PLATE Not Necessary 60.00 FS *-FS				•		
44 1 *METAL FILLER POWDER Necessary 280.00 FS *280.00 FS 45 1 *REAR WINDSCREEN SEALANT Not Necessary 200.00 FS *-FS 46 1 *1/4 GLASS SEALANT Not Necessary 100.00 FS *-FS 47 1 *REAR NO PLATE Not Necessary 60.00 FS *-FS				•		
45 1 *REAR WINDSCREEN SEALANT Not Necessary 200.00 FS *-FS 46 1 *1/4 GLASS SEALANT Not Necessary 100.00 FS *-FS 47 1 *REAR NO PLATE Not Necessary 60.00 FS *-FS				•		
46 1 *1/4 GLASS SEALANT Not Necessary 100.00 FS *-FS 47 1 *REAR NO PLATE Not Necessary 60.00 FS *-FS		-		•		
47 1 *REAR NO PLATE Not Necessary 60.00 FS *-FS	_	-		•		
,		-				
40 I JUNDALES NECESSARY 000.00 FS "94.00 FS		•		•		
F=Franchise part. S=SpcNett.		-		ivecessary	000.0073	34.00 F3

F=Franchise part. S=SpcNett.

Total Parts (S\$) 26,768.00 12,299.28

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO PUT VEHICLE ON CELLETE BENCH FOR REPAIR	New	1,800.00	1,200.00
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER	New	800.00	0.00
3	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
4	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	0.00
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	0.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
7	TO REMOVE AND REINSTALL REAR SEAT ,BACK REST ,HAT TRAY ,ABSD ,PILLAR TRIMS ,LUGGAGE COMPARTMENT TRIMS ,DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
8	TO PLACE VEHICLE ON CAR O-LINER	New	2,400.00	0.00
9	TO INSTALL REAR LID TOP SPOILER	New	480.00	480.00
10	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID .CUT OUT AND WELD RHS REAR FENDER AND REAR END PANELLING .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New R	7,700.00	3,000.00
11	TO RESPRAY REAR BUMPER, REAR LID, HINGES, RHS REAR FENDER, RHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL END PANELLING AND SPARE WHEEL HOUSING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	6,350.00	2,750.00
12	TO RE-ALIGN RHS REAR EXHAUST SILENCER TO POSITION	New	280.00	280.00
13	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labou	r Cost (S\$)	24,162.00	9,662.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >