



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

17/03/2020

TP A16

Vic

Accident date: 17/03/2020

Estimated repair cost for vehicle no: GBC6452A MITSUBISHI CANTER FB70BB1SRDEA

CHASSIS: FB70BBA20600

3.0 M '13

| S/n | Qty | Items | U/price | Amount |
|-----|-----|---|---------|------------------------------|
| 1 | 1 | Front Bumper Bent | | \$821.00 ✓ |
| 2 | 1 | Front L/H Corner Panel Repair | | \$584.00 ✗ |
| 3 | 1 | Front L/H Headlamp cut | | \$694.00 ✓ |
| 4 | 1 | Front L/H Top lamp cut | | \$227.00 ✓ |
| 5 | 1 | Front L/H Side Lamp cracked | | \$168.00 ✓ |
| 6 | 1 | Front L/H Door Dented | | \$2,038.00 ✓ |
| 7 | 2 | Front L/H Door Hinge New | | \$162.00 ✗ |
| 8 | 1 | Front L/H Door Company Sticker New | | \$30.00 ✓ |
| 9 | 1 | Front L/H Door Company Logo Sticker New | | \$180.00 80/ln |
| 10 | 1 | Front L/H Door Moulding 3 x New | | \$170.00 ✗ |
| 11 | 1 | Front L/H Door Lock Assy | | \$671.00 ✗ |
| 12 | 1 | Front L/H Door Weatherstrip New | | \$286.00 ✗ |
| 13 | 1 | Front L/H Door Inner Trim Board 3 x New | | \$617.00 ✗ |
| 14 | 1 | Front L/H Door Outer Handle New | | \$228.00 ✗ |
| 15 | 1 | Front L/H Door Lower Protector cut | | \$255.00 ✓ |
| 16 | 1 | Front L/H Door Rear Pillar Repair | | \$1,533.00 ✗ |
| 17 | 1 | Front L/H Step Panel cracked | | \$389.00 ✓ |
| 18 | 1 | Front L/H Mudguard New | | \$523.00 ✗ |
| 19 | 1 | Front L/H Refridgerator Box Pillar 3 Repair | | \$2,000.00 ✗ |
| 20 | 1 | Front L/H Refridgerator Box Panel | | \$3,000.00 ✗ |
| 21 | 1 | Front L/H Refridgerator Box Panel Sticker cut | | \$1,500.00 700/ln |

4622

ca 780

Subtotal :- \$16,076.00

3466-30

Labour charges

| | | |
|--|------|---------------------------|
| To remove & refit cushion & trim board | | \$280.00 X |
| To remove & refit front L/H door, glass, lock, trim board, weatherstrip, window motor & regulator assy | | \$280.00 80 |
| To check wiring | | \$100.00 30 |
| Towing fee | | \$150.00 X |
| Tuff kote | 1760 | \$150.00 50 |
| Panel beating | | \$1,600.00 800 |
| Spray painting | | \$2,000.00 800 |

Subtotal :- \$4,560.00

Total:- \$20,636.00

total 6006.50

4/5 4.8K

05 Days.

4.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: