

Adjuster Letter/DV not verified.
This claim is to be authorized on the insurer's behalf.
Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.
Click on 'View Letter/DV' to verify the offer.
Insurer's Mandate Remarks
COR \$5,136 LOU \$1,080 (up to 6 days x \$180) LTA fee \$7.45

You cannot authorize this offer because
Adjuster Letter/DV not verified.
File to be authorized by your superior.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20004261/ABA3Q2
Date: 22/07/2020

REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 1800019999 |
| Claimant Vehicle No : | GBC6452A | Insured Vehicle No : | SLW8422A |
| Date of Loss: | 17/03/2020 | Nature of Claim: | TP |
| | | Claim No: | 3972620586SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---|-------------|--------------|
| Reg No: | GBC6452A | Engine No: | 4M42A91800 |
| Make & Model: | MITSUBISHI CANTER FB70BB1SRDEA, 3.0 D (M) | Chassis No: | FB70BBA20600 |
| Reg. Date: | 24/06/2013 (Man. Year: 2013) | Odometer: | 246443 km |
| Colour: | White | | |
| Engine Capacity: | 2977 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|---------------|
| Front Tyre Size: | 195 R15C | Rear Tyre Size: | 195 R15C |
| Front Left Side: | Dunlop 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|------------------|--------------|
| Parts | 16,076.00 | 4,246.50 | 11,829.50 | 73.58 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,560.00 | 1,760.00 | 2,800.00 | 61.40 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 20,636.00 | 6,006.50 | 14,629.50 | 70.89 |
| Approved Total (Overridden) (S\$) | | 4,800.00 | | |
| (S\$) | 20,636.00 | 4,800.00 | 15,836.00 | 76.74 |
| + GST 7.00/7.00% (S\$) | 1,444.52 | 336.00 | 1,108.52 | 76.74 |
| Nett Amount (S\$) | 22,080.52 | 5,136.00 | 16,944.52 | 76.74 |
| + Loss of Use (6.0 x S\$180.00/day) (S\$) | | 1,080.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 6,218.00 | | |
| Global Sum Settlement (S\$) | | 6,200.00 | | |

INSPECTION

| | | | |
|---------------------|------------|---------------|---|
| Date of Assignment: | 18/03/2020 | Inspected At: | New Hock Teck Motor Pte Ltd (HQ) |
| Date Inspected: | 18/03/2020 | | 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit |

7/22/2020

Merimen e-Claims

Estimated Period of Repair: 5.0 days

Singapore 417883

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Bent | 821.00 F | *821.00 FL |
| 2 | 1 | | *FRONT L/H CORNER PANEL | Repair | 584.00 F | *- FL |
| 3 | 1 | | *FRONT L/H HEADLAMP | Cut | 694.00 F | *694.00 FL |
| 4 | 1 | | *FRONT L/H TOP LAMP | Cut | 227.00 F | *227.00 FL |
| 5 | 1 | | *FRONT L/H SIDE LAMP | Cracked | 168.00 F | *168.00 FL |
| 6 | 1 | | *FRONT L/H DOOR | Dented | 2,038.00 F | *2,038.00 FL |
| 7 | 1 | | *FRONT L/H DOOR HINGE | Not Necessary | 162.00 F | *- FL |
| 8 | 1 | | *FRONT L/H DOOR COMPANY STICKER | Necessary | 30.00 F | *30.00 FL |
| 9 | 1 | | *FRONT L/H DOOR COMPANY LOGO STICKER | Necessary | 180.00 FS | *80.00 FS |
| 10 | 1 | | *FRONT L/H DOOR MOULDING | Not Necessary | 170.00 F | *- FL |
| 11 | 1 | | *FRONT L/H DOOR LOCK ASSY | Not Necessary | 671.00 F | *- FL |
| 12 | 1 | | *FRONT L/H DOOR WEATHERSTRIP | Not Necessary | 286.00 F | *- FL |
| 13 | 1 | | *FRONT L/H DOOR INNER TRIM BOARD | Not Necessary | 617.00 F | *- FL |
| 14 | 1 | | *FRONT L/H DOOR OUTER HANDLE | Not Necessary | 228.00 F | *- FL |
| 15 | 1 | | *FRONT L/H DOOR LOWER PROTECTOR | Crumpled | 255.00 F | *255.00 FL |
| 16 | 1 | | *FRONT L/H DOOR REAR PILLAR | Repair | 1,533.00 F | *- FL |
| 17 | 1 | | *FRONT L/H STEP PANEL | Cracked | 389.00 F | *389.00 FL |
| 18 | 1 | | *FRONT L/H MUDGUARD | Not Necessary | 523.00 F | *- FL |
| 19 | 1 | | *FRONT L/H REFRIDGERATOR BOX PILLAR | Repair | 2,000.00 F | *- FL |
| 20 | 1 | | *FRONT L/H REFRIDGERATOR BOX PANEL | Repair | 3,000.00 F | *- FL |
| 21 | 1 | | *FRONT L/H REFRIDGERATOR BOX PANEL STICKER | Cut | 1,500.00 FS | *700.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (S\$) | 16,076.00 | 5,402.00 |
| - List Item Discount on L Items 0.00/25.00% (S\$) | 0.00 | 1,155.50 |
| Total Parts (S\$) | 16,076.00 | 4,246.50 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items**There are no new miscellaneous items selected.****Recommended Labour**

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|--------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE & REFIT CUSHION & TRIM BOARD | New | 280.00 | 0.00 |
| 2 | TO REMOVE & REFIT FRONT L/H DOOR ,GLASS ,LOCK ,TRIM BOARD ,WEATHERSTRIP ,WINDOW MOTOR & REGULATOR ASSY | New | 280.00 | 80.00 |
| 3 | TO CHECK WIRING | New | 100.00 | 30.00 |
| 4 | TOWING FEE | New | 150.00 | 0.00 |
| 5 | TUFF KOTE | New | 150.00 | 50.00 |
| 6 | PANEL BEATING | New | 1,600.00 | 800.00 |
| 7 | SPRAY PAINTING | New | 2,000.00 | 800.00 |
| | | | Gross Labour Cost (S\$) | 4,560.00 |
| | | | | 1,760.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >