

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20004261/ABA3Q2**Date:** 16/07/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800019999
Claimant
Vehicle No : GBC6452A **Insured Vehicle No :** SLW8422A
Date of Loss: 17/03/2020 Nature of Claim: TP Claim No: 3972620586SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC6452A**
Make & Model: MITSUBISHI CANTER FB70BB1SRDEA, 3.0 D (M) Engine No: 4M42A91800
Reg. Date: 24/06/2013 (Man. Year: 2013) Chassis No: FB70BBA20600
Colour: White Odometer: 246443 km
Engine Capacity: 2977 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: Dunlop 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,076.00	4,246.50	11,829.50	73.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,560.00	1,760.00	2,800.00	61.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,636.00	6,006.50	14,629.50	70.89
Approved Total (Overridden) (S\$)		4,800.00		
(S\$)	20,636.00	4,800.00	15,836.00	76.74
+ GST 7.00/7.00% (S\$)	1,444.52	336.00	1,108.52	76.74
Nett Amount (S\$)	22,080.52	5,136.00	16,944.52	76.74
+ Loss of Use (6.0 x S\$180.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,223.45		
Global Sum Settlement (S\$)		6,200.00		

INSPECTION

Date of Assignment: 18/03/2020
Date Inspected: 18/03/2020 Inspected At: New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	821.00 F	*821.00 FL
2	1		*FRONT L/H CORNER PANEL	Repair	584.00 F	*- FL
3	1		*FRONT L/H HEADLAMP	Cut	694.00 F	*694.00 FL
4	1		*FRONT L/H TOP LAMP	Cut	227.00 F	*227.00 FL
5	1		*FRONT L/H SIDE LAMP	Cracked	168.00 F	*168.00 FL
6	1		*FRONT L/H DOOR	Dented	2,038.00 F	*2,038.00 FL
7	1		*FRONT L/H DOOR HINGE	Not Necessary	162.00 F	*- FL
8	1		*FRONT L/H DOOR COMPANY STICKER	Necessary	30.00 F	*30.00 FL
9	1		*FRONT L/H DOOR COMPANY LOGO STICKER	Necessary	180.00 FS	*80.00 FS
10	1		*FRONT L/H DOOR MOULDING	Not Necessary	170.00 F	*- FL
11	1		*FRONT L/H DOOR LOCK ASSY	Not Necessary	671.00 F	*- FL
12	1		*FRONT L/H DOOR WEATHERSTRIP	Not Necessary	286.00 F	*- FL
13	1		*FRONT L/H DOOR INNER TRIM BOARD	Not Necessary	617.00 F	*- FL
14	1		*FRONT L/H DOOR OUTER HANDLE	Not Necessary	228.00 F	*- FL
15	1		*FRONT L/H DOOR LOWER PROTECTOR	Crumpled	255.00 F	*255.00 FL
16	1		*FRONT L/H DOOR REAR PILLAR	Repair	1,533.00 F	*- FL
17	1		*FRONT L/H STEP PANEL	Cracked	389.00 F	*389.00 FL
18	1		*FRONT L/H MUDGUARD	Not Necessary	523.00 F	*- FL
19	1		*FRONT L/H REFRIDGERATOR BOX PILLAR	Repair	2,000.00 F	*- FL
20	1		*FRONT L/H REFRIDGERATOR BOX PANEL	Repair	3,000.00 F	*- FL
21	1		*FRONT L/H REFRIDGERATOR BOX PANEL STICKER	Cut	1,500.00 FS	*700.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,076.00	5,402.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,155.50
Total Parts (\$\$)	16,076.00	4,246.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	0.00
2	TO REMOVE & REFIT FRONT L/H DOOR ,GLASS ,LOCK ,TRIM BOARD ,WEATHERSTRIP ,WINDOW MOTOR & REGULATOR ASSY	New	280.00	80.00
3	TO CHECK WIRING	New	100.00	30.00
4	TOWING FEE	New	150.00	0.00
5	TUFF KOTE	New	150.00	50.00
6	PANEL BEATING	New	1,600.00	800.00
7	SPRAY PAINTING	New	2,000.00	800.00
Gross Labour Cost (\$\$)			4,560.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >