

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20004273/EKA3Q2

Date: 17/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0100569962-14

Claimant
Vehicle No : SMS4285P **Insured Vehicle No :** SDQ3118M

Date of Loss: 18/03/2020 Nature of Claim: TP Claim No: 2951687291SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS4285P	Engine No:	CVK087930
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Chassis No:	WAUZZZF4XKA116523
Reg. Date:	26/02/2020 (Man. Year: 2019)	Odometer:	844 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,154.00	0.00	11,154.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	2,272.00	2,850.00	55.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,276.00	2,272.00	14,004.00	86.04
+ GST 7.00/7.00% (S\$)	1,139.32	159.04	980.28	86.04
Nett Amount (S\$)	17,415.32	2,431.04	14,984.28	86.04
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,833.04		

INSPECTION

Date of Assignment: 25/03/2020

Date Inspected: 25/03/2020 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,068.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	553.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE -LH	Not Necessary	59.00 FS	*- FS
4	2		*FRONT BUMPER SECURING STRIP	Not Necessary	67.00 FS	*- FS
5	1		*FRONT FENDER- LH	Repair	722.00 FS	*- FS
6	1		*FRONT FENDER CLOSING ELEMENT -LH	Not Necessary	47.00 FS	*- FS
7	1		*FRONT FENDER BRACKET -LH	Not Necessary	33.00 FS	*- FS
8	1		*FENDER LEGE COVER -LH OUTER	Not Necessary	29.00 FS	*- FS
9	1		*FENDER LEDGE COVER	Not Necessary	21.00 FS	*- FS
10	1		*LED HEADLIGHT -LH	Not Necessary	7,321.00 FS	*- FS
11	2		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	34.00 FS	*- FS
12	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **11,154.00** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND LHS HEADLIGHT .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,450.00	500.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,122.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >