

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Jul 2016		13 Jul 2016 16:23 Edit Adj Rpt	S\$7,500.00 Edit Estimates	S\$7,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: YEE CHUN WEE , ID: S7976409D, Tel: +6593826915, Email: CHUN_WEE@YAHOO.COM									
Main Claimant: LIM HOCK POH , Co. Reg. No.: S1299355B									
Vehicle Reg. No.: SGE6916J		Date of Loss: 12/07/2016 14:00 - :59 [123 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / C0391810		Policy/Cover Note No.: GA086674 (Comprehensive)							
Vehicle Reg. No. (Insured): SKX4965H		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Lee Hong & Co Motor Service (HQ) BLK 9, SIN MING ROAD, #01-36, 575644 Sin Ming - Tel:									
Handling Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 ... [Handled by Yvonne Ang Ching Ching - 6880 4461]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/03/2020]									
Driver/Custodian (Insured): YEE CHUN WEE (36 / Male) , NRIC: S7976409D, Tel: +6593826915 Email: CHUN_WEE@YAHOO.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AXA_SG (15/04/2020): Alert - Adj Mandate Approved (S\$9070.00) - SGE6916J - Claim Handler: Yvonne Ang ... - AXA_SG (13/07/2016): New TP Assignment - C0391810/GA086674									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGE6916J (C0391810)**
[SKX4965H]
TP
LIM HOCK POH
Jul 12 2016 2:00PM
[YEE CHUN WEE]
Lee Hong & Co Motor Service

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼		
Assessment Reports 1 per page ▼ ☒					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/07/16 14:29	Adjuster Immediate Advice		Load HTM	
Photos/Images 3 per page ▼ ☒					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/07/16 12:46	General View		Load JPG	☒
2	18/07/16 12:46	General View		Load JPG	☒
3	18/07/16 12:46	General View		Load JPG	☒
4	18/07/16 12:46	General View		Load JPG	☒
5	18/07/16 12:46	General View		Load JPG	☒
6	18/07/16 12:46	General View		Load JPG	☒
7	18/07/16 12:46	General View		Load JPG	☒
8	18/07/16 12:46	General View		Load JPG	☒
9	18/07/16 12:46	General View		Load JPG	☒
10	18/07/16 12:46	General View		Load JPG	☒
11	18/07/16 12:46	General View		Load JPG	☒
12	18/07/16 12:46	General View		Load JPG	☒
13	18/07/16 12:46	General View		Load JPG	☒
14	18/07/16 12:46	General View		Load JPG	☒
15	18/07/16 12:46	General View		Load JPG	☒
16	18/07/16 12:46	General View		Load JPG	☒
17	18/07/16 12:46	General View		Load JPG	☒
18	18/07/16 12:46	General View		Load JPG	☒
19	18/07/16 12:46	General View		Load JPG	☒
20	18/07/16 12:46	General View		Load JPG	☒
21	18/07/16 12:46	General View		Load JPG	☒
22	18/07/16 12:46	General View		Load JPG	☒
23	18/07/16 12:46	General View		Load JPG	☒
24	18/07/16 12:46	General View		Load JPG	☒
25	18/07/16 12:46	General View		Load JPG	☒
26	18/07/16 12:46	General View		Load JPG	☒
27	18/07/16 12:46	General View		Load JPG	☒
28	18/07/16 12:46	General View		Load JPG	☒
29	18/07/16 12:46	General View		Load JPG	☒
30	18/07/16 12:46	General View		Load JPG	☒
31	18/07/16 12:46	General View		Load JPG	☒
32	18/07/16 12:46	General View		Load JPG	☒
33	18/07/16 12:46	General View		Load JPG	☒
34	18/07/16 12:46	General View		Load JPG	☒
35	27/06/17 12:30	LKK Survey Photo		Load PDF	
36	20/03/20 09:16	AFTER REPAIR		Load PDF	

Assessment Reports			1 per page ▼	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page ▼	
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	13/07/16 16:11	Email_ABS	Load PDF	
2	13/07/16 16:11	Co claimant_ABS	Load PDF	
3	13/07/16 16:11	SKX4965H INSD GIA Report_ABS	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/07/16 14:30	TP ESTIMATE - MARKED	Load PDF	
2	19/07/16 14:30	TP GIA REPORT & POLICE REPORT	Load PDF	
3	25/07/16 09:59	LETTER TO OI	Load PDF	
4	05/05/20 15:07	Authorisation to Act	Load PDF	
5	05/05/20 15:07	PAYMENT BREAKDOWN – EXPRESS SETTLEMENT FORM	Load PDF	
6	05/05/20 15:07	RENTAL RECEIPT	Load PDF	
7	05/05/20 15:21	INVOICE NO DATED 05.07.2017	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16013048/GPA3S2-1
Date: 05/05/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: GA086674
Claimant Vehicle No : SGE6916J **Insured Vehicle No :** SKX4965H
 Date of Loss: 12/07/2016 Nature of Claim: TP Claim No: C0391810

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGE6916J**
 Make & Model: MITSUBISHI LANCER, 1.6 (A) Engine No: 4G18HB7742
 Reg. Date: 23/03/2006 (Man. Year: 2006) Chassis No: JMYSTCS3A6U006984
 Colour: Red Odometer: 332780 km
 Engine Capacity: 1584 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16
 Front Left Side: Kumho 8 mm Rear Left Side: Kumho 8 mm
 Front Right Side: Kumho 8 mm Rear Right Side: Kumho 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,773.83	7,152.53	4,621.30	39.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	2,810.00	1,380.00	32.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,963.83	9,962.53	6,001.30	37.59
Approved Total (Overridden) (S\$)		7,500.00		
Nett Amount (S\$)	15,963.83	7,500.00	8,463.83	53.02
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
Nett Liability (S\$)		8,500.00		
Global Sum Settlement (S\$)		8,500.00		

INSPECTION

Date of Assignment: 13/07/2016
 Date Inspected: 15/07/2016 Inspected At: LEE HONG & COMPANY MOTOR SERVICE (HQ)
 9 Sin Ming Industrial Sector C, #01-36
 Singapore 575644
 Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2020)
Parts:	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGE6916J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER (CONSISTENT)	Deformed	731.00 FN	*731.00 FN
2	1	*REAR BUMPER REINFORCEMENT (CONSISTENT)	Bent	268.00 FN	*268.00 FN
3	2	*REAR BUMPER SIDE RETAINERS (CONSISTENT)	Distorted	78.00 FN	*78.00 FN
4	1	*REAR BUMPER SPOILER (CONSISTENT)	Distorted	653.00 FN	*653.00 FN
5	2	*REAR LAMPS (CONSISTENT)	Cracked	796.00 FN	*796.00 FN
6	1	*BOOT LID (CONSISTENT)	Bent	582.00 FN	*582.00 FN
7	2	*BOOT LID HINGES (CONSISTENT)	Repair	176.00 FN	*- FN
8	1	*BOOT LID TOP LOCK (CONSISTENT)	Bent	58.00 FN	*58.00 FN
9	1	*BOOT LID BOTTOM LOCK (CONSISTENT)	Bent	18.00 FN	*18.00 FN
10	1	*BOOT LID RUBBER (CONSISTENT)	Distorted	139.00 FN	*139.00 FN
11	1	*BOOT LID LANCER NAME PLATE (CONSISTENT)	Necessary	25.20 FN	*25.20 FN
12	1	*BOOT LID BADGE (CONSISTENT)	Necessary	38.00 FN	*38.00 FN
13	1	*BOOT LID GLX EMBLEM (CONSISTENT)	Necessary	25.00 FN	*25.00 FN
14	1	*BOOT LID RALLI-ART NAME PLATE (CONSISTENT)	Necessary	73.40 FN	*73.40 FN
15	1	*BOOT LID LICENCE PLATE GARNISH (CONSISTENT)	Distorted	100.00 FN	*100.00 FN
16	2	*LICENCE PLATE LAMPS (CONSISTENT)	Serviceable	96.00 FN	*- FN
17	1	*REAR PANEL (CONSISTENT)	Bent	398.00 FN	*398.00 FN
18	2	*REAR LAMP PANELS (CONSISTENT)	Bent	134.00 FN	*134.00 FN
19	1	*REAR PANEL TOP GARNISH (CONSISTENT)	Distorted	140.00 FN	*140.00 FN
20	1	*REAR PANEL INNER TRIM COVER (CONSISTENT)	Serviceable	141.00 FN	*- FN
21	2	*REAR FENDERS (CONSISTENT)	Distorted	1,242.00 FN	*1,242.00 FN
22	2	*REAR FENDER REINFORCEMENT PLATES (CONSISTENT)	Repair	282.00 FN	*- FN
23	2	*REAR FENDER INNER TRIM COVERS (CONSISTENT)	Serviceable	424.00 FN	*- FN
24	1	*BOOT FLOOR PANEL (CONSISTENT)	Repair	659.00 FN	*- FN
25	1	*SPARE TYRE HARDBOARD (CONSISTENT)	Torn	141.00 FN	*141.00 FN
26	1	*REAR EXHAUST PIPE (CONSISTENT)	Not Necessary	459.00 FN	*- FN
27	1	*REAR EXHAUST CENTRE PIPE (CONSISTENT)	Serviceable	491.00 FN	*- FN
28	2	*REAR EXHAUST PIPE MOUNTINGS (CONSISTENT)	Necessary	56.00 FN	*56.00 FN
29	1	*REAR WINDSCREEN MOULDING (CONSISTENT)	Necessary	28.00 FN	*28.00 FN
30	1	*REAR WINDSCREEN INNER RUBBER BEADING (CONSISTENT)	Necessary	38.10 FN	*38.10 FN
31	2	*FRONT SEAT SLIDING RAIL (CONSISTENT)	Bent	1,278.00 FS	*500.00 FS
32	2	*FRONT SEAT RECLINING GEAR (CONSISTENT)	Bent	1,530.00 FS	*500.00 FS
33	1	*BOOT LID SPOILER (CONSISTENT)	Necessary	850.00 FS	*600.00 FS
34	1	*REAR EXHAUST CHROME PIPE (CONSISTENT)	Bent	67.00 FS	*67.00 FS
35	1	*REAR NUMBER PLATES (CONSISTENT)	Bent	50.00 FS	*40.00 FS
36	1	*SET REVERSE SENSORS (CONSISTENT)	Necessary	240.00 FS	*220.00 FS
37	1	*REAR WINDSCREEN SEALANT (CONSISTENT)	Necessary	80.00 FS	*40.00 FS
38	1	*REAR WINDSCREEN INNER RUBBER BEADING (CONSISTENT)	Not Necessary	38.10 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	12,622.80	7,728.70
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	848.97	576.17
Total Parts (\$\$)	11,773.83	7,152.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	80.00	60.00
2	TO REMOVE DAMAGED LAMPS AND NECESSARY WIRINGS TO ENABLE NECESSARY REPAIRS ,CHECK,REPLACE DAMAGED LAMPS AND REFIT	New	50.00	30.00
3	TO REMOVE BOTH FRONT SEATS ,REPAIR SEAT FRAME,CHECK,REPLACE SLIDING RAIL AND RECLINING GEAR ASSY .REFIT SAME	New	240.00	0.00
4	TO REMOVE REAR SEATS AND BACKREST ,REAR PARCAL TRAY ,GARNISHES AND NECESSARY INTERIOR UPHOLSTERY TO ENABLE REPAIR AND REPLACE OF PARTS ,REFIT SAME ,INCLUDING CLEANING AND VACUUM UP INTERIOR COMPARTMENT	New	220.00	120.00
5	TO REMOVE REAR WINDSCREEN GLASS ASSY ,TO ENABLE NECESSARY REPAIRS ,CHECK ,REFIT GLASS ASSY (BONDED TYPE WINDSCREEN GLASS)	New	150.00	120.00
6	TO CHECK WHEEL ALIGNMENT -COMPUTERIZE	New	80.00	0.00
7	TO CHECK AND RE-ALIGN BODY STRUCTURE ON CHASSIS ALIGNMENT SYSYEMS	New	350.00	0.00
8	TO REMOVE REAR EXHAUST PIPE AND SILENCER ASSY ,CHECK,REPLACE SAME WITH MOUNTING AND REFIT	New	180.00	80.00
9	TO REMOVE DAMAGED PARTS ,JACK AND CUT OUT DAMAGED BODY PANELS ,JACK OUT,STRAIGHTEN UP DAMAGED BODY PANELS AND REPAIR BODY PARTS AND FITTINGS ,WHICHEVER POSSIBLE AND NECESSARY ,REPLACE AND WELD NECESSARY DAMAGED PARTS ,REFIT AND REALIGN WHICHEVER PARTS NECESSARY	New	1,200.00	1,100.00
10	TO SPRAY PAINTING REPLACEMENT PARTS AND REPAINT DAMAGED SECTIONS WITH WELDED PORTIONS IN AND OUTSIDE ,INCLUDING PUTTY	New	1,400.00	1,200.00
11	TO PERFORM A COMPUTERISE SYSTEMS CHECKING AFTER REMOVING OF NECESSARY WIRINGS AND ELECTRICAL FITTINGS TO ENABLE NECESSARY DIAGNOSTING AND RE-SETTING TO SPECIFICATIONS	New	120.00	0.00
12	TO RUST PROOFING DAMAGED PORTIONS AND REPLACEMENT PARTS	New	120.00	100.00
Gross Labour Cost (\$\$)			4,190.00	2,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >