

WORKSHOP 99 AUTO SERVICES

Blk 9 Sin Ming Road
#01-34 Sin Ming Industrial Estate
Singapore 575644.

T. (65) 6458 8460
F. (65) 6455 5379
E. workshop99@rocketmail.com

Date	24-Feb-2015	Ref.:	TP Claim
Owner Particulars			
Name	Fun Fook Wai		
# Nos	S1309210/I	Mobile	9666-7283
Address	Blk 35 Toa Payoh Lor 5 #16-333 Singapore 310035		
Vehicle Particulars			
Number	SJJ 7443M		
Model	TOYOTA WISH 1.8 AUTO		
Engine	1ZZ3139505		
Chassis	JTDER12W703000773		
Year	24-Sep-08		
Accident Details			
Date	Monday, 23 February, 2015		
Time	18.20 Hrs		
Place	Toa Payoh Lor 2 Towards PIE and Lor 1		
Insured With			
Insurance	AIG Asia Pacific Insurance Pte. Ltd.		
Policy No.	2100097244		
Expiry			
Driver Particulars			
Name	As Above		
Nric Nos.		Mobile No.	
Address			
Parts & Labour			
List Price			\$ 10,883.00
Less	25%		\$ 2,720.75
			\$ 8,162.25
Special Nett			\$ 320.00
Labour Charges			\$ 2,060.00
Total			\$ 10,542.25



AXA.

Estimate Cost Of Repairs		Vehicle #	SJJ 7443M
QTY	DESCRIPTIONS	UNITS	AMOUNTS
1 pce	Rear bumper fascia ✓		\$ 880.40
2 pcs.	Rear bumper brackets ?	\$ 55.60	\$ 111.20
2 pcs.	Rear bumper side retainers ✓	\$ 48.60	\$ 97.20
1 pce	Rear bumper beam ?		\$ 201.00
1 pce	Rear bumper o/s reflector ?		\$ 76.00
1 pce	Tailgate X Repair		\$ 1,209.00
1 pce	Tailgate emblem ✓		\$ 107.00
1 pce	Tailgate "Aero Tourer" name plate ✓		\$ 96.00
1 pce	Tailgate chrome handle X		\$ 209.00
1 pce	Tailgate inner lock top ?		\$ 443.50
1 pce	Tailgate inner trim cover ✓ (photo)		\$ 391.50
1 pce	Tailgate rubber ✓		\$ 329.10
2 pcs.	Rear lamps assy ✓	\$ 408.00	\$ 916.00
1 pce	Rear end panel ?		\$ 440.00
1 pce	Rear end panel inner garnish ?		\$ 395.00
1 pce	Boot compartment tool box ?		\$ 806.00
1 pce	Rear o/s body panel X Repair		\$ 781.90
1 pce	Rear o/s body panel inner shield ?		\$ 143.20
1 pce	Rear o/s body panel inner side trim ?		\$ 886.00
1 pce	Rear exhaust pipe assy ?		\$ 971.00
1 pce	Center exhaust pipe assy X ?		\$ 1,303.00
2 pcs.	Rear exhaust mountings ?	\$ 45.00	\$ 90.00
			\$ 10,883.00
		Less 25%	\$ 2,720.75
			\$ 8,162.25
	S/Nett		
1 set	Reverse sensors ✓		\$ 230.00
1 pce	Rear o/s body glass sealant X		\$ 40.00
1 pce	Number plate X		\$ 50.00
	Labour		
	To remove damaged lamps and necessary Wirings to enable necessary repairs.		\$ 30.00 ✓
	To remove rear o/s body panel glass assy., Check, replace damaged parts and fittings, (Bonded type glass assy.)		\$ 80.00 X
	To remove centre exhaust pipe, rear exhaust pipe and silencer assy., check, replace same with mounting and refit.		\$ 180.00 60
	To remove damaged parts, jack and cut out Damaged body panels, jack out, straighten up Damaged body panels and repair body parts and fittings, whichever possible and necessary, replace and weld necessary damaged parts, refit and realign whichever parts necessary. [Incl. alignments of body members.]		\$ 850.00 600
	Paint replacement parts and repaint damaged Sections with welded portions in and outside. [2K Chemical Paint]		\$ 800.00 700
	To rust proofing damaged portions and replacement parts		\$ 120.00 60
	5-6 Days.		\$ 10,542.25

Lump Sum Repair.

Guo Qiang 82880282.
Guo Qiang @ IKK auto. com

27/2/15.

