Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

Our File No: CS/CTI20004276/EVF3E2

3 Anson Road, #16-00 Springleaf Tower Singapore 079909

Date: 14/04/2020

REFERENCE

Insured/Claimant: HUANG HONGLIANG Policy No: DMPCSN30326419000

Date of Loss: 17/03/2020 Nature of Claim: OD Claim No: SNM20D201361C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJQ9878S

 Make & Model:
 BMW 216D, 1.5 D Active Tourer (F45) (A)
 Engine No:
 32055263B37C15A

 Reg. Date:
 14/05/2018 (Man. Year: 2018)
 Chassis No:
 WBA2B32060V926372

Colour: Silver Odometer: 39233 km

Engine Capacity: 1496 cc Market Value/New Car Price: \$\$105,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm
Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------|------------|------------|------------|--------|
| Parts | 3,853.15 | 2,706.75 | 1,146.40 | 29.75 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 7,248.00 | 5,533.00 | 1,715.00 | 23.66 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 11,101.15 | 8,239.75 | 2,861.40 | 25.78 |
| - Excess (S\$) | 500.00 | 500.00 | 0.00 | 0.00 |
| (S\$) | 10,601.15 | 7,739.75 | 2,861.40 | 26.99 |
| + GST 7.00/7.00% (S\$) | 742.08 | 541.78 | 200.30 | 26.99 |
| Nett Amount (S\$) | 11,343.23 | 8,281.53 | 3,061.70 | 26.99 |

INSPECTION

Date of Assignment: 20/03/2020

Date Inspected: 20/03/2020 Inspected At: Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair: 5.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen ... 14/4/2020

Adjuster Report Page 2 of 4

Adjuster: CHEN TSUE YEE Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

| Reference | | | | |
|--|--|--|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 14 Apr 2020) | | |
| Parts: | M1-MPV | BMW 216D 1.5 D Active Tourer (F45) (A) (Catalogue:Merimen Singapore 1.0) | | |
| Labour: | Repairer's | (Price-denominated Standard List) | | |
| Print Code: | ode: (Unsubmitted, no print-code for SJQ9878S) | | | |
| Validity: | ty: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | | | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | | | | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|--------------|---------------------------------|-------------------|-------------|--------------|
| 1 | 1 | | *SUNDRIES | Necessary | 150.00 FS | *80.00 FS |
| 2 | 1 | | *ALLOY RIM 7JX16 DOUBLE SPK 473 | Cut | 757.00 FS | *757.00 FS |
| 3 | 1 | | *HUB CAP WITH CHROME EDGE | Not Necessary | 29.40 FS | *-FS |
| 4 | 1 | | *# FRT RH FENDER | Dented | 627.15 FS | *627.15 FS |
| 5 | 1 | | *FRT RH DOOR | Dented | 1,136.90 FS | *1,136.90 FS |
| 6 | 1 | | *# FRT BUMPER PANEL PRIMED (PMA | Repair | 897.25 FS | *-FS |
| 7 | 2 | | *GROMMET | Not Necessary | 1.60 FS | *-FS |
| 8 | 1 | | *# FRT RH DOOR EXTERIOR CHANNEL | Not Necessary | 99.80 FS | *-FS |
| 9 | 1 | | *# RH SEAL A PILLAR | Not Necessary | 48.35 FS | *-FS |
| 10 | 1 | | *PLAQUE 82MM | Necessary | 71.60 FS | *71.60 FS |
| 11 | 1 | | *FRT DOOR JOINT SEAL | Necessary | 32.10 FS | *32.10 FS |
| 12 | 4 | | *RIVET | Necessary | 2.00 FS | *2.00 FS |
| F=Fra | anchise | part. S=SpcN | lett. | _ | | |
| | | | | Total Parts (S\$) | 3,853.15 | 2,706.75 |
| | | | | - | | |

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|---|-----------------|------------|----------|
| Lab | our Items | | | |
| 1 | TO REPLACE FRONT BUMPER, FRONT RIGHT FENDER AND FRONT RIGHT DOOR | New | 3,400.00 | 2,125.00 |
| 2 | TO RESPRAY FRONT BUMPER, FRONT RIGHT FENDER AND FRONT RIGHT DOOR | New | 2,808.00 | 2,527.00 |
| 3 | TO CARRY OUT BODY CAVITY PRESERVATION (2X) | New | 238.00 | 200.00 |
| 4 | TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (1X) | New | 531.00 | 451.00 |
| 5 | TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X) | New | 94.00 | 80.00 |
| 6 | TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS | New | 177.00 | 150.00 |
| | Gross Labour Cost (S\$) | | 7,248.00 | 5,533.00 |
| | Report was unsubmitted during | this print-out. | | |

< END OF ESTIMATES >