

22/03/2002

ASS. REC. BY:

REF: CS/FWD 20064286/Gvf3

Special Instruction: ☒

done

Surveyor: GQ ASSIGNMENT (Office)From (Person): Vinessa Chan of FWD Date/Time: 20.3.2020

Estimated Cost: _____ Bill to: _____

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLA 40399 Insured: SLB 1822Kat Workshop m/s Revol Cars Tel: 97406856of 10 Ann Industrial Park 2A #02-18Policy No: PNPV2019 00003982 Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19.3.2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 20.3.20 1.21 p.m. Person Contacted: Gavin H.O.D. Endorsement: _____
Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>985 / 1447</u>
<u>25/3/20</u>	<u>Send preti revised via merimen</u> <u>Randy</u>
<u>30/3/20</u>	<u>@ 12pm final fig \$3785.53 Confirmed with Gavin</u> <u>(Ref 1533.68, 6690) CHO LS)</u>

ASS. REC. BY: ELREF: FWD**ASSIGNMENT**

From: _____ Date: 24.3.2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 4039 G

at Workshop m/s Revo 1

of NO 10 AMK Industri (PARK 2A) #02-18

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Acer 2pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$43K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 4 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS np

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLQ4039 G Yr Regn: 26 May 2015

Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 2 C.C. 1496

Colour: red A/C: Insured / Std / NI / NA

Sp. Reading: 72561 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6DJ2HAA01100232

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55 R16
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19-03-20 D.O.I. 24-03-20

Survey held at w/s 3pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

cek: 38154

RECEIVED 31 MAR 2020

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2) 30/3 - typistReport Format: MerimenLump Sum / LBI: (\$) 3785.52Days Of Repair: 4Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

2503 trips15011411

Revol Carz Garage Pte Ltd

Blk 10 Ang Mo Kio Industrial Park 2a, Ang Mo Kio Autopoint #02-18
Singapore 568047
Tel: 65551171 Fax: 62679317

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimated repair of SLQ 4039 G

Name : Revol Carz Garage Pte Ltd
Address : c/o 10 Ang Mo Kio Industrial Park 2A
#02-18, Ang Mo Kio AutoPoint Singapore 568047

Date :

25-Mar-20

Model : MAZDA 2

QTY	ITEM	AMT (\$)
-----	------	----------

<u>List Items</u>		
1 pc	Car boot	956.7
1 pc	Boot lock	\$ 212.30
1 pc	Boot logo	\$ 61.20
1 pc	Mazda 2 wording	\$ 58.30
2 pc	Boot lamp	\$ 233.00
1 pc	Boot switch	\$ 85.10
1 pc	Rear wiper motor	\$ 333.00
1 pc	Skyactiv emblem	\$ 68.00
1 pc	Rear bumper	\$ 892.80
2 pc	Rear bumper retainer	\$ 27.20
2 pc	Car plate light module	\$ 55.80
1 pc	Reverse camera	\$ 846.00
1 pc	Boot inner garnish	\$ 93.50
1 pc	Rear end panel	\$ 399.30
1 pc	Rear end panel top garnish	\$ 77.00
1 pc	Carplate with cover	\$ 80.00
1 pc	Reverse sensor 1 set	\$ 280.00
		\$ 4,759.20

<u>Special Nett Items</u>		
1 pc	Rear bumper clip (1 set)	\$ 50.00
		\$ 50.00

<u>S/N</u>	<u>Labour Charge</u>	
1	To remove and refit front electrical wiring, replaced damaged lamps and test for proper functioning	\$ 40.00
2	To remove and refit rear bumper sensor	\$ 80.00
3	To remove and refit inner trims, inner garnishes, to facilitate the repairs	\$ 80.00
4	To remove and refit rear undercarriage	\$ 500.00
5	To remove and replace the above damaged parts, repair exhaust, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 2,800.00
6	To spray paint on the replaced and repaired parts prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available	\$ 2,500.00
7	To apply undercoating on the repaired and replaced panels for rust protection	\$ 60.00
8	To reset computerize fault code	\$ 250.00
9	To remove and refit rear windscreen glass.	\$ 200.00
		\$ 6,510.00

Total : \$ 11,319.20

Dollars : Eleven Thousand Three Hundred Nineteen And Cents Twenty Only

Guo Qiang - 8288 0282

24/3/2020

3785.52

20% 3000

2494.4

1995.52

24/3/2020

40 days

unpsm repair

After repair photos