

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20004288/DYD3E2

Date: 22/04/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001222491

Claimant Vehicle No : SJW4477S

Insured Vehicle No : SJU6203M

Date of Loss: 18/03/2020

Nature of Claim: TP

Claim No: 240931

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW4477S**

Make & Model: KIA CERATO K3, 1.6 (A)

Engine No: G4FGGH641704

Reg. Date: 02/05/2017 (Man. Year: 2017)

Chassis No: KNAFX411MH5720676

Colour: Grey

Odometer: 151775 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Pirelli 5 mm

Rear Left Side:

Pirelli 5 mm

Front Right Side: Pirelli 5 mm

Rear Right Side:

Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,306.40	19,884.79	6,421.61	24.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,040.00	4,060.00	2,980.00	42.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,346.40	23,944.79	9,401.61	28.19
Approved Total (Overridden) (S\$)		19,200.00		
Nett Amount (S\$)	33,346.40	19,200.00	14,146.40	42.42

INSPECTION

Date of Assignment: 23/03/2020

Date Inspected: 20/03/2020 Inspected At:

 Alfred Auto Services & Supplies (HQ)
 Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang
 Mo Kio Industrial Park 2
 Singapore 569538

Estimated Period of Repair: 15.0 days

Adjuster: BRYAN TANI

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2020)
Parts:	143	KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW4477S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	952.00 F	*952.00 FL
2	1		*FRONT BONNET LOCK	Not Necessary	49.00 F	*- FL
3	2		*FRONT BONNET HINGER	Not Necessary	74.00 F	*- FL
4	10		*FRONT BONNER SPONGE CLIPS	Not Necessary	50.00 F	*- FL
5	2		*FRONT BONNET STOPPER	Not Necessary	36.00 F	*- FL
6	1		*FRONT FENDER O/S	Dented	348.00 F	*348.00 FL
7	1		*FRONT FENDER DUST GARNISH	Deformed / Torn	89.00 F	*89.00 FL
8	10		*FRONT FENDER DUST GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
9	2		*FRONT HEAD LAMP ASSY	O/S Cracked / N/S Mtg Cracked	3,614.00 F	*3,614.00 FL
10	1		*FRONT HEAD LAMP BRACKET	O/S Broken / N/S Not Necessary	80.00 F	*40.00 FL
11	1		*FRONT BUMPER	Dented	630.00 F	*630.00 FL
12	1		*FRONT BUMPER KIA LOGO	Necessary	37.00 F	*37.00 FL
13	1		*FRONT BUMPER SIDE RETAINER	O/S Broken / N/S Not Necessary	80.00 F	*40.00 FL
14	1		*FRONT BUMPER SPONGE	Torn	196.00 F	*196.00 FL
15	1		*FRONT BUMPER REINFORCEMENT	Dented	310.00 F	*310.00 FL
16	2		*FRONT BUMPER BRACKET	Not Necessary	130.00 F	*- FL
17	1		*FRONT BUMPER TOP RUBBER	Not Necessary	57.00 F	*- FL
18	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	87.00 F	*- FL
19	1		*FRONT BUMPER FOG LAMP ASSY O/S	Mtg Cracked	283.00 F	*283.00 FL
20	1		*FRONT BUMPER TOWING COVER	Dislodged / Broken	14.00 F	*14.00 FL
21	1		*FRONT BUMPER NO. PLATE GARNISH	Dented	39.00 F	*39.00 FL
22	1		*FRONT NO. PLATE & BOX	Bent	50.00 FS	*45.00 FS
23	10		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
24	1		*FRONT GRILLE	Cracked	385.00 F	*385.00 FL
25	6		*FRONT GRILLE CLIPS	Necessary	36.00 FS	*15.00 FS
26	1		*WIPER TANK	Deformed / Cracked	198.00 F	*198.00 FL
27	1		*FRONT SUPPORT PANEL	Cracked / Dented	469.00 F	*469.00 FL
28	1		*RADIATOR	Not Necessary	668.00 F	*- FL
29	1		*RADIATOR COOLANT	Not Necessary	60.00 F	*- FL
30	1		*REAR BOOT	Buckled	1,388.00 F	*1,388.00 FL
31	2		*REAR BOOT HINGER	Bent	148.00 F	*148.00 FL
32	1		*REAR BOOT KIA LOGO	Necessary	37.00 F	*37.00 FL
33	1		*REAR BOOT CERATO K3 EMBLEM	Necessary	34.00 F	*34.00 FL
34	1		*REAR C& C LOGO	Necessary	16.00 F	*16.00 FL
35	2		*REAR BOOT LAMP	Cracked	1,160.00 F	*1,160.00 FL
36	2		*REAR BOOT NO. PLATE LAMP	Not Necessary	76.00 F	*- FL
37	1		*REAR BOOT REVERSE CAM	Not Necessary	297.00 F	*- FL
38	1		*REAR BOOT STOPPER	O/S Not Necessary/N/SDislodged	24.00 F	*12.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*REAR BOOT LOCK	Bent	149.00 F	*149.00 FL
40	1		*REAR BOOT OPENER SWITCH	Not Necessary	69.00 F	*- FL
41	1		*REAR BOOT HANDLE	Not Necessary	38.00 F	*- FL
42	1		*REAR BOOT INNER GARNISH	Bent	221.00 F	*221.00 FL
43	1		*REAR BOOT INNER GARNISH CLIPS (12PCS)	Necessary	60.00 FS	*20.00 FS
44	2		*REAR LAMP	Cracked / Mtg Cracked	1,278.00 F	*1,278.00 FL
45	2		*REAR LAMP PANEL	Dented	420.00 F	*420.00 FL
46	1		*REAR WEATHER STRIP	Deformed	105.00 F	*105.00 FL
47	1		*REAR SUPPORT PANEL	Buckled	347.00 F	*347.00 FL
48	1		*REAR SUPPORT PANEL GARNISH	Bent	58.00 F	*58.00 FL
49	1		*REAR SUPPORT PANEL LOCK CATCH	Bent	28.00 F	*28.00 FL
50	1		*REAR SPARE TANK FLOOR PANEL	Buckled	714.00 F	*714.00 FL
51	1		*REAR SPARE TANK TOOLS SPONGE	Not Necessary	290.00 F	*- FL
52	1		*REAR SPARE TANK INSULATOR	Necessary	280.00 FS	*80.00 FS
53	1		*REAR SPARE TANK DUST GARNISH	Not Necessary	49.00 F	*- FL
54	6		*REAR SPARE TANK DUST GARNISH CLIPS	Not Necessary	30.00 F	*- FL
55	1		*REAR SPARE TYRE COVER	Serviceable	280.00 F	*- FL
56	1		*WINDSCREEN MOULDING	Necessary	45.00 F	*45.00 FL
57	1		*WINDSCREEN SEAL	Necessary	28.00 F	*28.00 FL
58	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
59	2		*REAR FENDER	Dented	2,448.00 F	*2,448.00 FL
60	2		*REAR FENDER LOWER DUST GARNISH	Not Necessary	410.00 F	*- FL
61	10		*REAR FENDER DUST GARNISH CLIPS	Not Necessary	50.00 F	*- FL
62	2		*REAR FENDER INNER GARNISH TRIM	Bent	362.00 F	*362.00 FL
63	20		*REAR FENDER INNER GARNISH CLIPS	Necessary	100.00 FS	*30.00 FS
64	1		*REAR FENDER AIR DUCT (RH)	Deformed	128.00 F	*128.00 FL
65	1		*REAR BUMPER	Dented	737.00 F	*737.00 FL
66	1		*REAR BUMPER SPONGE	Torn	299.00 F	*299.00 FL
67	1		*REAR BUMPER REINFORCEMENT	Broken	346.00 F	*346.00 FL
68	1		*REAR BUMPER LOWER BRACKET (4PCS)	N/S Not Necessary / O/S Bent	128.00 F	*64.00 FL
69	1		*SET REAR BUMPER PARKING SENSOR	Damaged	380.00 FS	*220.00 FS
70	1		*REAR BUMPER SPOILER	Torn	1,050.00 F	*1,050.00 FL
71	2		*REAR BUMPER REFLECTOR	O/S Cracked / N/S Scratched	264.00 F	*264.00 FL
72	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
73	1		*REAR EXHAUST	Bent	591.00 F	*591.00 FL
74	4		*REAR EXHAUST MOUNTING	Not Necessary	96.00 F	*- FL
75	1		*REAR EXHAUST CENTRE PIPE	Bent	661.00 F	*661.00 FL
76	1		*REAR EXHAUST ALUMINIUM HEAT SHIELD	Bent	141.00 F	*141.00 FL
77	1		*SET REAR TOUGH COAT SHIELD	Not Necessary	400.00 F	*- FL
78	1		*REAR NO. PLATE & BOX	Bent	50.00 FS	*45.00 FS
79	2		*REAR BIG BRACKET	Dented	196.00 F	*196.00 FL
80	1		*FRONT BUMPER TOP COVER BASE	Mtg Cracked	109.00 F	*109.00 FL
81	4		*FRONT BUMPER TOP BASE CLIPS	Necessary	20.00 FS	*20.00 FS
82	1		*FRONT BUMPER LOWER BEAM	Serviceable	165.30 F	*- FL
83	1		*FRONT RADIATOR RH SIDE GARNISH	Torn	105.80 F	*105.80 FL
84	1		*FRONT RH FENDER INNER COVER	Torn	99.30 F	*99.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 26,306.40 22,028.10
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 2,143.31

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	26,306.40
						19,884.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING, REMOVE & REFIT & CHECK SRS, ABS, SENSOR, HEAD LAMP SENSOR, ROOM, TAIL LAMP & RESETTING & ERASE FAULT CODE	New	480.00	120.00
2	TO REMOVE & REFIT RADIATOR, AIR-CON CONDENSER & TOP-UP AIR-CON & GAS	New	200.00	120.00
3	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
4	TO REMOVE & REFIT INTERIOR GARNISH, CARPET, CUSHION, & ALL ACCIDENT AFFECTED AREA	New	280.00	120.00
5	TO REMOVE & REFIT EXHAUST PIPE, BOX & ALL AFFECTED AREA	New	220.00	100.00
6	TO REMOVE & REFIT FUEL TANK	New	250.00	0.00
7	TO REMOVE & REFIT REAR UNDERCARRIAGE & AFFECTED DAMAGE AREA	New	400.00	0.00
8	TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT	New	180.00	0.00
9	TO WELDING, KNOCKING, STRAIGHTENING REPAIR & RENEW ALL ACCIDENT DAMAGED AFFECTED AREA	New	2,200.00	1,800.00
10	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA. (FRONT / REAR) (PEARL)	New	2,400.00	1,600.00
11	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	250.00	80.00
Gross Labour Cost (S\$)			7,040.00	4,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >