



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2006229  
INV Date 10/09/2020  
Reference CC4/FCI20004291/Kea3s2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SMJ 4913H  
Insured Veh. SHC 7282X  
Claim No. D20001571MFSH  
Policy No. D-20094921MFSH  
Accident Date 18/03/2020  
Inspection Date 20/03/2020

Description	Total
Survey Inspection	225.00
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>225.00</b>
<b>GST (7%)</b>	<b>15.75</b>
<b>Grand Total</b>	<b>240.75</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20004291/Kea3s2

36 ROBINSON ROAD  
#16-01 CITY HOUSES SINGAPORE 068877

Date : 10-09-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHC 7282X	<b>Veh. Inspected</b>	SMJ 4913H
<b>Policy No.</b>	D-20094921MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D20001571MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	MERINA	<b>Assign Date</b>	20/03/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA VELLFIRE (A)	<b>c.c</b>	2493
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	AGH300024419	<b>Colour</b>	METLLIC BLACK
<b>Odometer</b>	196064	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	235/50 R18	BRIDGESTONE	4 mm
<b>L/H Front Tyre</b>	235/50 R18	BRIDGESTONE	4 mm
<b>R/H Rear Tyre</b>	235/50 R18	BRIDGESTONE	4 mm
<b>L/H Rear Tyre</b>	235/50 R18	BRIDGESTONE	4 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	18/03/2020	<b>Inspection Date</b>	20/03/2020
<b>Survey held at</b>	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>6 Working Days</b>
-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 4913H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT LH DOOR	BENT	1,672.70	1,672.70
1	FRONT LH DOOR PROTECTOR	DENTED	1,061.70	1,061.70
1	FRONT LH DOOR TOP INNER RUBBER	* CHECK	188.10	-
1	FRONT LH DOOR INNER RUBBER	* CHECK	380.50	-
1	FRONT LH DOOR GLASS REGULATOR	* CHECK	489.80	-
1	LH SLIDING DOOR	BENT	1,920.90	1,920.90
1	LH SLIDING DOOR LOWER PROTECTOR	DENTED	728.40	728.40
1	LH SLIDING DOOR INNER RUBBER	* CHECK	348.70	-
1	LH CENTRE PANEL OUTER	TO REPAIR SEE LABOUR	496.20	-
	LESS 25% DISCOUNT		-1,821.75	-1,345.92
			5,465.25	4,037.78
<b><u>SPECIAL NETT ITEMS</u></b>				
1	DOOR SUN VISOR (SN)	NECESSARY	280.00	280.00
1	LH DOOR PROTECTION (SN)	* CHECK	300.00	-
1	FRONT LH DOOR FRAME RUBBER (SN)	CUT	45.00	45.00
1	ROLL LH SLIDING DOOR GLASS GUM (SN)	NECESSARY	40.00	40.00
			665.00	365.00
<b><u>LABOUR</u></b>				
	REMOVE & REFIX FRT LH DOOR, TRANSFER DOOR LOCK ASSY, INNER TRIM BOARD ASSY, RUBBER, REMOVE & REFIX LH SLIDING DOOR, CUT, WELD & RENEW LH DOOR PILLAR, KNOCK & REPAIR LH ROCKER PANEL & REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF LH CENTRE PANEL OUTER.		1,000.00	700.00
	REMOVE & REFIX FRT LH DOOR GLASS.		60.00	60.00
	REMOVE & REFIX LH SLIDING DOOR GLASS.		100.00	80.00
	REMOVE & REFIX CARPET, GARNISH, SAFETY BELT, ETC.	* CHECK	100.00	-
	PUTTY & RESPRAY ON FRT LH DOOR, LH ROCKER PANEL, LH DOOR PILLAR, LH SLIDING DOOR, PROTECTORS & ALL AFFECTED AREAS.		1,000.00	900.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RUSTPROOFING.		90.00	60.00
			2,350.00	1,800.00
GRAND TOTAL			8,480.25	6,202.78

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,455.33 NETT)				4,950.00
---	--	--	--	----------

Report Ref No. CC4/FCI20004291/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 4913H

INSPECTION








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

