

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20004297/T1ES3Q2

Date: 07/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993856

Claimant
Vehicle No : SKQ4273H **Insured Vehicle No :** SMN5262A

Date of Loss: 13/03/2020 Nature of Claim: TP Claim No: 1123562829SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ4273H		
Make & Model:	MAZDA 6, 2.5 4-DOOR SEDAN 2.5L SP.6E (A)	Engine No:	PY20463874
Reg. Date:	27/11/2014 (Man. Year: 2014)	Chassis No:	JM6GJ1031F0146916
Colour:	White	Odometer:	151523 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,302.04	2,081.36	6,220.68	74.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,350.00	1,600.00	54.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,252.04	3,431.36	7,820.68	69.50
Approved Total (Overridden) (\$\$)		2,700.00		
(\$\$)	11,252.04	2,700.00	8,552.04	76.00
+ GST 7.00/7.00% (\$\$)	787.64	189.00	598.64	76.00
Nett Amount (\$\$)	12,039.68	2,889.00	9,150.68	76.00
+ Car Rental (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		3,525.45		

INSPECTION

Date of Assignment: 19/03/2020

Date Inspected: 19/03/2020 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,378.40 FL	*879.80 FL
2	2		*REAR BUMPER RETAINER	Not Necessary	144.80 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	532.10 FL	*460.00 FL
4	2		*REAR BUMPER REFLECTOR	Cracked	162.50 FL	*162.50 FL
5	1		*END PANEL	Bent	565.40 FL	*482.60 FL
6	1		*END PANEL TOP GARNISH	Deformed	323.40 FL	*180.10 FL
7	1		*REAR LH TAILLAMP	Not Necessary	791.10 FL	*- FL
8	1		*REAR RH TAILLAMP	Not Necessary	791.10 FL	*- FL
9	1		*BOOTLID	Repair	1,394.10 FL	*- FL
10	1		*BOOTLID WEATHERSTRIP	Not Necessary	190.60 FL	*- FL
11	1		*BOOTLID EMBLEM LOGO	Necessary	63.70 FL	*63.70 FL
12	1		*BOOTLID EMBLEM -MAZDA	Necessary	46.40 FL	*46.40 FL
13	1		*BOOTLID EMBLEM -6	Necessary	39.10 FL	*39.10 FL
14	1		*BOOTLID LAMP LH	Not Necessary	436.00 FL	*- FL
15	1		*BOOTLID LAMP RH	Not Necessary	436.00 FL	*- FL
16	1		*BOOTLID LOCK STRIKER	Not Necessary	118.50 FL	*- FL
17	1		*BOOTLID INNER TRIM	Not Necessary	212.60 FL	*- FL
18	1		*BOOTLID OUTER CHROME GARNISH	Not Necessary	391.40 FL	*- FL
19	1		*SPARE TYRE TOP BOARD	Not Necessary	486.75 FL	*- FL
20	1		*REAR EXHAUST SILENCER	Repair	1,008.60 FL	*- FL
21	2		*REAR EXHAUST MOUNTING	Not Necessary	40.00 FL	*- FL
22	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
23	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
24	1		*SET REAR REVERSE SENSOR	Not Working	400.00 FS	*200.00 FS
25	1		*SET BOOT LID INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
26	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,212.55	2,544.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,910.51	462.84
Total Parts (\$\$)	8,302.04	2,081.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE,REFIT REAR LINING TRIM AND GARNISH	New	150.00	60.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	30.00
4	REMOVE AND RENEW REAR EXHAUST SILENCER	New	120.00	0.00
5	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	0.00
6	PANEL BEATING AND RENEW DAMGAR PARTS ON AFFECTED AREA	New	1,000.00	600.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	600.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	30.00
Gross Labour Cost (\$\$)			2,950.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >