

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004300/UPS3Q2
Date: 28/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900253749	
Claimant Vehicle No :	GBH4345M	Insured Vehicle No :	GBE5071L	
Date of Loss:	13/03/2020	Nature of Claim:	TP	Claim No: 3890408778SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH4345M		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KD2805612
Reg. Date:	01/06/2018 (Man. Year: 2018)	Chassis No:	JTFHT02PX00242998
Colour:	Silver	Odometer:	67329 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,269.82	3,129.32	5,140.50	62.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	1,510.00	2,170.00	58.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,949.82	4,639.32	7,310.50	61.18
Approved Total (Overridden) (S\$)		3,700.00		

Nett Amount (S\$)	11,949.82	3,700.00	8,249.82	69.04
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		4,378.45		

INSPECTION

Date of Assignment: 20/03/2020

Date Inspected: 20/03/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Zoom Autowerks Pte Ltd (Bedok)
 130 Bedok Reservoir Road, #08-1339
 Singapore 470130

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Torn	933.70 FL	*631.10 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	264.00 FL	*- FL
3	2		*REAR BUMPER BRACKET	Not Necessary	196.00 FL	*- FL
4	2		*REAR BUMPER CORNER	Not Necessary	350.00 FL	*- FL
5	2		*REAR BUMPER IMPACT BRACKET	No such part	386.00 FL	*- FL
6	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*50.00 FL
7	2		*REAR TAILLAMP	Not Necessary	1,989.60 FL	*- FL
8	1		*REAR TAILGATE	Dented / Bent	2,150.00 FL	*2,150.00 FL
9	1		*REAR TAILGATE LOGO	Necessary	98.00 FL	*98.00 FL
10	1		*REAR TAILGATE EMBLEM STICKER (HIACE)	Necessary	72.00 FL	*72.00 FL
11	1		*REAR TAILGATE EMBLEM STICKER (TOYOTA)	Necessary	68.00 FL	*68.00 FL
12	1		*REAR TAILGATE GLASS INNER SPONGE SEAL	Necessary	98.00 FL	*98.00 FL
13	1		*REAR TAILGATE INNER TRIMBOARD	Not Necessary	245.70 FL	*- FL
14	1		*REAR TAILGATE INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
15	1		*REAR TAILGATE LOCK	Serviceable	482.50 FL	*- FL
16	1		*REAR END PANEL TOP TRIM GARNISH	Not Necessary	384.60 FL	*- FL
17	1		*REAR END PANEL INNER	Repair	685.00 FL	*- FL
18	1		*REAR END PANEL OUTER	Badly Dented	672.00 FL	*672.00 FL
19	1		*REAR EXHAUST END PIPE	Not Necessary	942.00 FL	*- FL
20	2		*REAR EXHAUST MOUNTING	Not Necessary	136.00 FL	*- FL
21	1		*REAR TAILGATE STICKER 70KM	Necessary	45.00 FS	*10.00 FS
22	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
23	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
24	1		*REAR NUMBER PLATE W/GARNISH	Not Necessary	80.00 FS	*- FS
25	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,838.10	4,089.10
- List Item Discount on L Items 25.00/25.00% (\$)	2,568.28	959.78
Total Parts (\$)	8,269.82	3,129.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,200.00	600.00
2	TO PUTTY ,SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS	New	1,400.00	600.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	80.00	20.00
4	TO REMOVE & INSTALL REAR TAILGATE COMPONENTS TRIM & GARNISH	New	150.00	60.00
5	TO REMOVE & INSTALL REAR TAILGATE GLASS	New	200.00	120.00
6	TO REMOVE & INSTALL REAR EXHAUST PIPE	New	150.00	0.00
7	TO RE-POSITION ,DRILL & INSTALL REVERSE SENSOR	New	150.00	50.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	60.00
Gross Labour Cost (\$\$)			3,680.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >