



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 4655J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT RIGHT DOOR PANEL ASSY	BENT	1,652.00	1,380.00
1	FRONT RIGHT DOOR INNER BOARD	SERVICEABLE	312.00	-
1	FRONT RIGHT DOOR LOCK MECHANISM	TO REPAIR SEE LABOUR	205.00	-
1	FRONT RIGHT DOOR LOCK CATCH	TO REPAIR SEE LABOUR	68.00	-
1	FRONT RIGHT DOOR GLASS	SERVICEABLE	650.00	-
1	FRONT RIGHT DOOR GLASS MOULDING	SERVICEABLE	185.00	-
1	FRONT RIGHT DOOR OUTER HANDLE	SERVICEABLE	176.00	-
1	FRONT RIGHT REGULATOR WITH MOTOR ASSY	TO REPAIR SEE LABOUR	478.00	-
1	FRONT RIGHT DOOR CHECKER LINKAGE	SERVICEABLE	167.00	-
1	FRONT RIGHT DOOR HINGE	BENT / DISTORTED	195.00	195.00
1	FRONT RIGHT DOOR SIGNAL LAMP	BROKEN	95.00	95.00
1	FRONT BUMPER ASSY (ADDITIONAL)	TO REPAIR SEE LABOUR	952.00	-
1	RH HEAD LAMP (ADDITIONAL)	CUT	872.90	872.90
	LESS 25% DISCOUNT		-1,501.97	-635.73
			4,505.93	1,907.17
1	DOOR OUTER WEATHER (@ \$175.10 DISC 50%) (SN) (ADDITIONAL)	CUT	210.00	87.55
	LESS 25% DISCOUNT		-52.50	-
			157.50	87.55
<u>SPECIAL NETT ITEMS</u>				
10	FRONT RIGHT DOOR INNER BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
1	FRONT RIGHT DOOR COMPANY STICKER (SN)	NECESSARY	180.00	80.00
1	RH DOOR DECAL (LOWER) (SN) (ADDITIONAL)	NECESSARY	40.00	25.00
			250.00	105.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT RIGHT AFFECTED AREA AND REPLACE FRONT RIGHT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT RIGHT DOOR LOCK MECHANISM, FRONT RIGHT DOOR LOCK CATCH, FRONT RIGHT REGULATOR WITH MOTOR ASSY AND FRONT BUMPER ASSY.		1,200.00	400.00
	TO PUTTY AND SPRAY PAINTING FRONT RIGHT PORTION.		1,200.00	500.00
	TO CHECK WIRING AND FOCUS FRONT HEALAMP.		50.00	20.00
	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AFFECTED AREA.		120.00	30.00
	TO TRANSFER FRONT RIGHT DOOR GLASS TO NEW DOOR. }		80.00	60.00
	TO REMOVE AND INSTALL FRONT RIGHT DOOR LOCK MECHANISM. }		80.00	-
	TO CHECK DOOR CENTRAL LOCKING FOR FUNCTION.	NOT NECESSARY	80.00	-
	TOWING SERVICE.	NOT NECESSARY	100.00	-
			2,910.00	1,010.00
	GRAND TOTAL		7,823.43	3,109.72
	RECOMMENDED COST OF REPAIRS			3,109.72

Report Ref No. CS/AWA20004306/Ksd3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.