

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2020		12 Apr 2020 15:22 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	-, Co. Reg. No.: -								
Main Claimant:	M W BROTHERS AUTO REPAIR, Co. Reg. No.: 51556900C								
Vehicle Reg. No.:	SJM5550J	Date of Loss:	17/03/2020 11:00 - :59 [134 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D201382C02	Policy/Cover Note No.:	DMB1SN30732219011						
Vehicle Reg. No. (Insured):	PC869E	Policy No. (Claimant):	5110202746-000006						
		Excess:	S\$0.00						
Repairer:	M W Brothers Auto Repair (HQ) 2 Kaki Bukit Avenue 2, #02-02 Kaki Bukit Autohub, 417921 Toa Payoh - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Albert Chua]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/04/2020]								
Adj Asg. Remarks:	survey revert								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJM5550J (SNM20D201382C02)**
[PC869E]

TP

M W BROTHERS AUTO REPAIR

Mar 17 2020 11:00AM

[-]

M W Brothers Auto Repair

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports

1 per page ☒

No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	17/03/20 14:27	Accident Statement		Load HTM	

Photos/Images

3 per page ☒

No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	17/03/20 14:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	17/03/20 14:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	17/03/20 14:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	17/03/20 14:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	17/03/20 14:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	17/03/20 14:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	17/03/20 14:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/05/20 09:42	General View		Load JPG	☒
2	28/05/20 09:42	General View		Load JPG	☒
3	28/05/20 09:42	General View		Load JPG	☒
4	28/05/20 09:42	General View		Load JPG	☒
5	28/05/20 09:42	General View		Load JPG	☒
6	28/05/20 09:42	General View		Load JPG	☒
7	28/05/20 09:42	General View		Load JPG	☒
8	28/05/20 09:42	General View		Load JPG	☒
9	28/05/20 09:42	General View		Load JPG	☒
10	28/05/20 09:42	General View		Load JPG	☒
11	28/05/20 09:42	General View		Load JPG	☒
12	28/05/20 09:42	General View		Load JPG	☒
13	28/05/20 09:42	General View		Load JPG	☒
14	28/05/20 09:42	General View		Load JPG	☒
15	28/05/20 09:42	General View		Load JPG	☒
16	28/05/20 09:42	General View		Load JPG	☒
17	28/05/20 09:42	General View		Load JPG	☒
18	28/05/20 09:42	General View		Load JPG	☒
19	28/05/20 09:42	General View		Load JPG	☒
20	28/05/20 09:42	General View		Load JPG	☒
21	28/05/20 09:42	General View		Load JPG	☒
22	28/05/20 09:42	General View		Load JPG	☒
23	28/05/20 09:42	General View		Load JPG	☒
24	28/05/20 09:42	General View		Load JPG	☒
25	28/05/20 09:42	General View		Load JPG	☒
26	28/05/20 09:42	General View		Load JPG	☒
27	28/05/20 09:42	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail Print
28	28/05/20 09:42	General View		Load JPG ☒
29	28/05/20 09:42	General View		Load JPG ☒
30	28/05/20 09:42	General View		Load JPG ☒
31	28/05/20 09:42	General View		Load JPG ☒
32	28/05/20 09:42	General View		Load JPG ☒
33	28/05/20 09:42	General View		Load JPG ☒
34	28/05/20 09:42	General View		Load JPG ☒
35	28/05/20 09:42	General View		Load JPG ☒
36	28/05/20 09:42	General View		Load JPG ☒
37	28/05/20 09:42	General View		Load JPG ☒
38	28/05/20 09:42	General View		Load JPG ☒
39	28/05/20 09:42	General View		Load JPG ☒
40	28/05/20 09:42	General View		Load JPG ☒
41	28/05/20 09:42	Chassis Number		Load JPG ☒
42	28/05/20 09:42	Odometer Reading		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail Print
1	17/03/20 14:27	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF
2	17/03/20 14:27	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF
3	17/03/20 14:27	certificate of insurance [Linked Accident Report Documents]		Load TIF
4	17/03/20 14:27	leasing agreement [Linked Accident Report Documents]		Load TIF
5	17/03/20 14:27	leasing agreement [Linked Accident Report Documents]		Load TIF
6	17/03/20 14:27	leasing agreement [Linked Accident Report Documents]		Load TIF
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	12/04/20 15:22	Pre-Repair Survey		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail Print
1	17/03/20 14:27	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail Print
1	17/03/20 14:26	Accident Photo		Load JPG ☒
2	17/03/20 14:26	Accident Photo		Load JPG ☒
3	17/03/20 14:26	Accident Photo		Load JPG ☒
4	17/03/20 14:26	Accident Photo		Load JPG ☒
5	17/03/20 14:26	Accident Photo		Load JPG ☒
6	17/03/20 14:26	Accident Photo		Load JPG ☒
7	17/03/20 14:26	Accident Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail Print
1	17/03/20 14:27	Accident Sketch Plan		Load TIF
2	17/03/20 14:27	Accident Sketch Plan		Load TIF
3	17/03/20 14:27	certificate of insurance		Load TIF
4	17/03/20 14:27	leasing agreement		Load TIF
5	17/03/20 14:27	leasing agreement		Load TIF
6	17/03/20 14:27	leasing agreement		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI20004309/GTD3S2**Date:** 01/06/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN30732219011
Claimant Vehicle No :	SJM5550J	Insured Vehicle No :	PC869E
Date of Loss:	17/03/2020	Nature of Claim:	TP
		Claim No:	SNM20D201382C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM5550J	Engine No:	1NZD178675
Make & Model:	TOYOTA COROLLA, 1.5 AXIO (A)	Chassis No:	NZE1416095455
Reg. Date:	08/01/2009 (Man. Year: 2008)	Odometer:	200276 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	12/04/2020	
Date Inspected:	22/05/2020	Inspected At: M W Brothers Auto Repair (HQ) 2 Kaki Bukit Avenue 2, #02-02 Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/1/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00 - \$2,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2020)
Parts:	143	TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM5550J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >