

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD20004314/R1YD3E2
Date: 07/07/2020

REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2019-00009769
Claimant Vehicle No :	SKT3214U	Insured Vehicle No :	SBW8283C
Date of Loss:	12/03/2020	Nature of Claim:	TP
			Claim No: 1202000014160

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT3214U		
Make & Model:	VOLKSWAGEN JETTA GP, 1.4 TSI 90 HL HID 1634G5 (A)	Engine No:	CAXE94927
Reg. Date:	29/05/2015 (Man. Year: 2014)	Chassis No:	WVWZZZ16ZFM001863
Colour:	Black	Odometer:	124134 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,160.00	1,596.80	2,563.20	61.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	510.00	410.00	100.00	19.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,670.00	2,006.80	2,663.20	57.03
+ GST 7.00/7.00% (S\$)	326.90	140.48	186.42	57.03
Nett Amount (S\$)	4,996.90	2,147.28	2,849.62	57.03

INSPECTION

Date of Assignment:	20/03/2020	
Date Inspected:	24/03/2020	Inspected At: Mk Vehicle Engineering Pte Ltd (HQ) 48 TOH GUAN ROAD EAST, #04-124/125 ENTERPRISE HUB Singapore 608586
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2020)
Parts: 143	VOLKSWAGEN JETTA GP 1.4 TSI 90 HL HID 1634G5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT3214U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,650.00 F	*1,212.00 FL
2	1		*REAR BUMPER SPONGE	Serviceable	225.00 F	*- FL
3	1		*REAR BUMPER SPOILER	Cut	855.00 F	*540.00 FL
4	1		*REAR BUMPER CARRIER	Serviceable	795.00 F	*- FL
5	1		*REAR BUMPER CENTRE RETAINER	Serviceable	105.00 F	*- FL
6	2		*REAR BUMPER RETAINER LH / RH	Serviceable	240.00 F	*- FL
7	2		*REAR LIGHT REFLECTOR - LH / RH	Serviceable	240.00 F	*- FL
8	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,160.00	1,772.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	175.20
Total Parts (S\$)	4,160.00	1,596.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND RENEW REAR BUMPER ASSY. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	150.00	150.00
2	TO RESPRAY REAR BUMPER	New	300.00	200.00
3	TO CARRY OUT DIAGNOSTIC CHECKS	New	60.00	60.00
Gross Labour Cost (S\$)			510.00	410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >