



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2007569
INV Date 11/11/2020
Reference CC4/LPC20004316/T1ea3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SGU 3123R
Insured Veh. XB 5833K
Claim No. 19/20/20/VC05/23223
Policy No. Z/19/VC05/003717
Accident Date 12/03/2020
Inspection Date 20/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC20004316/T1ea3q2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 11-11-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XB 5833K	Veh. Inspected	SGU 3123R	
Policy No.	Z/19/VC05/003717	Coverage (\$)	0.00	
Claim No.	19/20/20/VC05/23223	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	20/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	ACR507047406	Colour	SILVER	
Odometer	200276	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	BEARWAY	6 mm	
L/H Front Tyre	215/50 R17	BEARWAY	6 mm	
R/H Rear Tyre	215/50 R17	BEARWAY	6 mm	
L/H Rear Tyre	215/50 R17	BEARWAY	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/03/2020	Inspection Date	20/03/2020	
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 3123R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	856.60	856.60
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	496.40	-
1	FRONT BUMPER LOWER GRILLE	DEFORMED	198.70	198.70
1	FRONT BUMPER LOWER SIDE GRILLE LH	NOT NECESSARY	96.40	-
1	FRONT GRILLE	CRACKED	456.60	456.60
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	1,489.60	-
1	RADIATOR	NOT NECESSARY	2,685.40	-
1	AIR CON CONDENSER	NOT NECESSARY	1,547.40	-
1	LH FRONT HEADLAMP	CRACKED	865.40	865.40
1	FRONT SUPPORT PANEL TOP GARNISH	CRACKED	189.70	189.70
1	BONNET	BENT	798.80	798.80
1	BONNET LOCK	BENT	248.60	248.60
	LESS 25% DISCOUNT		-2,482.40	-903.60
			7,447.20	2,710.80
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	20.00
1	FRONT NUMBER PLATE WITH CASING (SN)	CRACKED	60.00	45.00
1	AIR CON GAS (SN)	NOT NECESSARY	80.00	-
			190.00	65.00
<u>LABOUR</u>				
	TO CHECK ELECTRICAL WIRING .		50.00	30.00
	VACCUM AND TOP AIR CON GAS.	NOT NECESSARY	150.00	-
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	100.00	-
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	30.00
	SPRAY PAINTING ON AFFECTED AREAS.		600.00	500.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL .		800.00	600.00
			1,820.00	1,160.00
GRAND TOTAL			9,457.20	3,935.80



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00
---	--	--	----------

Report Ref No. CC4/LPC20004316/T1ea3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGU 3123R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGU 3123R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

