

ASS. REC. BY: Tan Kah REF: CS3/AGI19016124/110d30-1 and instructions

Survey: Justin Wong ASSIGNMENT (Office) 20/3/2020

From (Person): Ivy Reffler of AGI Date/Time: 12/9/19 @ 9:51am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD/TP/VS/TP RES / OD RES / EYA / RV / MV / CS

To Inspect Vehicle No: GBE 5336Z Insured: SGM 5347R

at Workshop m/s: 8in Foo Hing Battery Tel: 97336031

of 27A Jurong Port Road # 01-30

Policy No: \_\_\_\_\_ Claim No: C10003981/ky

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 10/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 10:49am @ 12/9/19 Person Contacted: Mr. Sin Vehicle IN/OUT: OUT

Date/Time	Action/Instruction
	<u>Vehicle X</u>
	<u>SGM 5347R - CCG/MJ1501 XCB3/1cpb312 D.O.A. 17/10/15</u>
	<u>GBE 5336Z X</u>
	<u>Before paint: 18/9/2019</u>
	<u>After paint: 23/9/2019</u>
<u>26/3/20</u>	<u>Submit US \$ 9000, 10 days.</u>
	<u>Chkd \$ 2000, 18%.</u>

2/5/9000, 10 days

25/3/2020

RECEIVED 26 MAR 2020

460-220 = 240

PRS

Tan Jie

AGI

# ASSIGNMENT

06/01/2016

Form

Date

13/09/2014

Estimated Cost

OU / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

GBE 5336Z

at Workshop no

Sin Foo Hing Battery

at

27A Junyong Port Road # 01-30

Insured

Policy No

Claims No

Sum Insured


Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. of Market Value:

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs

days

Res:

Yes or No

Turn Sum:

%

3 Val

Yes or No

CA / REV / REP. / 24 HRS

(wp)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

GBE 5336Z

or Regn

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna cc 2982

Colour

Silver

A/C

Insured / Std / NI / NA

Sp Reading

143508

T/Radio

Insured / Std / NI / NA

Eng/No

C/No

1723 8022415

Gen. Cond

Good / Fair / Poor / Burnt

Steering

Insured / Jammed / Leaked / Burnt or

Brake

Insured / Jammed / Leaked / Burnt or

Mod

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/75/R15

R:

145/R13 (17)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

6

mm

R/Bal

6/6

mm

L/Bal

6

mm

L/Bal

6/6

mm

D.O.A.

D.O.I.

13/9/14 @ 12pm

Survey held at

Sin Foo Hing

Des. of Damages

Frnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

N. 6/14

\$9000 - \$10,000, 10 days

Use/Time, File Photo?



: Preli. Report

U



: Final Report

Est/Time, File Photo?

3

Days Of Repair:

10

Resturvey No. of Trip:

2

Survey Fee:

Inspection

1 - PRE - 34

1 - PRE - 34

1 - PRE - 34

1 - PRE - 34

1 - PRE - 34

100

60

60

210

Artd Fee:



Site Insp: 15



Interview: 15



Truck Insp: 15



Truck Insp: 15

Exp/Grp/Insured

PRS

Exp/Grp/Insured

MAR019120542 / Automotive Repair Centre Pte Ltd - HQ  
 ENTRY DATE & TIME: 11/09/2019 12:22  
 SUBMITTED BY: Lin Shu Juan

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 11/09/2019 12:22  
 Date Of Accident 10/09/2019 15:30  
 Exact Location Of Accident ALONG AYE TOWARDS CLEMENTI  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SGM5347R  
**Insured/Policyholder**  
 Name Of Registered Owner YONG WAI LEONG  
 NRIC No S7523464C  
 Email Address TEAMZ.ERA.SEAN@GMAIL.COM  
 Mobile Phone No (LOCAL) +65-82870379  
 Alternative Phone No Others-82870379

### Vehicle Particulars

Manufacturer TOYOTA  
 Model WISH-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number P10023962R01  
 Cover Note Number

### Driver

Name of Driver LAI WING JYE  
 NRIC No S7501931I  
 Date Of Birth 12/01/1975  
 Occupation OUTDOOR  
 Date Of Driving Pass 02/03/2007  
 Driving Experience 12 YEARS AND 6 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-82870379

Fax Number	
Contact Number	OTHERS-82870379
Email Address	TEAMZ.ERA.SEAN@GMAIL.COM
Address	BLK 545 CHOA CHU KANG STREET 52 #05-06
Postcode	680545
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - EMPLOYEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	GBE5336Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	SHAO QIZHU
NRIC/Passport Number	G8162316W
Contact Number	
Address	
Postcode	

Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJE8998Z  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number 84326888  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number GBA3028Y  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category GOODS VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number 91551563  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SMA9141H  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number 87238998  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Sketch Plan #2

## SKETCH PLAN



## LOCATION:

AYE TOWARDS CLEMENZI.

A- 8AM5347R

B- GBE33362

C- 3JE89982

D- GBH3028Y

E- SMH9141H

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Was driving along the above mentioned date, time and location when the lorry in front of me make a sudden e-brake I was unable to react hence my vehicle collided into the rear of the lorry I alighted and realised there were a total of 5 cars involved (including mine) in this incident

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date &amp; Time:

Driver's Signature

(If driver is not the policyholder)

Date &amp; Time:

11/9/2019

12 29 pm

Reporting Centre Personnel's Signature

Name:

NRIC/VIN No



## CARLINK CONSULTANCY

60 Hillside Drive, Singapore 549009

Fax: 62874788 Tel: 62856178

## INVOICE

M/S Pan Ocean Singapore Pte Ltd  
C/o 27A Jurong Port Road, #01-30  
Singapore 619101

Invoice No: CL 12188 TP  
Our Ref: CL 12188 GBE 5336 Z  
Date: 7th January 2020

S/N	DESCRIPTION	QTY	UNIT PRICE (\$)	AMOUNT (\$)
1	Vehicle No: GBE 5336 Z Charges for accident vehicle inspection and appraisal report, transportation, photographs & misc**** (photographs - 196 copies)			\$1,101.00
			<b>Total:</b>	<b>\$1,101.00</b>



We thank you for the opportunity to serve you and assure you of our best at all times

Automotive Engineer Assessor  
MIMI, MRTE, LCGI, I ENG, LAE, CGLIFTC

Note: Payment by cheque should be crossed and made payable to "CARLINK CONSULTANCY"



# CARLINK CONSULTANCY


80 Hillside Drive  
Singapore 549009

Tel : 62856178

Fax : 62874788

## ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CL 12188 GBE 5336 Z

<b>1 REFERENCE</b>			
Date of request	:	13th September 2019	
Requested by	:	M/S Pan Ocean Singapore Pte Ltd C/o 27A Jurong Port Road #01-30 Singapore 619101	
Type of claim	:	Third party	
Workshop	:	M/S Sin Foo Hing Battery Service 27A Jurong Port Road, #01-30 Singapore 619101	
Date of survey	:	13th September 2019	
Accident date	:	10th September 2019	
<b>2 DETAILS OF VEHICLE</b>			
Registration No.	:	GBE 5336 Z	
Make & Model	:	Toyota Dyna 3.0M	
Date of registration	:	6th January 2018	
Engine No.	:	1KD2589029	
Chassis No.	:	KDY2318022415	
Speedometer reading	:	143508 Km	
Transmission	:	Manual	
Colour	:	Silver	
<b>3 STATIC CHECK</b>			
Steering	:	see annex(es)	Paintwork : Good
Footbrake	:	see annex(es)	Modification : Nil
Handbrake	:	see annex(es)	General condition : Good
<b>4 TYRE CONDITION</b>			
		<u>Nearside/Make</u>	<u>Offside/Make</u> <u>Size</u>
Front tyre	:	6mm/Bridgestone	6mm/Bridgestone : 175/75 R15
Rear tyre	:	6mm/Bridgestone	6mm/Bridgestone : 145 R13
<b>5 POINT OF IMPACT</b>			
See Annex(es) and Motor Accident Reports			
<b>6 REMARK</b>			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

## Annex A : Assesement / Adjustment on Spare Parts

GBE 5336 Z

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
<b>List Items</b>						
1	Front bumper	Dented/bent	1	\$595.30	25%	\$446.48
2	Front bumper bracket	Dented/bent	2	\$354.90	25%	\$266.18
3	Front bumper fog lamp LH	Distorted/cracked	1	\$280.10	25%	\$210.08
4	Front bumper fog lamp garnish LH	Distorted/cut	1	\$65.20	25%	\$48.90
5	Front bumper fog lamp RH	Distorted/cracked	1	\$280.10	25%	\$210.08
6	Front bumper fog lamp garnish RH	Distorted/cut	1	\$65.20	25%	\$48.90
7	Front windscreen glass rubber	Necessary	1	\$548.20	25%	\$411.15
8	Head lamp LH	Grazed/cracked	1	\$781.85	25%	\$586.39
9	Head lamp lower rubber seal LH	Necessary	1	\$29.30	25%	\$21.98
10	Head lamp RH	Grazed/cracked	1	\$781.85	25%	\$586.39
11	Head lamp lower rubber seal RH	Necessary	1	\$29.30	25%	\$21.98
12	Front grille	Bent/cracked	1	\$527.00	25%	\$395.25
13	Front grille clips	Necessary	6	\$77.40	25%	\$58.05
14	Front grille bracket	Bent	2	\$82.20	25%	\$61.65
15	Front grille badge	Grazed/bent	1	\$61.75	25%	\$46.31
16	Front panel	Buckled	1	\$985.20	25%	\$738.90
17	Front LH corner panel	Shifted/distorted	1	\$286.10	25%	\$214.58
18	Front LH corner panel clips	Necessary	3	\$19.50	25%	\$14.63
19	Front RH corner panel	Shifted/distorted	1	\$286.10	25%	\$214.58
20	Front RH corner panel clips	Necessary	3	\$19.50	25%	\$14.63
21	Front apron garnish (center)	Grazed/bent/cut	1	\$291.80	25%	\$218.85
22	Front apron garnish (side-LH)	Bent	1	\$96.00	25%	\$72.00 X ND
23	Front apron garnish (side-RH)	Bent/slack	1	\$96.00	25%	\$72.00 X ND
24	Front apron garnish clips	Necessary	8	\$103.20	25%	\$77.40 X NN
25	Front wiper panel	Dented/bent	1	\$395.90	25%	\$296.93
26	Front wiper panel rubber seal	Shifted/cut	1	\$39.45	25%	\$29.59
27	Front wiper panel clips	Necessary	6	\$39.00	25%	\$29.25
28	Front wiper panel side garnish LH	Distorted/slack	1	\$68.30	25%	\$51.23 X ND
29	Front wiper panel side garnish clips LH	Necessary	3	\$19.50	25%	\$14.63 X NN
30	Front wiper panel side garnish RH	Distorted/slack	1	\$68.30	25%	\$51.23 X ND
31	Front wiper panel side garnish clips RH	Necessary	3	\$19.50	25%	\$14.63 X NN
32	Front wiper nozzle	Leaked	2	\$132.20	25%	\$99.15
33	Rear number plate holder	Dented/bent	1	\$261.10	100%	\$0.00 Rx
34	Rear number plate lamp	Shifted/faulty	2	\$121.10	25%	\$90.83
35	Rear chassis cross member	Repair	1	\$748.10	100%	\$0.00 Rx
<b>S/Nett Items</b>						
36	Front number plate	Cracked	1	\$38.00		\$38.00 30
37	Rear number plate	Cracked	1	\$38.00		\$38.00 30
38	Rear bumper guard c/w bracket	Bent/cut	1	\$1,200.00		\$1,200.00 1000
39	Rear over rider rubber bumper guard LH	Grazed/cut	1	\$150.00		\$150.00
40	Rear over rider rubber bumper guard RH	Grazed/cracked	1	\$150.00		\$150.00

GBE 5336 Z

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
41	Refrigerator box doors sticker sheet with company letter & logo LH	Grazed/cut	1	\$700.00		\$700.00
42	Refrigerator box doors sticker sheet with company letter & logo RH	Grazed/cut	1	\$700.00		\$700.00
43	Refrigerator box doors lower panel (stain less steel)	Repair	1	\$948.00		\$0.00
44	70 km/h sticker	Necessary	1	\$15.00		\$15.00
Total for Spare Parts :				\$12,594.50		\$8,725.73

7756.61

## Annex B : Adjustment on Labour and Spray Painting

GBE 5336 Z

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	To check wiring system & lighting system	\$180.00	\$120.00 60
2	Anti rust treatment	\$180.00	\$120.00 60
3	To remove & refix front windscreen to assist in repair	\$180.00	\$120.00 XNN
4	Labour to remove/replace refrigerator box doors sticker L/R	\$280.00	\$180.00 120.
5	Labour to renew damaged parts, straighten/repair and aligned all parts	\$2,500.00	\$2,100.00 1400
6	To respray affected areas	\$2,100.00	\$1,600.00 1200.
TOTAL FOR LABOUR & SPRAY PAINTING :		\$5,420.00	\$4,240.00 2840

### Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$12,594.50	\$8,725.73
TOTAL FOR LABOUR & SPRAY PAINTING :	\$5,420.00	\$4,240.00
TOTAL REPAIR COSTS :	\$18,014.50	\$12,965.73

7756.01  
 2840  
 10596.61  
 15% 45490.00

## CARLINK CONSULTANCY

GBE 5336 Z

### Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S Sin Foo Hing Battery Service estimated repair cost is **S\$18,014.50** and we have adjusted it to **S\$12,965.73** on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.

The repairer have agreed to undertake the repairs on a contract lump sum of **S\$11,000.00** ,according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of **12** working days.

We have advised the repairer that the inspection was conducted strictly on a WITHOUT PREJUDICE basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,  
CARLINK CONSULTANCY



PATRICK NG

Automotive Engineer Assessor  
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC.

# SIN FOO HING BATTERY SERVICE

27A Jurong Port Road #01-30 Singapore 619101

Fax: 6265 8115 HP: 9733 6031

Reg No: 52898075X

## INVOICE

P.O. No. \_\_\_\_\_

DATE: 7 January 2020

VEH. No.: GBE 5336 Z

TERMS: \_\_\_\_\_

M/s: Pan Ocean Singapore Pte Ltd  
No. 10 Fishery Port Road Singapore 619732

FINAL REPAIR BILL FOR VEHICLE NO. GBE 5336 Z

Lump Sum Repairs \$11,000.00




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL		Ref : CS3/AGI19016184/T1qd3e2-1		
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 26-03-2020		
		Code : AGI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGM 5347R	Veh. Inspected	GBE 5336Z	
Policy No.	P10023962R01	Coverage (\$)	0.00	
Claim No.	C10003981/KY	Excess (\$)	0.00	
Assign From	JUSTIN WONG	Assign Date	20/03/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KDY2318022415	Colour	SILVER	
Odometer	143508	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	175/75 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	175/75 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	145 R13 (D)	BRIDGESTONE	6/6 mm	
L/H Rear Tyre	145 R13 (D)	BRIDGESTONE	6/6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/09/2019	Inspection Date	13/09/2019	
Survey held at	SIN FOO HING-27A JURONG PORT ROAD#01-30			
Repairer	-			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 5336Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DENTED / BENT	595.30	595.30
2	FRONT BUMPER BRACKET	DENTED / BENT	354.90	354.90
1	FRONT BUMPER FOG LAMP LH	DISTORTED / CRACKED	280.10	280.10
1	FRONT BUMPER FOG LAMP GARNISH LH	DISTORTED / CUT	65.20	65.20
1	FRONT BUMPER FOG LAMP RH	DISTORTED / CRACKED	280.10	280.10
1	FRONT BUMPER FOG LAMP GARNISH RH	DISTORTED / CUT	65.20	65.20
1	FRONT WINDSCREEN GLASS RUBBER	NECESSARY	548.20	548.20
1	HEAD LAMP LH	GRAZED / CRACKED	781.85	781.85
1	HEAD LAMP LOWER RUBBER SEAL LH	NECESSARY	29.30	29.30
1	HEAD LAMP RH	GRAZED / CRACKED	781.85	781.85
1	HEAD LAMP LOWER RUBBER SEAL RH	NECESSARY	29.30	29.30
1	FRONT GRILLE	BENT / CRACKED	527.00	527.00
6	FRONT GRILLE CLIPS	NECESSARY	77.40	77.40
2	FRONT GRILLE BRACKET	BENT	82.20	82.20
1	FRONT GRILLE BADGE	GRAZED / BENT	61.75	61.75
1	FRONT PANEL	BUCKLED	985.20	985.20
1	FRONT LH CORNER PANEL	SHIFTED / DISTORTED	286.10	286.10
3	FRONT LH CORNER PANEL CLIPS	NECESSARY	19.50	19.50
1	FRONT RH CORNER PANEL	SHIFTED / DISTORTED	286.10	286.10
3	FRONT RH CORNER PANEL CLIPS	NECESSARY	19.50	19.50
1	FRONT APRON GARNISH (CENTER)	GRAZED / BENT / CUT	291.80	291.80
1	FRONT APRON GARNISH (SIDE-LH)	NOT DAMAGED	96.00	-
1	FRONT APRON GARNISH (SIDE-RH)	NOT DAMAGED	96.00	-
8	FRONT APRON GARNISH CLIPS	NOT NECESSARY	103.20	-
1	FRONT WIPER PANEL	DENTED / BENT	395.90	395.90
1	FRONT WIPER PANEL RUBBER SEAL	SHIFTED / CUT	39.45	39.45
6	FRONT WIPER PANEL CLIPS	NECESSARY	39.00	39.00
1	FRONT WIPER PANEL SIDE GARNISH LH	NOT DAMAGED	68.30	-
3	FRONT WIPER PANEL SIDE GARNISH CLIPS LH	NOT NECESSARY	19.50	-

Report Ref No. CS3/AGI19016184/T1qd3e2-1





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WIPER PANEL SIDE GARNISH RH	NOT DAMAGED	68.30	-
3	FRONT WIPER PANEL SIDE GARNISH CLIPS RH	NOT NECESSARY	19.50	-
2	FRONT WIPER NOZZLE	LEAKED	132.20	132.20
1	REAR NUMBER PLATE HOLDER	TO REPAIR SEE LABOUR	261.10	-
2	REAR NUMBER PLATE LAMP	SHIFTED / FAULTY	121.10	121.10
1	REAR CHASSIS CROSS MEMBER	TO REPAIR SEE LABOUR	748.10	-
	LESS 25% DISCOUNT		-	-1,793.88
			8,655.50	5,381.62
	<b>SPECIAL NETT ITEMS</b>			
1	FRONT NUMBER PLATE (SN)	CRACKED	38.00	30.00
1	REAR NUMBER PLATE (SN)	CRACKED	38.00	30.00
1	REAR BUMPER GUARD C/W BRACKET (SN)	BENT / CUT	1,200.00	1,000.00
1	REAR OVER RIDER RUBBER BUMPER GUARD LH (SN)	GRAZED / CUT	150.00	150.00
1	REAR OVER RIDER RUBBER BUMPER GUARD RH (SN)	GRAZED / CRACKED	150.00	150.00
1	REFRIGERATOR BOX DOORS STICKER SHEET WITH COMPANY LETTER & LOGO LH (SN)	GRAZED / CUT	700.00	500.00
1	REFRIGERATOR BOX DOORS STICKER SHEET WITH COMPANY LETTER & LOGO RH (SN)	GRAZED / CUT	700.00	500.00
1	REFRIGERATOR BOX DOORS LOWER PANEL (STAIN LESS STEEL) (SN)	TO REPAIR SEE LABOUR	948.00	-
1	70 KM/H STICKER (SN)	NECESSARY	15.00	15.00
			3,939.00	2,375.00
	<b>LABOUR</b>			
	TO CHECK WIRING SYSTEM & LIGHTING SYSTEM.		180.00	60.00
	ANTI RUST TREATMENT.		180.00	60.00
	TO REMOVE & REFIX FRONT WINDSCREEN TO ASSIST IN REPAIR.	NOT NECESSARY	180.00	-
	LABOUR TO REMOVE / REPLACE REFRIGERATOR BOX DOORS STICKER L/R.		280.00	120.00
	LABOUR TO RENEW DAMAGED PARTS, STRAIGHTEN / REPAIR AND ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF REAR NUMBER PLATE HOLDER, REAR CHASSIS CROSS MEMBER AND REFRIGERATOR BOX DOORS LOWER PANEL (STAIN LESS STEEL).		2,500.00	1,400.00
	TO RESPRAY AFFECTED AREAS.		2,100.00	1,200.00
			5,420.00	2,840.00

Report Ref No. CS3/AGI19016184/T1qd3e2-1



GRAND TOTAL		18,014.50	10,596.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,000.00

Report Ref No. CS3/AGI19016184/T1qd3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.