

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20004338/ABA3Q2

Date: 27/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900102803

Claimant Vehicle No : SMR7873C **Insured Vehicle No :** SML5790C

Date of Loss: 19/03/2020 Nature of Claim: TP Claim No: 9202134082SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR7873C		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR2G21281
Reg. Date:	22/01/2020 (Man. Year: 2019)	Chassis No:	ZWR800425526
Colour:	Black	Odometer:	18363 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,281.50	5,772.50	7,509.00	56.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,410.00	1,970.00	440.00	18.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,691.50	7,742.50	7,949.00	50.66
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	15,691.50	6,000.00	9,691.50	61.76
+ GST 7.00/7.00% (S\$)	1,098.41	420.00	678.41	61.76
Nett Amount (S\$)	16,789.91	6,420.00	10,369.91	61.76
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,227.45		
Global Sum Settlement (S\$)		7,200.00		

INSPECTION

Date of Assignment: 20/03/2020

Date Inspected: 20/03/2020 Inspected At:

Green Forest Automobile Pte Ltd (Kaki Bukit)
8 Kaki Bukit Avenue 4, #05-25,,
[Premier@Kaki Bukit](mailto:Premier@KakiBukit)
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,774.20 F	*1,774.20 FL
2	1		*REAR BOOT LID HYBRID LOGO	Necessary	40.00 F	*40.00 FL
3	1		*REAR BOOT LID LOCK	Damaged	385.10 F	*385.10 FL
4	1		*REAR BOOT LID CENTER MOULDING	Cracked	315.00 F	*315.00 FL
5	6		*REAR BOOT LID CENTER MOULDING CLIPS	Necessary	39.00 F	*39.00 FL
6	1		*REAR BOOT LID WEATHERSTRIP	Cut	285.00 F	*285.00 FL
7	1		*REAR BOOT LID EMBLE LOGO	Necessary	55.90 F	*55.90 FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	117.00 F	*- FL
10	1		*REAR BOOT LID INNER RUBBER	Repeated	265.00 F	*- FL
11	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	552.10 F	*552.10 FL
12	2		*BOOT LID SIDE REFLECTOR	Not Necessary	310.40 F	*- FL
13	2		*REAR TAIL LAMP	Not Necessary	1,250.40 F	*- FL
14	2		*TAIL LAMP LOWER PANEL	Not Necessary	510.80 F	*- FL
15	1		*REAR BUMPER	Deformed	1,455.00 F	*770.00 FL
16	1		*REAR BUMPER TOWING COVER	Missing	68.00 F	*36.00 FL
17	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	190.40 F	*- FL
18	8		*REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
19	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
20	1		*ANTENNA ELECTRICAL KEY	Cracked	425.00 F	*95.00 FL
21	1		*END PANEL	Dented	783.20 F	*783.20 FL
22	1		*END PANEL TOP GARNISH	Deformed	258.20 F	*258.20 FL
23	1		*REAR SPARE TIRE PANEL	Repair	1,225.20 F	*- FL
24	1		*REAR SPARE TIRE PANEL TOP SPONGE	Not Necessary	265.30 F	*- FL
25	1		*REAR SPARE TIRE PANEL TOP COVER	Cracked	485.20 F	*485.20 FL
26	1		*REAR SPARE TIRE PANEL SEALANT	Not Necessary	250.00 F	*- FL
27	2		*REAR FENDER SIDE INNER TRIM	Cracked	1,310.80 F	*1,310.80 FL
28	1		*REAR WINDSCREEN SEAL	Necessary	215.30 F	*215.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,281.50	7,630.00
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,857.50
Total Parts (\$)	13,281.50	5,772.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX CUSHION	New	120.00	60.00
2	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	GUM	New	50.00	50.00
4	TO REMOVE & REFIX REAR REVERSE SENSOR	New	120.00	50.00
5	TO CHECK WIRING SYSTEM	New	80.00	30.00
6	TUFF KOTE	New	120.00	60.00
7	PANEL BEATING	New	900.00	800.00
8	SPRAY PAINTING	New	900.00	800.00
Gross Labour Cost (\$\$)			2,410.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >