

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20004350/GVD3E2

Date: 29/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1900017783
Claimant Vehicle No : FBM1649E	Insured Vehicle No : SMJ5468U
Date of Loss: 18/03/2020	Nature of Claim: TP Claim No: 0657011384SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM1649E		
Make & Model:	HONDA WW150, 153cc	Engine No:	KF18E5049468
Reg. Date:	31/07/2017 (Man. Year: 2017)	Chassis No:	RLHKF18AXJY201126
Colour:	White	Odometer:	67726 km
Engine Capacity:	153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	100/90-14	Rear Tyre Size:	90/90-14
Front Left Side:	Michelin 5 mm	Rear Left Side:	IRC 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	20/03/2020		
Date Inspected:	22/06/2020	Inspected At:	Mcs Auto (HQ) 1100 Serangoon Rd Singapore 328195
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Repair	0.00 F	*- F
2	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
3	1		*HANDLE BAR	Repair	0.00 F	*- F
4	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
5	1		*CENTER FAIRING REAR	Cut	0.00 F	*- F
6	1		*FAIRING LOWER	Cut	0.00 F	*- F
7	1		*STEP BOARD	Cut	0.00 F	*- F
8	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
9	1		*REAR RIM	Repair	0.00 F	*- F
10	1		*REAR TAILLAMP	Scratched	0.00 F	*- F
11	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
12	1		*REAR BOX	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >