

621E

ASSIGNMENT

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB 3125Bat Workshop m/s TT MOTORSPORTof HB, TOH Huan Road No 1-103Insured: Alh

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 80K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 13 days 20 days Res. Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLB 3125B Yr Regn: 2016 / APRType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA HARRIER 2.0 E.L c.c. 1986Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 68663 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZSU600065404 *Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/65R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 13/03/2020Survey held at TT MOTORSPORTDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 23/03/2020

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

no G7D 8911121

Range & no. of days - (23k - 25k) / 24 days

RECEIVED 30 MAR 2020

Date/Time, File Pass to?

30/03/201) Fast

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportRep. Format: PRS

Lump Sum / L.B.I. (\$) _____

Days Of Repair: 20Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 180

Transportation: _____

S + RS. SI _____

Photos _____

Others 11TOTAL 191