Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG20004383/EYF3E2

AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Date: 25/08/2020

REFERENCE

Insured/Claimant: PHILIP LAM KHEEN TZEH Policy No: 1900141468

Date of Loss: 14/03/2020 Nature of Claim: OD Claim No: 9907389149SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJV2007J

Make & Model: AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A) Engine No: DAX057596

Reg. Date: 31/07/2019 (Man. Year: 2019) Chassis No: WAUZZZFY2K2117727

Colour: Grey Odometer: 5510 km

Engine Capacity: 1984 cc Market Value/New Car Price: \$\$172,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,988.00	4,450.40	1,537.60	25.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,752.00	3,152.00	2,600.00	45.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,740.00	7,602.40	4,137.60	35.24
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	10,740.00	6,602.40	4,137.60	38.53
+ GST 7.00/7.00% (S\$)	751.80	462.17	289.63	38.52
Nett Amount (S\$)	11,491.80	7,064.57	4,427.23	38.53

INSPECTION

Date of Assignment: 23/03/2020

Date Inspected: 23/03/2020 Inspected At: 281 Alexandra Road

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE Manager: YVONNE WONG YIN CHENG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Dented	2,972.00 FS	*2,377.60 FS
2	1		*REAR DOOR OUTER SEAL - LH	Necessary	193.00 FS	*154.40 FS
3	1		*BONDING AGENT	Necessary	46.00 FS	*36.72 FS
4	1		*CLEANING SOLUTION	Necessary	64.00 FS	*51.20 FS
5	1		*SEALING STRIP	Necessary	16.00 FS	*12.08 FS
6	1		*REAR DOOR CATCH	Not Necessary	137.00 FS	*-FS
7	1		*REAR DOOR ATTACHMENT PARTS	Necessary	209.00 FS	*167.20 FS
8	1		*REAR DOOR COVER - LH	Cut	595.00 FS	*476.00 FS
9	1		*REAR WHEEL COVER - LH	Cut	502.00 FS	*401.60 FS
10	1		*REAR ALUMINIUM RIM - LH	Cut	954.00 FS	*763.20 FS
11	1		*SUNDRIES	Necessary	300.00 FS	*10.40 FS
F=Franchise part. S=SpcNett.						-
				Total Parts (S\$)	5,988.00	4,450.40

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES	New	280.00	280.00
2	TO DISMANTLE AND RENEW LHS REAR DOOR. RE- ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY LHS REAR DOOR, DOOR COVER AND LHS REAR WHEEL ARCH TRIM	New	2,000.00	850.00
4	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REPAIR LHS REAR FENDER	New	800.00	500.00
7	TO RESPRAY LHS REAR FENDER	New	1,000.00	550.00
	Gross Labour Cost (S\$)		5,752.00	3,152.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >