

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20004384/AKA3Q2

**Date:** 07/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100447568-04

**Claimant**  
**Vehicle No :** SMM4905R **Insured Vehicle No :** SGW9998H

**Date of Loss:** 12/10/2019 **Nature of Claim:** TP **Claim No:** 4142393126SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMM4905R</b>		
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	CVK078046
Reg. Date:	28/06/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF47KA047998
Colour:	Blue	Odometer:	11498 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,014.00	8,199.12	5,814.88	41.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	3,022.00	2,100.00	41.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>19,136.00</b>	<b>11,221.12</b>	<b>7,914.88</b>	<b>41.36</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,339.52</b>	<b>785.48</b>	<b>554.04</b>	<b>41.36</b>
<b>Nett Amount (\$\$)</b>	<b>20,475.52</b>	<b>12,006.60</b>	<b>8,468.92</b>	<b>41.36</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (\$\$)</b>		400.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>12,408.60</b>		

### INSPECTION

Date of Assignment: 26/03/2020

Date Inspected: 26/03/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,068.00 FS	*1,654.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	553.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	34.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE -RH	Not Necessary	59.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	198.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	127.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	36.00 FS	*- FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	117.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	757.00 FS	*- FS
10	1		*LOCK CARRIER BRACKET	Not Necessary	129.00 FS	*- FS
11	2		*FRONT BUMPER SUPPORT -LH/RH	Not Necessary	54.00 FS	*- FS
12	1		*HORN -RH LOW TONE	Not Necessary	270.00 FS	*- FS
13	1		*SPRING SHACKLE-RH	Not Necessary	27.00 FS	*- FS
14	1		*FRONT PARKING AID SENSOR -INNER /OUTER (NPA)	Not Necessary	0.00 FS	*- FS
15	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
16	1		*FRONT FENDER -RH	Dented	722.00 FS	*577.60 FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	190.00 FS	*- FS
18	1		*FRONT FENDER CLOSING ELEMENT -RH	Not Necessary	47.00 FS	*- FS
19	1		*FRONT FENDER BRACKET -RH	Not Necessary	33.00 FS	*- FS
20	1		*FRONT FENDER BRACE -RH	Not Necessary	112.00 FS	*- FS
21	1		*WHEEL HOUSING LINER -RH	Not Necessary	228.00 FS	*- FS
22	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	219.00 FS	*- FS
23	1		*WHEEL SPOILER -RH	Not Necessary	69.00 FS	*- FS
24	1		*WHEEL SPOILER TRIM -RH	Not Necessary	34.00 FS	*- FS
25	1		*STONE CHIP GUARD -RH	Necessary	48.00 FS	*37.92 FS
26	1		*FENDER LEDGE COVER -RH OUTER	Necessary	29.00 FS	*23.20 FS
27	1		*FENDER LEDGE COVER -RH FRONT	Necessary	21.00 FS	*16.72 FS
28	1		*LED HEADLIGHT -RH	Cut	7,321.00 FS	*5,856.80 FS
29	1		*LIFT CYLINDER RH	Not Necessary	198.00 FS	*- FS
30	1		*SUNDRIES	Necessary	300.00 FS	*32.48 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 14,014.00 8,199.12**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,450.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,122.00</b>	<b>3,022.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >