

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20004392/EBA3N2
Date: 19/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800074425
Claimant
Vehicle No : SLG6292E **Insured Vehicle No :** SCG5522E
 Date of Loss: 21/03/2020 Nature of Claim: TP Claim No: 4571343099SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG6292E**
 Make & Model: AUDI A1, 1.4 (A) Engine No: CYV643110
 Reg. Date: 23/01/2020 (Man. Year: 2019) Chassis No: WVVZZZ16ZKM509501
 Colour: Orange Odometer: 2055 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R18 Rear Tyre Size: 235/45 R18
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,870.27	0.00	4,870.27	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	3,340.00	3,980.00	54.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,190.27	3,340.00	8,850.27	72.60
+ GST 7.00/7.00% (S\$)	853.32	233.80	619.52	72.60
Nett Amount (S\$)	13,043.59	3,573.80	9,469.79	72.60
+ Car Rental (6.0 x S\$80.00/day + 7.00% GST) (S\$)		513.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,089.40		

INSPECTION

Date of Assignment: 27/03/2020
 Date Inspected: 27/03/2020 Inspected At: Volkswagen Centre Singapore (HQ)
 247 Alexandra Road
 Singapore 159934
 Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*COVER FRT BUMPER PRIMED FRT BUMPER	Repair	1,313.79 FS	*- FS	
2	1		*GUIDE PIECE RHF SIDE BRACKET	Not Necessary	33.43 FS	*- FS	
3	1		*FENDER RHF	Repair	597.40 FS	*- FS	
4	1		*CROSS SUPPORT RHF FENDER BRACKET	Not Necessary	66.37 FS	*- FS	
5	1		*GAS DISCHARGE HEADLIGHT W RHF	Not Necessary	2,859.28 FS	*- FS	
					Total Parts (S\$)	4,870.27	0.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	3,360.00	1,260.00
2	SPRAY PAINTING	New	3,200.00	1,600.00
3	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
4	CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	0.00
			Gross Labour Cost (\$\$)	3,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >