

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD20004397/AGA3Q2

**Date:** 18/08/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00011934-01

**Claimant**  
**Vehicle No :** SMS1891J **Insured Vehicle No :** SLB3318L

**Date of Loss:** 21/03/2020 **Nature of Claim:** TP **Claim No:** 1202000014740

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMS1891J</b>                   |             |                   |
| Make & Model:               | TOYOTA CAMRY, 2.5 HYBRID CVT (A)  | Engine No:  | A25A5206901       |
| Reg. Date:                  | 14/02/2020 (Man. Year: 2019)      | Chassis No: | JTNB23HK903036726 |
| Colour:                     | White                             | Odometer:   | 9726 km           |
| Engine Capacity:            | 2487 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 215/55 R17    | Rear Tyre Size:  | 215/55 R17    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 8,228.62          | 5,966.20          | 2,262.42          | 27.49         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 3,910.00          | 1,800.00          | 2,110.00          | 53.96         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>              | <b>12,138.62</b>  | <b>7,766.20</b>   | <b>4,372.42</b>   | <b>36.02</b>  |
| <b>Approved Total (Overridden) (S\$)</b>         |                   | <b>6,200.00</b>   |                   |               |
| <b>(S\$)</b>                                     | 12,138.62         | 6,200.00          | 5,938.62          | 48.92         |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 849.70            | 434.00            | 415.70            | 48.92         |
| <b>Nett Amount (S\$)</b>                         | <b>12,988.32</b>  | <b>6,634.00</b>   | <b>6,354.32</b>   | <b>48.92</b>  |
| <b>+ Loss of Use (6.0 x S\$100.00/day) (S\$)</b> |                   | 600.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                    |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>7,241.45</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>               |                   | <b>7,200.00</b>   |                   |               |

### INSPECTION

Date of Assignment: 23/03/2020

Date Inspected: 23/03/2020 Inspected At:

MG Solution Pte Ltd (HQ)  
23 Kaki Bukit Avenue 4 #02-03B,  
VICOM Inspection Centre  
Singapore 415933

Estimated Period of Repair: 6.0 days

---

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                   |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 21 Jul 2020)                     |
| <b>Parts:</b>        | 143                                                                                                                                                                          | TOYOTA CAMRY 2.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                 |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SMS1891J)                                                                                                                                    |                                                                   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *BOOTLID                              | Distorted     | 1,122.50 FL | *1,122.50 FL |
| 2   | 1   |          | *BOOT LID LOGO                        | Necessary     | 90.00 FL    | *90.00 FL    |
| 3   | 1   |          | *BOOT LTD EMBLEM CAMRY                | Necessary     | 80.00 FL    | *80.00 FL    |
| 4   | 1   |          | *BOOT LTD EMBLEM HYBRID               | Necessary     | 80.00 FL    | *80.00 FL    |
| 5   | 1   |          | *BOOTLID LOCK                         | Damaged       | 320.00 FL   | *320.00 FL   |
| 6   | 2   |          | *BOOT LID LAMP                        | Cracked       | 760.00 FL   | *760.00 FL   |
| 7   | 1   |          | *BOOT LID DETECTOR                    | Cracked       | 250.00 FL   | *250.00 FL   |
| 8   | 1   |          | *BOOT LID NUMBER PLATE GARNISH        | Cracked       | 388.40 FL   | *388.40 FL   |
| 9   | 1   |          | *SET BOOT LID NUMBER PLATE LAMP       | Not Necessary | 180.00 FL   | *- FL        |
| 10  | 1   |          | *REAR BUMPER                          | Deformed      | 890.00 FL   | *890.00 FL   |
| 11  | 2   |          | *REAR BUMPER SIDE RETAINER            | Necessary     | 124.80 FL   | *124.80 FL   |
| 12  | 1   |          | *REAR BUMPER REINFORCEMENT            | Bent          | 455.80 FL   | *455.80 FL   |
| 13  | 2   |          | *REAR BUMPER OUTER BLADE              | Not Necessary | 180.00 FL   | *- FL        |
| 14  | 1   |          | *REAR BUMPER UNDER COVER              | Not Necessary | 320.00 FL   | *- FL        |
| 15  | 2   |          | *TAILLAMP                             | Cut           | 1,260.00 FL | *990.60 FL   |
| 16  | 2   |          | *TAILLAMP PANEL                       | Repair        | 480.00 FL   | *- FL        |
| 17  | 1   |          | *REAR END PANEL                       | Dented        | 677.50 FL   | *677.50 FL   |
| 18  | 1   |          | *REAR END PANEL TOP GARNISH           | Deformed      | 422.50 FL   | *387.00 FL   |
| 19  | 1   |          | *REAR TOOLS SPONGE                    | Cracked       | 410.00 FL   | *325.00 FL   |
| 20  | 1   |          | *REAR NUMBER PLATE                    | Not Necessary | 50.00 FS    | *- FS        |
| 21  | 1   |          | *BOOTLID STRIPE                       | Necessary     | 250.00 FS   | *150.00 FS   |
| 22  | 1   |          | *SET REAR BUMPER CLIPS                | Necessary     | 20.00 FS    | *20.00 FS    |
| 23  | 1   |          | *SET TAILLAMP CLIPS                   | Necessary     | 20.00 FS    | *20.00 FS    |
| 24  | 1   |          | *TAILLAMP PANEL SEALANT               | Not Necessary | 80.00 FS    | *- FS        |
| 25  | 1   |          | *REAR END PANEL INSULATION SEAL       | Necessary     | 200.00 FS   | *60.00 FS    |
| 26  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS | Necessary     | 20.00 FS    | *10.00 FS    |
| 27  | 1   |          | *REVERSE SENSOR                       | Damaged       | 220.00 FS   | *200.00 FS   |
| 28  | 1   |          | *CERAMIC COATING                      | Necessary     | 1,000.00 FS | *300.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>10,351.50</b> | <b>7,701.60</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>2,122.88</b>  | <b>1,735.40</b> |
| <b>Total Parts (\$\$)</b>                                  | <b>8,228.62</b>  | <b>5,966.20</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                    | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                                                                |          |                 |                 |
| 1                               | PANEL BEATING ,REMOVAL AND REPLACING PARTS                                                     | New      | 1,600.00        | 800.00          |
| 2                               | TO SPRAY PAINT AFFECTED AREA                                                                   | New      | 1,600.00        | 800.00          |
| 3                               | TUFF COAT                                                                                      | New      | 250.00          | 60.00           |
| 4                               | WIRING CHECK                                                                                   | New      | 80.00           | 30.00           |
| 5                               | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                                           | New      | 120.00          | 50.00           |
| 6                               | TRANFER BOOTLID MECHANISM                                                                      | New      | 80.00           | 60.00           |
| 7                               | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC | New      | 180.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                |          | <b>3,910.00</b> | <b>1,800.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >