



## Case Details

Case Reference Number : TAX/03/20/2055  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHC4639X

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-10899-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd  
 Accident Date and Time : 19/03/2020 03:00 AM  
 Vehicle Age(In Months) : 66

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

| SMRT Recommendation   |              |         |                 |                            |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|-----------------------|--------------|---------|-----------------|----------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                  | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| Standard              | Main         |         | 6505548         | BUMPER REAR                | 1   | 458.60                  | 458.60         | 25.00  | 343.95          | Replace         | 1                 | 343.95                   | Replace        | ✓ chn   |
| Standard              | Main         |         | 6505551         | BUMPER SEAL, RR RH         | 1   | 65.70                   | 65.70          | 25.00  | 49.28           | Replace         | 0                 | 0                        | Not Givr       | ✗ svc   |
| Standard              | Main         |         | 6505549         | BUMPER SIDE RETAINER RR/RH | 1   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace         | 0                 | 0                        | Not Givr       | ✗ svc   |
| Standard              | Main         |         | 6505618         | BUMPER LIP COVER RR/RH     | 1   | 118.10                  | 118.10         | 25.00  | 88.57           | Replace         | 0                 | 0                        | Not Givr       | ✗ svc   |
| Standard              | Main         |         | 6505522         | END PANEL                  | 1   | 602.10                  | 602.10         | 25.00  | 451.58          | Replace         | 0                 | 0                        | Check          | ✗ svc   |
| One Time Key In       | Main         |         |                 | BUMPER CLIPS               | 10  | 1.61                    | 16.10          | 25.00  | 12.08           | Replace         | 10                | 12.08                    | Replace        | ✓ Nec   |
| One Time Key In       | Main         |         |                 | PIXEL STICKER              | 2   | 60.00                   | 120.00         | 0.00   | 120.00          | Replace         | 2                 | 120.00                   | Replace        | ✓ Nec   |
| One Time Key In       | Main         |         |                 | SENSOR REVERSE             | 1   | 180.00                  | 180.00         | 0.00   | 180.00          | Replace         | 0                 | 0                        | Not Givr       | ✗ svc   |
| One Time Key In       | Main         |         |                 | SEALANT SIKAFLEX           | 1   | 37.00                   | 37.00          | 0.00   | 37.00           | Replace         | 0                 | 0                        | Not Givr       | ✗ svc   |
| One Time Key In       | Main         |         |                 | FENDER RR/RH               | 1   | 766.80                  | 766.80         | 25.00  | 575.10          | Replace         | 0                 | 0                        | Not Givr       | ✗ svc   |
| One Time Key In       | Main         |         |                 | STICKER DECAL SMRT         | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace         | 0                 | 0                        | Not Givr       | ✗ svc   |
| One Time Key In       | Main         |         |                 | STICKER DECAL 6555 8888    | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace         | 0                 | 0                        | Not Givr       | ✗ svc   |
| One Time Key In       | Main         |         |                 | TAIL LAMP RH               | 1   | 557.80                  | 557.80         | 10.00  | 502.02          | Replace         | 0                 | 0                        | Not Givr       | ✗ svc   |
| Total Spare Part Cost |              |         |                 |                            |     |                         |                |        | 2,460.08        |                 | Surveyor Total    |                          |                |         |
| Lump Sum Discount (%) |              |         |                 |                            |     |                         |                |        | 20.00           |                 | Lump Sum Dis (%)  |                          |                |         |
|                       |              |         |                 |                            |     |                         |                |        |                 |                 | 20                |                          |                |         |
| Final Spare Part Cost |              |         |                 |                            |     |                         |                |        | 1,968.06        |                 | Final Sur Total   |                          |                |         |
|                       |              |         |                 |                            |     |                         |                |        |                 |                 | 380.82            |                          |                |         |

**Labour's Cost Detail**

| S.No.         | Costing Type | Job Scope                 | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|---------------------------|-------------------------|-------------------------|---------|
| 1             | Main         | TO REPAIR RH REAR PORTION | 676.00                  | 200                     |         |
| <b>Total:</b> |              |                           | <b>676.00</b>           | <b>200.00</b>           |         |

**Spray Cost Detail**

| S.No.         | Costing Type | Job Scope                 | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|---------------------------|-------------------------|-------------------------|---------|
| 1             | Main         | TO RESPRAY REAR BUMPER    | 378.00                  | 200                     |         |
| 2             | Main         | TO RESPRAY REAR FENDER RH | 378.00                  | 0                       |         |
| 3             | Main         | TO RESPRAY REAR PANEL     | 180.00                  | 0                       |         |
| <b>Total:</b> |              |                           | <b>936.00</b>           | <b>200.00</b>           |         |

**Other Cost Detail**

| S.No.         | Costing Type | Job Scope                               | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|-----------------------------------------|-------------------------|-------------------------|---------|
| 1             | Main         | TO APPLY RUST-PROOFING ON AFFECTED AREA | 100.00                  | 0                       |         |
| 2             | Main         | TO TEST AND REFIX REVERSE SENSOR SYSTEM | 120.00                  | 20                      |         |
| 3             | Main         | TO CHECK WIRING AND SYSTEM FUNCTION     | 80.00                   | 0                       |         |
| 4             | Main         | TO REPLACE SUNDRY PARTS                 | 100.00                  | 0                       |         |
| 5             | Main         | TO WASH AND VACUUM                      | 60.00                   | 0                       |         |
| <b>Total:</b> |              |                                         | <b>460.00</b>           | <b>20.00</b>            |         |

**Summary**

|                         | Estimator Assesment(\$)             | Surveyor Assesment(\$)              |
|-------------------------|-------------------------------------|-------------------------------------|
| Total Spare Part Detail | 1,968.06                            | 380.82                              |
| Total Labour Cost       | 676.00                              | 200.00                              |
| Total Spray Painting    | 936.00                              | 200.00                              |
| Other                   | 460.00                              | 20.00                               |
| <b>Overall Total</b>    | <b>4,040.06</b>                     | <b>800.82</b>                       |
| Lump Sum Repair Option  | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| <b>Lump Sum Total</b>   | <b>4,050.00</b>                     | <b>800.00</b>                       |

|                          | Estimator Assessment(\$) | Surveyor Assessment(\$)                                                                                                                                         |
|--------------------------|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Surveyor Approved Amount |                          | 800.00                                                                                                                                                          |
| No of Repair Days*       | 5                        | 2 <i>2 days</i>                                                                                                                                                 |
| Remarks                  |                          | Lump sum Repair, After paint Photo.                                                                                                                             |
| Surveyor Name            |                          | Sun Pin (LKK)                                                                                                                                                   |
| Signature                |                          | <br><input type="button" value="Save"/> <input type="button" value="Clear"/> |
| Survey Date              | 20/03/2020               |                                                                                                                                                                 |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed with  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: