

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

29/4/20 11/172.00 Confirmed with Ray (Red \$2866, 20%)

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1) 29/04 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 3

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Report Format :

OD

Camp Cam / I.B.I. (\$ 11172

TOTAL

3/28/2020

Repairer Estimates


PROGRESSIVE
 CAR CARE PTE LTD

Progressive Car Care Pte Ltd

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

INSURER:

FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0320-7440
Policy No:	PNPV2018-00015701	Date of Loss:	21/03/2020
Vehicle Reg. No.:	SLJ6942Y	Driveable?	
Driver Age/Info:	32 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG NGEE LENG		
Driver:	NG HAN QIAN SAM		
Make/Model:	TOYOTA WISH, 1.8 (A)	Vehicle Reg. Date:	21/12/2016
Vehicle Colour:	GOLD	Chassis No:	NTDGG20W10J006197
Engine No:	2ZR1866803		
Odometer:	18703 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336		
Remarks:	VEHICLE IS IN WORKSHOP		
Present Location:	PROGRESSIVE CAR CARE PTE LTD (HQ)		

Not Authorized
done
take photo before painting,
6 hrs @ 750

10 days.
1/p @ 11172.00

COST OF CLAIMS	Amount
Parts	6,433.00
Miscellaneous Items	235.00
Labour	1,840.00
Paintwork Labour	1,600.00
Towing	0.00
Gross Total (S\$)	10,108.00
+ GST 7.00% (S\$)	707.56
Nett Amount (S\$)	10,815.56

This claim is handled by: NG PEI WEN

LKK Auto Consultants hence notify
 the Repairer of the following:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 24 Mar 2020)

Parts: M1-MPV

TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SLJ6942Y/24/03/2020 09:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BUMPER <i>Dis</i>		0.00	*200.00 F ✓
2	2	NA	*FRONT BUMPER SIDE HOLDER - LH; RH <i>n/s cna 1pc</i>	40	0.00	*80.00 F 1pc ✓
3	10	NA	*FRONT BUMPER CLIPS <i>noe</i>		0.00	*15.00 F ✓
4	2	NA	*FRONT BUMPER SIDE GRILLE - LH; RH <i>11 X</i>		0.00	*70.00 F X
5	2	NA	*FRONT BUMPER ENGINE UNDERCOVER <i>Turn</i>		0.00	*90.00 F ✓
6	10	NA	*FRONT BUMPER ENGINE UNDERCOVER CLIPS <i>11 X</i>		0.00	*15.00 F X
7	2	NA	*FRONT FOGLAMP - LH; RH <i>n/s bro 1pc</i>	95	0.00	*190.00 F 1pc ✓
8	2	NA	*FRONT FOG LAMP COVER - LH; RH <i>n/s cna 1pc</i>	50	0.00	*90.00 F 1pc ✓
9	1	NA	*FRONT GRILLE ASSY WITH OUTER CHROME (UPPER) <i>cra</i>		0.00	*160.00 F ✓
10	2	NA	*HEAD LAMP - LH; RH <i>n/s bro 0.5 mth cna</i>		0.00	*720.00 F ✓
11	1	NA	*FRONT SUPPORT PANEL ASSY <i>half turn</i>		0.00	*450.00 F ✓
12	1	NA	*FRONT SUPPORT PANEL TOP GARNISH <i>Dis</i>	60	0.00	*70.00 F ✓
13	10	NA	*FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>noe</i>		0.00	*18.00 F ✓
14	2	NA	*FRONT FENDER - LH; RH <i>Turn</i>		0.00	*540.00 F ✓
15	2	NA	*FRONT FENDER COWLING - LH; RH <i>Turn</i>		0.00	*150.00 F ✓
16	20	NA	*FRONT FENDER COWLING CLIPS - LH; RH <i>11 X</i>		0.00	*30.00 F X
17	1	NA	*FRONT BONNET <i>Turn</i>		0.00	*330.00 F ✓
18	2	NA	*FRONT BONNET HINGE - LH; RH <i>Turn</i>		0.00	*70.00 F ✓
19	1	NA	*FRONT INSULATOR <i>Turn</i>		0.00	*150.00 F ✓
20	10	NA	*FRONT INSULATOR CLIP <i>noe</i>		0.00	*18.00 F ✓
21	1	NA	*FRONT REINFORCEMENT <i>noe</i>		0.00	*140.00 F ✓
22	1	NA	*FRONT FOAM <i>Turn</i>		0.00	*60.00 F ✓
23	2	NA	*FRONT FENDER QUARTER WINDOW MOULDING - LH; RH <i>11 X</i>		0.00	*260.00 F X
24	2	NA	*FRONT FENDER INNER UPPER GARNISH WITH SPONGE - LH; RH <i>11 X</i>		0.00	*56.00 F X
25	1	NA	*WIPER GARNISH RUBBER (LONG) <i>11 X</i>		0.00	*70.00 F X
26	10	NA	*WIPER GARNISH CLIPS <i>11 X</i>		0.00	*18.00 F X
27	1	NA	*AIR CLEANER BOX <i>noe</i>		0.00	*320.00 F ✓
28	1	NA	*BATTERY UPPER BRACKET <i>noe</i>		0.00	*28.00 F ✓
29	1	NA	*FUEL BOX COVER SET - TOP <i>noe</i>		0.00	*50.00 F X
30	1	NA	*AIRCON CONDENSER ASSY <i>Turn</i>		0.00	*360.00 F ✓
31	1	NA	*RADIATOR ASSY <i>Turn</i>		0.00	*480.00 F ✓
32	2	NA	*RADIATOR FAN MOTOR <i>Turn</i>		0.00	*400.00 F ✓
33	2	NA	*RADIATOR FAN <i>Turn</i>	100	0.00	*150.00 F X
34	1	NA	*RADIATOR FAN SHROUD <i>Turn</i>		0.00	*110.00 F ✓
35	1	NA	*WIPER TANK ASSY <i>Turn</i>		0.00	*50.00 F ✓
36	1	NA	*RADIATOR SPARE TANK <i>Turn</i>		0.00	*70.00 F ✓
37	1	NA	*WIPER GARNISH; SIDE - LH; RH <i>noe</i>	90	0.00	*200.00 F ✓
38	1	NA	*RADIATOR TOP COVER <i>noe</i>		0.00	*50.00 F X
39	1	NA	*FUSE BOX - LOWER <i>cra</i>		0.00	*75.00 F ✓

F=Franchise part.

Total Parts (S\$)

6,433.00

Progressive Car Care Pte Ltd/SLJ6942Y/24/03/2020 09:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS 7052

p-5339
s-1713
s.w-180
L-2820
SL-1120
11172

3/24/2020

Repairer Estimates

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	BATTERY	180.00
2	1	COOLANT	20.00
3	1	FRONT NUMBER PLATE WITH CASING	35.00
Sub Total (\$\$)			235.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,600.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS FRONT WHEEL; REMOVE; REPLACE ACCIDENT PARTS	New	1,540.00
3	TO CHECK WIRING	New	20.00
4	TO RESET CHECK LIGHT	New	60.00
5	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00
6	TO REMOVE; REFIX FENDER QUARTER GLASS - LH RH	New	120.00
Gross Labour Cost (\$\$)			3,440.00

Progressive Car Care Pte Ltd/SLJ6942Y/24/03/2020 09:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK OUT DENTS ON FRT BOTH WHEEL HOUSE, CHASSIS , LH FRT CHASSIS SIDE PANEL, INNER , OUTER AND LH FRT FENDER SIDE BRACKET. NOT STK	New 220	1,100.00
2	TO REMOVE, REFIX FRT ENGINE, REPLACE ENGINE MTGS	New 380	450.00
3	TO 4 WHEEL ALIGNMENT	New	70.00 ✓
4	TO REMOVE, REFIX FRT UNDER CARRIAGE, REMOVE, REFIX DRIVE SHARFT, AIR CLEANER BOX, AIR CLEANER DUCT 1 , 2, AND RELATED PARTS.	New 350	500.00
5	TO REPAIR WIRE HARNESS	New	100.00 ✓
Gross Labour Cost (\$\$)			2,220.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Apr 2020)
 Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLJ6942Y)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET LOCK <i>Bent/tw</i>	50	0.00	✓ *90.00 F ✓
2	1		*BONNET CABLE <i>one</i>		0.00	✓ *30.00 F ✓
3	1		*FRT BUMPER UNDER LOWER COVER <i>Torn</i>		0.00	✓ *70.00 F ✓
4	1		*BRACE PANEL <i>tw</i>		0.00	✓ *45.00 F ✓
5	1		*BONNET STAND C BUSH <i>Torn</i>		0.00	✓ *5.00 F ✓
6	1		*BATTERY LOWER TRAY <i>one</i>		0.00	✓ *35.00 F ✓
7	1		*ENGINE MTG - RR <i>Torn</i>		0.00	✓ *75.00 F ✓
8	1		*ENGINE MTG - FRT <i>Torn</i>		0.00	✓ *75.00 F ✓
9	1		*ENGINE MTG BRACKET - FRT <i>tw</i>		0.00	✓ *50.00 F ✓
10	1		*ENGINE MTG - LH <i>Torn</i>		0.00	✓ *90.00 F ✓
11	1		*ENGINE MTG - RH <i>Torn</i>		0.00	✓ *125.00 F ✓
12	1		*FRT CROSSMEMBER <i>tw</i>		0.00	✓ *170.00 F ✓
13	1		*RELAY BLOCK COVER <i>one</i>		0.00	✓ *18.00 F ✓
14	1		*AIR CLEANER DUCT NO 1 <i>one</i>		0.00	✓ *55.00 F ✓
15	1		*AIR CLEANER DUCT NO 2 <i>one</i>		0.00	✓ *65.00 F ✓
16	1		*FUSE BOX - CENTRE <i>one</i>		0.00	✓ *70.00 F ✓
17	1		*FUSE BOX - TOP <i>one</i>		0.00	✓ *50.00 F ✓
18	1		*RADIATOR JOINT HOSE <i>tw</i>		0.00	✓ *25.00 F ✓
19	1		*WIPER GARNISH <i>one</i>		0.00	✓ *230.00 F ✓
20	1		*TOYOTA AUTO OIL <i>one</i>		0.00	✓ *42.00 F ✓ 45 ✓
21	1		*FRT BUMPER REIN FRAME BRACKET - L <i>one</i>		0.00	✓ *35.00 F ✓
22	1		*FRT BUMPER REIN FRAME BRACKET - R <i>Bent</i>		0.00	✓ *35.00 F ✓
23	1		*FRT BUMPER LOWER GRILLE - L <i>Torn</i>		0.00	✓ *35.00 F ✓
24	1		*FRT BUMPER LOWER GRILLE, SIDE PROT - L <i>Torn</i>		0.00	✓ *35.00 F ✓
25	1		*BONNET LOGO <i>one</i>		0.00	✓ *30.00 F ✓
26	1		*CONDENSER SIDE GARNISH - L <i>Torn</i>		0.00	✓ *45.00 F ✓

F=Franchise part.

Total Parts (S\$) 1,590.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

1593

Supp 2713.00
 Parts 5459.00
 SN 180.00
 LHS 2940.00
 11292.00
 11172

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Apr 2020)
Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Progressive Car Care Pte Ltd/SLJ6942Y/27/04/2020 10:03
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*DISCHARGE HOSE	0.00	0.00	*120.00 F
F=Franchise part.						
Total Parts (S\$)						120.00

Progressive Car Care Pte Ltd/SLJ6942Y/27/04/2020 10:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS