Estimates on Miscellaneous Items There are no new miscellaneous items selected.

Estimat	20	On	10	hai	110
	162	OH	La	DOL	41

No	Particulars	Lab.Type		Amount	
Lab	TO KNOCK OUT DENTS ON EDT DOTH WILEEL HOURS OUASSIS HIJEDT CHASSIS SIDE	New	120	1,100.00	
	TO KNOCK OUT DENTS ON FRT BOTH WHEEL HOUSE, CHASSIS , LH FRT CHASSIS SIDE PANEL, INNER , OUTER AND LH FRT FENDER SIDE BRACKET. NOT STK	New		1,100.00	
2	TO REMOVE, REFIX FRT ENGINE, REPLACE ENGINE MTGS	New	380	450.00	
3	TO 4 WHEEL ALIGNMENT	New		70.00	
	TO REMOVE, REFIX FRT UNDER CARRIAGE, REMOVE, REFIX DRIVE SHARFT, AIR CLEANER BOX, AIR CLEANER DUCT 1, 2, AND RELATED PARTS.	New	350	500.00	
5	TO REPAIR WIRE HARNESS	New		100.00	
	Gross Labo	ur Cost (S	5)	2,220.00	

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS < END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Apr 2020)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLJ6942Y)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page Validity:

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty Part No.	Particulars		%Disc	%Depr	Amount
1	1	*BONNET LOCK BUTTON	50	0.00	0.00	✓ *50.00F/
2	1	*BONNET CABLE (AL		0.00	0.00	✓ *30.00 F
3	1	*FRT BUMPER UNDER LOWER COVER 7011		0.00	0.00	∨ *70.00F
4	1	*BRACE PANEL 7~/		0.00	0.00	∨ *45.00 F
5	1	*BONNET STAND C BUSH 7, CA		0.00	0.00	✓ *5.00 F
6	1	*BATTERY LOWER TRAY (1)		0.00	0.00	✓ *35.00 F
7	1	*ENGINE MTG - RR ZCA		0.00	0.00	✓ *75.00 F
8	1	*ENGINE MTG - FRT 70 CA		0.00	0.00	✓ *75.00 F
9	1	*ENGINE MTG BRACKET - FRT 1W/		0.00	0.00	✓ *50.00F
10	1	*ENGINE MTG - LH 70 co		0.00	0.00	▼ *90.00 F
11	1	*ENGINE MTG - RH 70.0		0.00	0.00	✓*125.00 F
12	1	*FRT CROSSMEMBER 7wl		0.00	0.00	✓ *170.00 F
13	1	*RELAY BLOCK COVER COU		0.00	0.00	*18.00F
14	1	*AIR CLEANER DUCT NO 1 COA		0.00	0.00	V *55.00F
15	1	*AIR CLEANER DUCT NO 2 C/L		0.00	0.00	✓ *65.00 F
16	1	*FUSE BOX - CENTRE (~2		0.00	0.00	✓*70.00F
17	1	*FUSE BOX - TOP DU		0.00	0.00	¥ *50.00 F
18	1	*RADIATOR JOINT HOSE TWI		0.00	0.00	✓ *25.00 F
19	1	*WIPER GARNISH 715		0.00	0.00	✓ *230.00 F
20	1	*TOYOTA AUTO OIL 12		0.00	0.00	V 12.00 F 45
21	1	*FRT BUMPER REIN FRAME BRACKET - L		0.00	0.00	✓ *35.00 F
22	1	*FRT BUMPER REIN FRAME BRACKET - R BENT		0.00	0.00	✓ *35.00 F
23	1	*FRT BUMPER LOWER GRILLE - L 70-1		0.00	0.00	✓ *35.00 F
24	1	*FRT BUMPER LOWER GRILLE, SIDE PROT - L 70-0		0.00	0.00	✓ *35.00 F
25	1	*BONNET LOGO MC		0.00	0.00	✓ *30.00 F
26	1	*CONDENSER SIDE GARNISH - L 7010		0.00	0.00	√*45.00F
F=Fr	anchise part.		Total Parts (S\$)			1,590.00

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

REPAIR D	ETAILS			
Reference	ce		and the same	
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2020)		
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue: Merimen Singa	apore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:		r Care Pte Ltd/SLJ6942Y/27/04/2020 10:03		Sary Pile Line S (5-12) 17 (-2) 17 (-5) 20
Validity:	These estimates on the last estim	are valid only if they contain the print code (above) on all ate page	l estimate pages, running page	numbers with the END OF ESTIMATES marker
Further Info:	Items/values not	in reference catalogue are prefixed with an asterisk *.		

Estimates on Parts No. Qty Part No.	Particulars		%Disc	%Depr			Amount
1 1 F=Franchise part	*DISCHARGE HOSE		0.00	0.00	tui/	Sel	*120.00 F
r-rianchise part.		Total Parts (S\$)			1		120.00