Adjuster Report Page 1 of 3

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20004425/R1TD3E2

Date: 23/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700079349

Claimant Vehicle No: SJY2411J Insured Vehicle No: SLT9511K

Date of Loss: 16/03/2020 Nature of Claim: TP Claim No: 2437621456SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJY2411J

Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 1NZY100540

Reg. Date: 12/08/2010 (Man. Year: 2010) Chassis No: MR053HY9305168219

Colour: Grey Odometer: 187973 km

Engine Capacity: 1497 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 24/03/2020

Date Inspected: 24/03/2020 Inspected At: Fix Auto Pte Ltd (HQ)

5 SOON LEE STREET, #01-61 PIONEER

**POINT** 

Singapore 627607

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER BRACKET	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
5	2		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
6	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
7	1		*REAR END PANEL	Bent	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
11	1		*BOOTLID	Bent	0.00 F	*- F
12	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID LOCK	Bent	0.00 F	*- F
14	1		*BOOTLID RUBBER	Necessary	0.00 F	*- F
15	2		*BOOTLID HINGE	Bent	0.00 F	*- F
16	1		*SPARE TYRE BOARD	Deformed	0.00 F	*- F
17	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
18	1		*REAR EXHAUST CHROME PIPE	Scratched	0.00 F	*- F
19	1		*REAR LH FENDER	Repair	0.00 F	*- F
20	1		*BOOT COMPARTMENT SPONGE TRAY	Dented	0.00 F	*- F
F=Fra	anchise	part.				
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >