

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20004427/UKA3Q2

**Date:** 29/12/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994098

**Claimant**  
**Vehicle No :** GBJ8136M **Insured Vehicle No :** SLG7008D

Date of Loss: 21/03/2020 Nature of Claim: TP Claim No: 7563448465SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBJ8136M</b>		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KD2860254
Reg. Date:	30/08/2019 (Man. Year: 2019)	Chassis No:	JTFAT35Y10K213708
Colour:	Silver	Odometer:	12466 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,340.00	2,635.92	2,704.08	50.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,520.00	930.00	37.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,790.00</b>	<b>4,155.92</b>	<b>3,634.08</b>	<b>46.65</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,300.00</b>		
<b>Nett Amount (\$\$)</b>	<b>7,790.00</b>	<b>3,300.00</b>	<b>4,490.00</b>	<b>57.64</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (\$\$)</b>		400.00		
<b>+ Doc/Search Fee (\$\$)</b>		36.45		
<b>Nett Liability (\$\$)</b>		<b>3,736.45</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>3,700.00</b>		

### INSPECTION

Date of Assignment: 24/03/2020

Date Inspected: 24/03/2020 Inspected At:

Zoom Autowerks Pte Ltd (HQ)  
130 Bedok Reservoir Road, Eunos  
Spring, #08-1339  
Singapore 470130

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented / Bent	1,945.20 FL	*1,465.60 FL
2	2		*REAR TAILGATE LATCH	Not Necessary	390.00 FL	*- FL
3	1		*REAR TAILGATE SIDE MEMBER WITH RUBBER	N/S Bent	536.00 FL	*179.00 FL
4	2		*REAR TAILGATE HINGES	Not Necessary	136.00 FL	*- FL
5	1		*REAR TAILGATE LOWER MEMBER	Bent	749.40 FL	*749.40 FL
6	1		*TAILLAMPS	N/S Cracked	750.00 FL	*339.70 FL
7	1		*TAILLAMPS BRACKET	N/S Bent	238.40 FL	*119.20 FL
8	1		*REAR NUMBER PLATE BRACKET	Bent	155.00 FL	*155.00 FL
9	1		*REAR NUMBER PLATE LAMP	Not Necessary	175.00 FL	*- FL
10	1		*REAR TYRE CARRIER	Not Necessary	385.00 FL	*- FL
11	1		*REAR TAILGATE STICKER (TOYOTA)	Necessary	175.00 FS	*110.00 FS
12	1		*REAR DYNA STICKER	Necessary	70.00 FS	*45.00 FS
13	1		*70KM/H STICKER	Necessary	35.00 FS	*10.00 FS
14	1		*REAR SIDE GATE ADVERTISEMENT STICKER	Not fitted	650.00 FS	*- FS
15	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
16	1		*REAR NUMBER PLATE	Bent	35.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>6,705.00</b>	<b>3,387.90</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,365.00	751.98
<b>Total Parts (\$)</b>	<b>5,340.00</b>	<b>2,635.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,200.00	850.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,000.00	600.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO RUST PROOF AFFECTED AREAS	New	200.00	50.00
<b>Gross Labour Cost (\$)</b>			<b>2,450.00</b>	<b>1,520.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**