

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG20004429/AQF3E2

Date: 05/11/2021

REFERENCE

Insured/Claimant:	SANDEEP HOODA	Policy No:	1900094067		
Date of Loss:	20/03/2020	Nature of Claim:	OD	Claim No:	4345995480SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML216C		
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	CVK077057
Reg. Date:	30/04/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF42KA040554
Colour:	Black	Odometer:	7512 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	46,571.00	13,318.88	33,252.12	71.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,792.00	10,552.00	4,240.00	28.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	61,363.00	23,870.88	37,492.12	61.10
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	59,763.00	22,270.88	37,492.12	62.73
+ GST 7.00/7.00% (S\$)	4,183.41	1,558.96	2,624.45	62.73
Nett Amount (S\$)	63,946.41	23,829.84	40,116.57	62.73

INSPECTION

Date of Assignment:	24/03/2020		
Date Inspected:	24/03/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,068.00 FS	*1,654.40 FS
2	2		*FRONT BUMPER SECURING STRIP	Distorted	67.00 FS	*52.96 FS
3	1		*FRONT BUMPER GRILLE CENTRE	Cracked	185.00 FS	*147.60 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Torn	198.00 FS	*158.00 FS
5	2		*FRONT BUMPER AIR GUIDE - LH/RH	Not Necessary	118.00 FS	*- FS
6	1		*RADIATOR GRILLE	Cracked	1,254.00 FS	*1,003.20 FS
7	2		*FRONT BUMPER AIR GUIDE GRILLE - LH/RH	Not Necessary	254.00 FS	*- FS
8	1		*FRONT BUMPER CARRIER	Bent	757.00 FS	*605.20 FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	117.00 FS	*93.60 FS
10	1		*FRONT BUMPER COVER	Cracked	120.00 FS	*96.00 FS
11	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS
12	1		*AIRCON STICKER	Not Necessary	7.00 FS	*- FS
13	1		*LOCK CARRIER BRACKET	Not Necessary	129.00 FS	*- FS
14	2		*FRONT BUMPER SUPPORT - LH/RH	Not Necessary	54.00 FS	*- FS
15	1		*HORN - LH HIGH TONE	Not Necessary	38.00 FS	*- FS
16	1		*HORN - RH LOW TONE	Not Necessary	270.00 FS	*- FS
17	2		*SPRING SHACKLE - LH/RH	Not Necessary	54.00 FS	*- FS
18	2		*FRONT PARKING AID SENSOR - INNER/OUTER	Not Necessary	0.00 FS	*- FS
19	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
20	1		*BONNET	Dented	2,634.00 FS	*2,107.20 FS
21	1		*BONNET ATTACHMENT PARTS	Not Necessary	388.00 FS	*- FS
22	2		*BONNET LID HINGE - LH/RH	Not Necessary	574.00 FS	*- FS
23	1		*BONNET IMPACT PROTECTION - CENTRE	Necessary	26.00 FS	*20.80 FS
24	2		*BONNET IMPACT PROTECTION - LH/RH	Necessary	52.00 FS	*41.12 FS
25	2		*BONNET GAS FILLED STRUT	Not Necessary	224.00 FS	*- FS
26	2		*BONNET STRIKER - LH/RH	Not Necessary	94.00 FS	*- FS
27	2		*BONNET LID LOCK	Not Necessary	403.00 FS	*- FS
28	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	54.00 FS	*- FS
29	1		*BONNET BOWDEN CABLE	Not Necessary	54.00 FS	*- FS
30	1		*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
31	1		*BONNET SOUND ABSORBER	Not Necessary	323.00 FS	*- FS
32	2		*LED HEADLIGHT - LH/RH	Not Necessary	14,642.00 FS	*- FS
33	2		*LIFT CYLINDER - LH/RH	Not Necessary	396.00 FS	*- FS
34	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	88.00 FS	*- FS
35	1		*LOCK CARRIER	Cracked	956.00 FS	*764.40 FS
36	2		*COLLANT REGULATOR SUPPORT	Not Necessary	71.00 FS	*- FS
37	1		*AIRCON CONDENSER	Not Necessary	586.00 FS	*- FS
38	1		*CHARGE AIR COOLER	Distorted	552.00 FS	*441.20 FS
39	1		*CHARGE AIR COOLER PRESSURE HOSE - RH	Not Necessary	336.00 FS	*- FS
40	1		*CHARGE AIR COOLER PRESSURE PIPE	Not Necessary	402.00 FS	*- FS
41	1		*RADIATOR	Dented	766.00 FS	*612.40 FS
42	1		*READY MIX COOLANT	Necessary	169.00 FS	*134.72 FS
43	1		*RADIATOR FAN RING	Not Necessary	240.00 FS	*- FS
44	1		*RADIATOR FAN	Not Necessary	1,877.00 FS	*- FS
45	1		*RADIATOR AIR GUIDE - LH/RH	O/S Torn	54.00 FS	*21.04 FS
46	2		*RADIATOR AIR GUIDE - LH/RH	Not Necessary	24.00 FS	*- FS
47	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	15.00 FS	*- FS
48	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	21.00 FS	*- FS
49	1		*AIR INTAKE AIR DUCT - RH	Not Necessary	21.00 FS	*- FS
50	1		*AIR INTAKE AIR FILTER	Not Necessary	362.00 FS	*- FS
51	1		*AIR INTAKE AIR GUIDE	Not Necessary	50.00 FS	*- FS
52	1		*AIR INTAKE AIR MASS METRE	Not Necessary	546.00 FS	*- FS
53	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	36.00 FS	*- FS
54	1		*NOISE INSULATION	Torn	537.00 FS	*429.60 FS
55	1		*FRONT ALUMINIUM RIM - RH	Cut	652.00 FS	*521.20 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SUPPORT FRAME	Not Necessary	3,096.00 FS	*- FS
57	1		*FRONT WISHBONE LINK - RH	Bent	507.00 FS	*405.20 FS
58	1		*FRONT SUSPENSION GUIDE - RH	Bent	887.00 FS	*709.60 FS
59	1		*UPPER CONTROL ARM - RH	Bent	480.00 FS	*384.00 FS
60	1		*REAR UPPER CONTROL ARM - RH UPPER	Bent	480.00 FS	*384.00 FS
61	1		*WHEEL BEARING HOUSING - RH	Damaged	912.00 FS	*729.60 FS
62	1		*SWIVEL JOINT	Bent	182.00 FS	*145.60 FS
63	1		*WHEEL HUB	Damaged	460.00 FS	*368.00 FS
64	1		*SUSPENSION FORKS - RH	Not Necessary	249.00 FS	*- FS
65	2		*COUPLING ROD	Not Necessary	0.00 FS	*- FS
66	1		*DRIVE SHAFT	Not Necessary	2,498.00 FS	*- FS
67	1		*GAS SHOCK ABSORBER	Not Necessary	284.00 FS	*- FS
68	1		*TRACK ROD	Not Necessary	93.00 FS	*- FS
69	1		*STEERING GEAR GREASE	Not Necessary	41.00 FS	*- FS
70	1		*TIE ROD END	Bent	186.00 FS	*148.40 FS
71	1		*DOUBLE ANGLE BALL BEARING	Damaged	237.00 FS	*189.60 FS
72	1		*REAR NOISE INSULATION	Torn	371.00 FS	*296.40 FS
73	1		*CENTRE UNDERBODY TRIM AIR GUIDE - RH	Not Necessary	0.00 FS	*- FS
74	1		*FRONT UNDERBODY TRIM - LH	Not Necessary	40.00 FS	*- FS
75	1		*UNDERBODY TRIM	Torn	305.00 FS	*243.60 FS
76	1		*REAR UNDERBODY TRIM - RH	Torn	125.00 FS	*99.60 FS
77	1		*FUEL TANK RIM	Torn	59.00 FS	*46.56 FS
78	1		*REAR SUSPENSION COVER STONE CHIP GUARD - RH	Cut	42.00 FS	*33.20 FS
79	1		*FRONT TYRE - RH (NPA)	Punctured	0.00 FS	*- FS
80	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
81	1		*SUNDRIES	Necessary	400.00 FS	*105.60 FS
82	1		*WHEEL SPOILER RH	Torn	69.00 FS	*55.04 FS
83	1		*FRONT BUMPER FIXING PARTS	Not Necessary	553.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 46,571.00 13,318.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCOND CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	New	1,200.00	1,200.00
3	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	New	350.00	300.00
4	TO RENEW RHS WHEEL SUSPENSION ASSY WITH SUBFRAME. TO INSPECT FOR FURTHER DAMAGES.	New	2,400.00	2,400.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO REPAIR RHS FRONT FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	5,250.00	2,750.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES, RHS FRONT DOOR AND RHS SILL PANEL.	New	4,400.00	2,750.00
7	TO RENEW RHS FRONT RIM AND TYRE. TO CARRY OUT PRE-WHEEL ALIGNMENT AND POST WHEEL ALIGNMENT.	New	520.00	480.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			14,792.00	10,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >