

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 9931B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR O/S DOOR ASSY	BENT	1,218.50	1,084.90
1	REAR O/S DOOR PROTECTOR	WARPED	376.10	322.50
1	REAR O/S DOOR FRAME BLACK STICKER	NECESSARY	134.50	134.50
1	REAR O/S DOOR INNER TRIM BOARD	SERVICEABLE	455.70	-
1	REAR O/S DOOR GLASS REGULATOR	DISTORTED	401.70	243.20
1	REAR O/S DOOR GLASS REGULATOR MOTOR	JAMMED	441.50	441.50
1	REAR O/S DOOR INNER LOCK	TO REPAIR SEE LABOUR	305.10	-
1	REAR O/S DOOR RUBBER	CUT	185.90	185.90
1	FRONT OS/ DOOR PROTECTOR	SERVICEABLE	397.10	-
1	REAR O/S FENDER ARCH GARNISH	DENTED	255.10	255.10
1	REAR O/S FENDER INNERSHIELD	SERVICEABLE	185.10	-
1	REAR O/S TAIL-LAMP ASSY	CUT	683.10	521.90
1	REAR BUMPER	CRACKED	985.10	948.60
1	REAR LOWER BUMPER	DENTED / CUT	685.70	580.00
1	O/S LOCKER PANEL GARNISH	CUT	655.70	546.70
	LESS 25% DISCOUNT		-1,841.48	-1,316.20
			5,524.42	3,948.60
	SPECIAL NETT ITEMS			
20	CLIP @ \$2.50 (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	LABOUR			
	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF REAR O/S DOOR INNER LOCK.		1,000.00	700.00
	TO PUTTY AND SPRAY PAINT.		1,000.00	600.00
	CHECK & RECONNECT WIRING.		45.00	20.00
	TO RESPRAY ANTI-RUST PROOFING TREATMENT.		120.00	30.00
	REMOVE / REFIT REAR TAIL-GATE MECHANISM TO NEW DOOR.		150.00	60.00
			2,315.00	1,410.00

Report Ref No. CS/LPC20004430/Ktd3s2



Page No.:2 of 2

GRAND TOTAL	7,889.42	5,408.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		4,300.00

Report Ref No. CS/LPC20004430/Ktd3s2

KONG SENG CHEONG

Licensed Appraiser