

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial PK 2 Singapore 569541
Tel : 64817221

Fax : 64816131

H. L Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 189556

Vehicle No : SLU 9931 B
Make/Model : Toyota C-HR
Year : 2017

*Not Authorised
21 Rep & 300k
Repair After Paint
5 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate cost of repair

1 pc	Rear o/s door assy	1084.90	\$1,218.50	✓
1 pc	Rear o/s door protector	322.50	\$376.10	✓
1 pc	Rear o/s door frame black sticker		\$134.50	✓
1 pc	Rear o/s door inner trim board		\$455.70	X
1 pc	Rear o/s door glass regulator	243.20	\$401.70	✓
1 pc	Rear o/s door glass regulator motor		\$441.50	✓
1 pc	Rear o/s door inner lock		\$305.10	X
1 pc	Rear o/s door rubber		\$185.90	✓
1 pc	Front o/s door protector		\$397.10	X
1 pc	Rear o/s fender arch garnish		\$255.10	✓
1 pc	Rear o/s fender innershield		\$185.10	X
1 pc	Rear o/s tail-lamp assy	521.90	\$683.10	✓
1 pc	Rear bumper	948.60	\$985.10	✓
1 pc	Rear lower bumper	580	\$685.70	✓
1 pc	O/S locker panel garnish	546.70	\$655.70	✓
			\$7,365.90	
			Less 25 %	\$1,841.48
				\$5,524.42

S Nett

20 pcs	Clip	\$2.50	\$50.00	✓
--------	------	--------	---------	---

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,000.00 *Foot*

To putty and spray paint

\$1,000.00 *600k*

Check & reconnect wiring.

\$45.00 *201*

balance c/f \$7,619.42

SLU 9931 B

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey, on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental work to be resurveyed and is subject to the Insurance Company

Acknowledged
Signature:
Date:

balance b/f \$7,619.42

Labour Charges

To respray anti-rust proofing treatment

\$120.00 301

Remove/refit rear tail-gate mechanism to new door.

\$150.00 601

Total \$7,889.42

ASS. REC. BY:

REF: LPC / CS / LPC 20004430 / Ktd3Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Lian Itar

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 9931B Yr Regn: 12, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or AMake: Toy CHR c.c. 1797Colour: M. Gray A/C: Insured / Std / NI / NASp. Reading: 125751 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZYX10 2082805Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD / RIM orTyre Size: F: 215/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO orFront 7 mm Rear 7 mmR/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 20/3/20 D.O.I. 24/3/2020Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

cls Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2/4 LI Rep @ 4300. email & confirm (Red: 3529.42: 45%)

Date/Time, File Pass to?

☐ : Prell. Report1) 13/4 typist☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$) 4300