

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004433/UHA3Q2

Date: 26/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993925

Claimant
Vehicle No : SLQ4229A **Insured Vehicle No :** SLC1863L

Date of Loss: 20/03/2020 Nature of Claim: TP Claim No: 0310748008SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ4229A		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	HIDDEN
Reg. Date:	01/07/2017 (Man. Year: 2017)	Chassis No:	MMBSTA13AHH004726
Colour:	White	Odometer:	98740 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 7 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,562.60	837.20	1,725.40	67.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,020.00	1,510.00	59.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,092.60	1,857.20	3,235.40	63.53
+ GST 7.00/7.00% (\$\$)	356.48	130.00	226.48	63.53
Nett Amount (\$\$)	5,449.08	1,987.20	3,461.88	63.53
+ Car Rental (3.0 x S\$100.00/day) (\$\$)		300.00		
Nett Liability (\$\$)		2,287.20		
Global Sum Settlement (\$\$)		2,200.00		

INSPECTION

Date of Assignment: 24/03/2020

Date Inspected: 24/03/2020 Inspected At:

SM SPRAY PAINTING PTE LTD
NO. 25 KAKI BUKIT ROAD 4
#08-30 SYNERGY @ KAKI BUKIT
SINGAPORE 417800

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	708.00 FL	*708.00 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	26.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	26.00 FL	*- FL
4	1		*REAR BUMPER REFLECTOR RH	Not Necessary	20.00 FL	*- FL
5	1		*REAR END PANEL	Repair	402.00 FL	*- FL
6	1		*REAR END PANEL TOP GARNISH	Not Necessary	62.00 FL	*- FL
7	1		*BOOTLID	Repair	828.00 FL	*- FL
8	1		*TAILGATE LOCK	Not Necessary	206.00 FL	*- FL
9	1		*TAILGATE EMBLEM	Serviceable	48.00 FL	*- FL
10	1		*TAILGATE ATTRAGE EMBLEM	Serviceable	38.00 FL	*- FL
11	1		*SET REAR BUMPER SENSOR	Shorted	400.00 FS	*200.00 FS
12	1		*REAR NUMBER PLATE	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,799.00	908.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	236.40	70.80
Total Parts (\$\$)	2,562.60	837.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT ,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
2	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	80.00	50.00
3	TO TRANSFER REAR TAILGATE	New	80.00	0.00
4	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS REPLACE DAMAGED PARTS	New	50.00	20.00
5	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	900.00	350.00
6	TO DO UP INTERIOR CLEANING AND CHEMICAL WASH	New	150.00	0.00
7	TO CARRY -OUT BODY CAVITY PRESERVATION	New	120.00	0.00
8	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	100.00	0.00
9	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	900.00	600.00
Gross Labour Cost (\$\$)			2,530.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >