## SM SPRAY PAINTING

## ON BEHALF OF OWNER:

Policy Particulars: - THIRD PARTY CLAIM

Insured veh.

SLQ4229A

Excess.

NIL

Policy No.

5113274271

Coverage.

Claiming Against.

Insured Under.

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Vehicle Particulars & Condition

Make & Model

MITSUBISHI ATTRAGE

Engine No.

3A92UDT3571

Chassis No.

MMBSTA13AHH004726

Odometer

Engine CC.

2016

Year Of Reg. Colour.

WHITE

Parf/COE Rebate.

MV

**Conditions Of Tyres** 

Size

Make

R/H Front Tyre

L/H Front Tyre R/H Rear Tyre

L/H Rear Tyre

**Description Of Damages** 

REAR PORTION

**General Information** 

Accident Date.

20/03/2020

Survey held at

Yew Tee Automobile Tech Pte Ltd

SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 \$417800

the Repairer of the following: · To resurvey before/after spray painting

LKK Auto Consultants hence notify

- To display damaged part(a) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

243/20 243/20 Zhe shoto Behire god The shoto Behire god P/P# 1857-20 P/P# 1857-20

- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Estimate Days Of Repair** 

Remarks

Acknowledged by Repairer

Signature:

ESTIMATE NORMAL PERIOD FOR REPAIR:

## **SM SPRAY PAINTING**

Qty.	Description Of Parts	Pricing		
1	REAR BUMPER	DD	\$	708.00
1	REAR BUMPER SIDE RETAINER RH	47	\$	26.00 ×
1	REAR BUMPER SIDE RETAINER LH	17	\$	26.00 0
1	REAR BUMPER REFLECTOR RH	17	\$	20.00
1	REAR END PANEL	2	\$	402.00
1	REAR END PANEL TOP GARNISH	11	\$	62.00 X
1	-TAIL GATE BOOHLD	1	\$	828.00 💉
1	TAIL GATE LOCK	11	\$	206.00
1	TAIL GATE EMBLEM	SUC	\$	48.00
1	TAIL GATE ATTRAGE EMBLEM	Sil	\$	38.00
		List items	\$	2,364.00
		Less 10%	\$	236.40
		Sub Total	\$	2,127.60

2/80 REAR BUMPER SENSOR
1 REAR NUMBER PLATE

Shell \$ 400.00 200 11 \$ 35.00 X 5/N \$ 435.00

## **SM SPRAY PAINTING**

Qty.	Description Of Parts	Pricing		
LABOUR				
To Remove and Re Exhaust Silencer ar	fit, Straighten and Re-adjust Exhaust Pipe and Rear nd Mountings.	u1	\$	150.00 X
	fit Rear Bumper Sensor.		Ś	80.00 50
To Transfer Rear Ta		11	\$	80.00 ×
To Disconnect and Replace Damaged	Reconnect, Check Electrical wiring Harness Wire, Sockets, Parts.	11	\$	50.00 20
To Remove and Re Realign and Repair	place the above Damaged Parts, Straighten, Knock out, including Cut and Weld body panels. To Re-adjust tion using power tools.		\$	900.00350
	Cleaning and Chemical Wash.	1-	10	150.00 ×
	Cavity Preservation.	1-	15	120.00 🗙
	rostat Sealant On The Cutting Areas.	1	15	100.00 🗴
To Spray painting o Masking Tape the u	on the Replaced and Repair Parts, Prepare Spray Such as unaffected areas with paper, Cleaning and Sanding colishing and Waxing are also available.	230	\$	900.00
		LABOUR	\$	2,530.00
		Sub Total.	Ś	5.092.60

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

P-708 102 P-637-20 S.N-2000000 L-1020.00

7% GSt \$ 356.48 Grand Total \$ 5,449.08