Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20004435/EGA3Q2

Date: 12/08/2020

REFERENCE

MCOM0015 Handling Insurer: India International Insurance Pte Ltd Policy No: Claimant SLP5793K

Insured Vehicle No: SHA1534U Vehicle No:

Date of Loss: Nature of Claim: ΤP 16/03/2020 Claim No: MCT20030283

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLP5793K Reg No:

Make & Model: MINI COOPER, 1.6 (A) Engine No: 31799932B38A15A Reg. Date: 09/06/2017 (Man. Year: 2017) Chassis No: WMWXS520102F22501

Colour: Odometer: 39758 km Red

Engine Capacity: 1499 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm Front Right Side: Rear Right Side: Pirelli 5 mm Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,823.61	4,714.89	108.72	2.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,030.00	5,310.00	720.00	11.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,853.61	10,024.89	828.72	7.64
+ GST 7.00/7.00% (S\$)	759.75	701.74	58.01	7.64
Nett Amount (S\$)	11,613.36	10,726.63	886.73	7.64

Global Sum Settlement (S\$) 0.00

INSPECTION

Date of Assignment: 27/03/2020

Date Inspected: 27/03/2020 Eurokars Habitat Pte Ltd (HQ) Inspected At:

27A Tanjong Penjuru Level 5

Singapore 609042

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Aug 2020)

Parts: M1-COUPE MINI COOPER 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLP5793K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

0----

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	793.52 F	*793.52 F
2	1		*FRONT BUMPER SUPPORT RH		70.46 F	*- F
3	1		*FRONT BUMPER LOWER CHROME FRAME	Necessary	134.16 F	*134.16 F
4	1		*FRONT FENDER RH	Dented	527.54 F	*527.54 F
5	1		*FRONT FENDER MOUNT RH	Bent	75.53 F	*75.53 F
6	1		*FRONT BUMPER SPOILER	Broken	242.32 F	*242.32 F
7	1		*FRONT FENDER WHEEL ARCH RH	Cut	178.29 F	*178.29 F
8	1		*FRONT FENDER INNER SHIELD RH	Crushed	152.94 F	*152.94 F
9	8		*WHEEL ARCH EXPANDING RIVET	Necessary	9.92 F	*9.92 F
10	6		*INNER SHIELD CLIP	Necessary	6.66 F	*6.66 F
11	2		*INNER SHIELD RIVET	Necessary	2.08 F	*2.08 F
12	1		*BONNET	Dented	1,349.08 F	*1,349.08 F
13	1		*BONNET ADJUSTER	Not Necessary	8.26 F	*- F
14	1		*TRIM RING LH	Necessary	73.25 F	*73.25 F
15	1		*TRIM RING RH	Necessary	73.25 F	*73.25 F
16	1		*MINI EMBLEM	Necessary	79.11 F	*79.11 F
17	15		*INSULATOR CLIP	Necessary	15.60 F	*15.60 F
18	1		*LABEL COOLANT	Necessary	31.85 F	*31.85 F
19	1		*FRONT RIM RH	Cut	949.79 F	*949.79 F
20	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
F=Fra	anchise	part. S=Spc	Nett.	T-4-1 D4- (Of)	4 000 04	4.744.00
				Total Parts (S\$)	4,823.61	4,714.89

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO REPLACE FRONT BUMPER ,FRONT FENDER RH AND BONNET ,TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,900.00	1,680.00				
2	TO RESPRAY FRONT BUMPER ,FRONT FENDER RH AND BONNET	New	2,600.00	2,400.00				
3	TO CARRY -OUT BODY CAVITY PRESERVATION	New	250.00	150.00				
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	120.00				
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	560.00				
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00				
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	250.00				
	Gross Labour Cost (S\$)		6,030.00	5,310.00				
	Report was unsubmitted during this print-out							

< END OF ESTIMATES >