

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INV No.

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877

INV Date Reference

AC2006104 07/09/2020

CC4/FCI20004444/Uka3q2

Code FC



PROFESSIONAL SERVICE FEE

Vehicle No. SLA 4175E

Insured Veh. SHA 4468H

Claim No. D20001563MFSH/1

Policy No. D-20094922MFSH

Accident Date 18/03/2020

Inspection Date 24/03/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LAM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile				
MS F	IS FIRST CAPITAL INSURANCE LTD Ref: CC4/FCl20004444/Uka3q2				
	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 07-09-2020 Code: FCI2		
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	SHA 4468H	Veh. Inspected	SLA 4175E	
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
	Claim No.	D20001563MFSH/1	Excess (\$)	0.00	
	Assign From	RACHEL WU	Assign Date	24/03/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	HONDA VEZEL (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	RU11107923	Colour	WHITE	
	Odometer	189797	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	215/65 R16	PIRELLI	6 mm	
	L/H Front Tyre	215/65 R16	PIRELLI	6 mm	
	R/H Rear Tyre	215/65 R16	PIRELLI	6 mm	
	L/H Rear Tyre	215/65 R16	PIRELLI	6 mm	
4.		Description	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		General	Information		
	Accident Date	18/03/2020	Inspection Date	24/03/2020	
	Survey held at	PROGRESSIVE CAR CARE PTE	E LTD		
	BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716				
5a.			emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				



LKK Auto Consultants Pte I 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 **LKK Auto Consultants Pte Ltd**

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 4175E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER -CENTRE ,BLACK	DENTED / DEFORMED	508.50	508.50
10	REAR BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
1	REAR BUMPER SIDE HOLDER-LH	NOT NECESSARY	21.50	-
1	REAR BUMPER SIDE HOLDER-RH	NOT NECESSARY	21.50	-
1	REAR PANEL	TO REPAIR SEE LABOUR	411.90	-
1	REAR PANEL TOP GARNISH	NOT NECESSARY	93.20	-
1	REAR BOOT	BADLY DENTED	1,050.90	953.00
1	REAR BOOT 'H' LOGO	NOT NECESSARY	27.40	-
1	REAR BOOT 'VEZEL' WORDING	NECESSARY	43.00	43.00
1	SET REAR BOOT WINDSCREEN MOULDING	NECESSARY	131.50	131.50
1	REAR BOOT RUBBER	NOT NECESSARY	96.80	-
	LESS 20% DISCOUNT		-489.04	-335.00
			1,956.16	1,340.00
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER SENSOR (SN)	SHORTED	220.00	200.00
2	SEALANT @\$20.00 (REAR WINDSCREEN) (SN)	NECESSARY	40.00	40.00
1	SPONGE TAPE (REAR WINDSCREEN) (SN)	NECESSARY	20.00	20.00
			280.00	260.00
	<u>LABOUR</u>			
	TO KNOCK OUT DENTS ,REAR BOOT ,CUT/WELD ,REMOVE,REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR PANEL .		600.00	400.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		600.00	400.00
	TO CHECK WIRING.		20.00	20.00
	TO REMOVE,REPLACE REAR BUMPER SENSOR .		50.00	50.00
	TO REMOVE,REFIX REAR GLASS.		120.00	120.00
	TO REMOVE,REFIX REAR GARNISH ,CARPET ,CUSHION,SEAT AND RELATED PARTS.		80.00	60.00

Report Ref No. CC4/FCI20004444/Uka3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO TRANSFER REAR BOOT.		60.00	60.00
			1,530.00	1,110.00
	GRAND TOTAL		3,766.16	2,710.00

RECOMMENDED COST OF LUMP SUM REPAIRS	2,150.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/FCI20004444/Uka3q2

CHUA KANG SENG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION

PHOTOGRAPHS FOR VEHICLE NO. SLA 4175E















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 4175E







