

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20004447/KPA3Q2

Date: 16/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800153357

Claimant
Vehicle No : SMQ6255Z **Insured Vehicle No :** SLJ8881B

Date of Loss: 21/03/2020 Nature of Claim: TP Claim No: 3889836350SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ6255Z	Engine No:	G4FGKU476263
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMLU012640
Reg. Date:	27/11/2019 (Man. Year: 2019)	Odometer:	23805 km
Colour:	Metallic Pearl White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 7 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	614.08	0.00	614.08	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	380.00	300.00	44.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,294.08	380.00	914.08	70.64
+ GST 7.00/7.00% (\$\$)	90.59	26.60	63.99	70.64
Nett Amount (\$\$)	1,384.67	406.60	978.07	70.64
+ Loss of Use (2.0 x S\$60.00/day) (\$\$)		120.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		528.60		
Global Sum Settlement (\$\$)		520.00		

INSPECTION

Date of Assignment: 01/04/2020

Date Inspected: 01/04/2020

Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	723.60 FL	*- FL
2	8		*REAR BUMPER CLIP	Serviceable	44.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	767.60	0.00
- List Item Discount on L Items 20.00/20.00% (S\$)	153.52	0.00
Total Parts (S\$)	614.08	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	300.00	180.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER	New	300.00	200.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER SENSOR & ETC	New	80.00	0.00
Gross Labour Cost (\$)			680.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >