

Date: 24.03.2020
Vehicle No: SMQ6255Z
Model: HYUNDAI AVANTE 1.6 GLS
Chassis: KMHD841CMLU012640-2019
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLJ8881B
Date of Accident: 21.03.2020

*Not with ash
+ 2 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		✓ \$723.60
2	REAR BUMPER CLIP	8	\$5.50	svc \$44.00
			SUB TOTAL	\$767.60
			LESS 20%	-\$153.52
			PARTS TOTAL	\$614.08

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST REAR ACCIDENT AREAS & ETC. \$300.00 *1801*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER. \$300.00 *2001*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER SENSOR & ETC. \$80.00 *Xnn*

LABOUR TOTAL \$680.00

TingAn **TOTAL \$1,294.08**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223